

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**X808**

**Asset: P.S. 8 MINISCHOOL - BRONX, 3010 BRIGGS AVENUE, New York, 10458**

Inspection Id	Inspection Type	Time In	Last Edited
EE : X808	Electrical	2017-10-03 8:36 AM	2018-06-18 10:57 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System, Intrusion Alarm System (Infrared Sensor, Remote Annunciator), Grounding System
	Years: 2014
	Systems: LAN, Telephone System
	Years: 2009
	Systems: Security Lights
	Years: 2006
	Systems: Interior Fluorescent Lighting (Retrofit)
	Years: 2004
	Systems: All Other Electrical Systems and Components
	Years: 1985

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>COMPUTER LAB</b>	Does not Exist
<b>GYMNASIUM</b>	Does not Exist
<b>KITCHEN</b>	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**X808**

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Does not Exist
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X808

Question	Response
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Does not Exist
<b>Elevator Recall</b>	Does not Exist
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Does not Exist
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST-3X
Capacity/Size Quantity	4
Capacity/Size UOM	Zones
Source of Capacity/Size	Diagram
Installation Year	2014
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**X808**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Remote Annunciator</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Does not Exist
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
Instance	Connected to Main Asset X008
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1985
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Connected to Main Asset X008
Deficiency Quantity	9,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**X808**

<b>Question</b>	<b>Response</b>
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Does not Exist
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Does not Exist
<b>Infrared Sensor</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	SIREN/STROBE NOT OPERATIONAL
Deficiency Location/Instance	Outside facing Bainbridge Avenue
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Ultrasonic Sensor</b>	Does not Exist
<b>Lighting - Security</b>	Inspected
Replacement Quantity	7
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Does not Exist
<b>SWITCHBOARD</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist
<b>TV SYSTEM</b>	Does not Exist