

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Asset: P.S. 41 - BROOKLYN, 411 THATFORD AVENUE, New York, 11212

Inspection Id	Inspection Type	Time In	Last Edited
EE : K041	Electrical	2019-04-12 8:31 AM	2019-04-22 12:58 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Gymnasium (LED Lighting)
	Years: 2018
	Systems: Telephone System
	Years: 2016
	Systems: Security Lights
	Years: 2015
	Systems: Fire Alarm System (CO Detector, Digital Communicator), Partial Switchboard
	Years: 2014
	Systems: Partial Exit Lights (Battery Pack), Interior Fluorescent Lighting, LED Lighting, Gymnasium (HID Lighting), Partial Emergency Lighting (Non Battery Pack)
	Years: 2013
	Systems: IPDVS/CCTV System
	Years: 2011
	Systems: LAN
	Years: 2009
	Systems: Fire Alarm System
	Years: 2008
	Systems: Public Address System, Local Sound System
	Years: 2006
	Systems: Intrusion Alarm System, Emergency Light/Exit Light Panel
	Years: 1995
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1985, 1995, 2014

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K041

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
AUDITORIUM	
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K041

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 318	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 318	Inspected
Lighting Fixture - Fluorescent	Inspected
Instance on Room 318	Inspected
Pendant Mounted	Inspected
Instance on Room 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 318	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 318	Does not Exist
Lighting Fixture - HID	Does not Exist
Instance on Room 318	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Instance on Room 318	Does not Exist
Lighting Fixture - LED	Does not Exist
Instance on Room 318	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K041

Question	Response
COMPUTER LAB	Inspected
Raceway With Receptacles	Inspected
Instance on Room 318	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2006
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Scoreboard	Inspected
Instance on 1st Floor	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
GYMNASIUM	Inspected
Scoreboard	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 217	Inspected
Lighting	Inspected
Instance on Room 217	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 217	Inspected
Pendant Mounted	Inspected
Instance on Room 217	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 217	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 217	Does not Exist
Lighting Fixture - HID	
Instance on Room 217	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 217	Does not Exist
Lighting Fixture - LED	
Instance on Room 217	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 217	Does not Exist
Projection System	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
LIBRARY	Inspected
Projection System	
Instance on Room 217	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 302	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 302	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 302	Inspected
Pendant Mounted	Inspected
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 302	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 302	Does not Exist
Lighting Fixture - HID	
Instance on Room 302	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 302	Does not Exist
Lighting Fixture - LED	
Instance on Room 302	Does not Exist
Projection System	Does not Exist
Instance on Room 302	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 302	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 302	Does not Exist
Power Supply	Does not Exist
Instance on Room 302	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K041

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	94,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	94,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
FIRE ALARM SYSTEM	
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Honeywell
Equipment	N/A
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K041

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Equipment	Fire Alarm Control Panel
Model	EST 2
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	MOTOR STARTER INDICATOR LIGHT NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	MAINTENANCE

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
MOTOR STARTER/CONTACTOR	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Mechanical Room C11
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
	Does not Exist
Fused Toggle Switch Type	
	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium, Cafeteria, Kitchen, Corridor (Basement, 1st, 2nd, 3rd Floors)
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Gymnasium, 2nd Floor Corridor - By Room 226
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	94,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2006
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	94,000
Replacement Uom	S.F.
Installation Year	2011
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Replacement Quantity	94,000
Replacement Uom	S.F.
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Model	Vista - 50P
Installation Year	1995
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	On Exterior wall (Above Main Entrance Door)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	47
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Main Service Switch
Capacity/Size Quantity	1,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K041

Question	Response
SERVICE SWITCH	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	
	Inspected
Number of Spares	2
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Electrical Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	I.T.E. Imperial Corp.
Equipment	DB1-1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

K041

Question	Response
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist