

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K043

Asset: I.S. 98 - BROOKLYN, 1401 EMMONS AVENUE, New York, 11235

Inspection Id	Inspection Type	Time In	Last Edited
EE : K043	Electrical	2017-11-02 8:25 AM	2017-11-21 7:39 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Emergency Generator Set, Fire Alarm System, Lightning Protection, Auditorium (Local Sound System), Motor Starters
	Years: Under construction
	Systems: Interior Lighting (Except Incandescent Lighting in Science Demo Room 232), Library, Most Emergency Lighting (Non-Battery Pack), Gymnasium (Scoreboard), Partial Fused Disconnect Switch Type Panel Board
	Years: 2015
	Systems: Security Lights, Intrusion Alarm System
	Years: 2012
	Systems: Public Address System, Local Sound System
	Years: 2009
	Systems: Auditorium (Theater Lighting System), LAN, Telephone System
	Years: 2007
	Systems: Emergency Light/Exit Light Panel
	Years: 2006
	Systems: Science Demo Room 232 (Incandescent Lighting)
	Years: 2005
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1995, 2012, 2015

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Panel Board - Cover Is Missing	Interior Cover and door lock are missing	PANEL BOARD Molded Case Circuit Breaker Type	Green House at Courtyard	Miguel Arzuaga	Fireman	Sent to DSF	
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Corridor by Room 151	Miguel Arzuaga	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K043

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Under Construction
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K043

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2009
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	
Lighting Fixture - LED	
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Rooms 301, 402	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Rooms 301, 402	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 301, 402	Inspected
Pendant Mounted	Inspected
Instance on Rooms 301, 402	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 301, 402	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 301, 402	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 301, 402	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 301, 402	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 301, 402	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms 301, 402	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K043

Question	Response
GYMNASIUM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2009
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Scoreboard	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 117	Inspected
Lighting	Inspected
Instance on Room 117	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 117	Inspected
Pendant Mounted	Inspected
Instance on Room 117	Inspected
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Room 117	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Room 117	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 117	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 117	Does not Exist
Lighting Fixture - LED	
Instance on Room 117	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 117	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 117	Does not Exist
LOCKER ROOM	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Alternative use	No
Lighting	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Pendant Mounted	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Surface Mounted	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 232	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
SCIENCE DEMO ROOM	
Power Panel	Yes
Alternative use	No
Instance on Rooms 207, 213, 214, 218, 223	Inspected
Power Panel	No
Alternative use	Yes
Lighting	Inspected
Instance on Rooms 207, 213, 214, 218, 223	Inspected
Instance on Room 232	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 207, 213, 214, 218, 223	Inspected
Instance on Room 232	Inspected
Pendant Mounted	Inspected
Instance on Rooms 207, 213, 214, 218, 223	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 232	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Inspected
Pendant Mounted	Does not Exist
Instance on Room 232	Does not Exist
Surface Mounted	Inspected
Instance on Room 232	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 232	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Does not Exist
Projection System	Does not Exist
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
SCIENCE DEMO ROOM	
Emergency Gas Shut-Off Valve	Does not Exist
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Does not Exist
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Rooms 207, 213, 214, 218, 223	Does not Exist
Instance on Room 232	Inspected
Instructor Unit	
Instance on Room 232	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 232	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	
	Inspected
Instance on Room 237	Inspected
Power Panel Alternative use	No No
Lighting	Inspected
Instance on Room 237	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 237	Inspected
Pendant Mounted	
Instance on Room 237	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 237	Does not Exist
Recessed Mounted	
Instance on Room 237	Does not Exist
Lighting Fixture - HID	
Instance on Room 237	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 237	Does not Exist
Lighting Fixture - LED	
Instance on Room 237	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 237	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 237	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
SCIENCE PREP ROOM	Inspected
Power Supply	Does not Exist
Instance on Room 237	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	142,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Under Construction
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
EXIT LIGHT	
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor - Boys Locker Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not Exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Under Construction
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Under Construction
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Under Construction
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Room 114, Penthouse Mechanical Room, Electrical Room, Boiler Room
Deficiency Quantity	6

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K043

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
	Does not Exist
Fused Toggle Switch Type	
	Does not Exist
Molded Case Circuit Breaker Type	
	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Green House in Courtyard
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Green House in Courtyard
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	By Room 115, Electrical Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, Electrical Room, by Rooms (332, 339)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridor 1st, 2nd, 3rd, 4th Floor), Auditorium, Kitchen, Cafeteria, Gymnasium, Electrical Room, Rooms (239, 241, 242, 245)
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	142,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2009
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, By Room 234
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	142,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
Condition	Does not Exist
Lighting - Security	
Replacement Quantity	25
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Roof Facing Schoolyard
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
Instance	Inspected
Instance Condition	Electrical Room
Instance Quantity	3 - Fair
Instance Quantity Uom	1
Instance Manufacturer	EACH
Instance Manufacturer	Standard Switchboard

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
SERVICE SWITCH	
Equipment	Main Service Switch
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	
	Inspected
Number of Spares	1
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Standard Switchboard
Equipment	Main Distr. Switchboard
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1965
Source of Installation	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K043

Question	Response
TELEPHONE SYSTEM	Inspected
Standard	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist