

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

School: P.S. 9 - MANHATTAN, 100 WEST 84 STREET, MANHATTAN, NY, 10024

InspectionId	Inspection Type	Time In	Last Edited
3771	ELECTRICAL	2019-04-11 09:16AM	2019-04-11 11:54AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Library, LAN, Telephone System Years: 2018 Systems: Science Lab - Room 326 Years: 2012 Systems: Auditorium (Local Sound System, Projection System), Exit Lights, IPDVS/CCTV System Years: 2010 Systems: Emergency Lighting (Non Battery Pack) Years: 2010, 2018 Systems: Gymnasium (LED Lighting) Years: 2016 Systems: Public Address System (Except Clocks), Cafeteria (Local Sound System) Years: 2015 Systems: Auditorium (Theater Lighting System) Years: 2007 Systems: Interior Fluorescent Lighting, Security Lights Years: 2001 Systems: Intrusion Alarm System Years: 1999 Systems: Most Molded Case Circuit Breaker Panel Board Years: 1990, 2001, 2007, 2012 Systems: Emergency Light/Exit Light Panel Years: 1994
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	condition recorded						

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Condition	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Condition	Does not exist
Lighting Fixture - Incandescent	
Condition	Does not exist
Lighting Fixture - LED	
Condition	Does not exist
COMPUTER LAB	
Instance on Room 226	Inspected
Power Panel?	Yes
Instance on Room 317	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 226	Inspected
Instance on Room 317	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 226	Inspected
Instance on Room 317	Inspected
Pendant Mounted	
Instance on Room 226	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 226	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 317	Does not exist
Surface Mounted	
Instance on Room 226	Does not exist
Instance on Room 317	Does not exist
Lighting Fixture - HID	
Instance on Room 226	Does not exist
Instance on Room 317	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 226	Does not exist
Instance on Room 317	Does not exist
Lighting Fixture - LED	
Instance on Room 226	Does not exist
Instance on Room 317	Does not exist
Raceway With Receptacles	
Instance on Room 226	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
EMERGENCY LIGHTING	
Non Battery Pack	
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	
Battery Pack	
Condition	Inspected
Deficiency	2- Between Good and Fair
Non Battery Pack	
EXIT/EMERGENCY LIGHT	
FIRE ALARM SYSTEM	
Area Smoke Detector	
Bell/Horn	
Condition	Does not exist
Deficiency	Inspected
CO Detector	
Duct Smoke Detector	
Elevator Recall	
Fan Shutdown Control	
Fire Alarm Digital Communicator	
Fused Cutout Panel	
Condition	Does not exist
Deficiency	3- Fair
Heat Detector	
Magnetic Door Holder/Contactor	
Main Panel	
Bell At Panel	
Condition	Does not exist
Deficiency	3- Fair
Fire Alarm Control Panel (Electronic)	
Fire Alarm Control Panel (Standard)	
Instance	Inspected
Instance Condition	Boiler Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	ACME
Capacity/Size Quantity	Fire Alarm
Capacity/Size UOM	7
Source of Capacity/Size	Circuits
Installation Year	Diagram
Source of Installation Year	1965
Deficiency	Documented
Deficiency Location/Instance	BEYOND USEFUL LIFE
Deficiency Quantity	Boiler Room
Quantity Uom	88,000
Potential Action	S.F.
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 1
Violations	LEVEL 2
Manual Pull Station	
Condition	Inspected
Deficiency	3- Fair
Remote Annunciator	
Does not exist	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Diagram
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	88,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Surface Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1965
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
INTERCOM SYSTEM	
Does not exist	
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	
Inspected	
Local Distribution Frame (I/LDF)	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 217	Inspected
Lighting	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
LIBRARY	
Lighting	
Instance on Room 217	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 217	Does not exist
Lighting Fixture - HID	
Instance on Room 217	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 217	Inspected
Pendant Mounted	
Instance on Room 217	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 217	Does not exist
Surface Mounted	
Instance on Room 217	Does not exist
Lighting Fixture - LED	
Instance on Room 217	Inspected
Pendant Mounted	
Instance on Room 217	Does not exist
Recessed Mounted	
Instance on Room 217	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 217	Does not exist
Projection System	
Instance on Room 217	Does not exist
Raceway With Receptacles	
Instance on Room 217	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 301, Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	
Condition	Inspected
	2- Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Corridors by Rooms 304, 103, 110
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Corridor By Room 304
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Gymnasium, Corridors By Rooms 308, 204, 110, Basement Corridor By Boiler Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria, Corridors by Rooms 304, 103, 110, 128
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	General Office - Room 140
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Quantum Multicom IP
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
SCIENCE LAB	
Instance on Room 326	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 326	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 326	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 326	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 326	Inspected
Pendant Mounted	
Instance on Room 326	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 326	Does not exist
Surface Mounted	
Instance on Room 326	Does not exist
Lighting Fixture - HID	
Instance on Room 326	Inspected
Pendant Mounted	
Instance on Room 326	Does not exist
Recessed Mounted	
Instance on Room 326	Does not exist
Surface Mounted	
Instance on Room 326	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - Incandescent	
Instance on Room 326	Does not exist
Lighting Fixture - LED	
Instance on Room 326	Does not exist
Power Supply	
Instance on Room 326	Inspected
Instructor Unit	
Instance on Room 326	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 326	Does not exist
Student Unit	
Instance on Room 326	Does not exist
Projection System	
Instance on Room 326	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SECURITY	
Intrusion Alarm System	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Instance	Custodian's Office - Room 142
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1999
Source of Installation Year	Custodial Staff
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Replacement Quantity	24
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Location/Instance	Outside By west 84th Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	N/A
Capacity/Size Quantity	1600

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M009

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	1
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan Electric
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair

NYC Department of Education
 Building Condition Assessment Survey 2018-2019

Electrical Inspection

M009

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Does not exist