

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

School: **I.S. 44 - MANHATTAN, 100 WEST 77 STREET, MANHATTAN, NY, 10024**

InspectionId	Inspection Type	Time In	Last Edited
330	ELECTRICAL	2018-11-27 08:35AM	2018-12-07 11:52AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Partial Emergency Lights (Battery Pack) Years: 2017 Systems: Fire Alarm System, Public Address System, Local Sound System (Cafeteria and Gymnasium), Motor Starters, Interior Fluorescent Lighting (Except Library, Science Lab 215, Students Toilet Rooms) Years: 2015 Systems: Auditorium (Local Sound System, Theater Lighting System, Projection System), Computer Lab G23A (Raceway with Receptacles), Gymnasium Scoreboard Years: 2012 Systems: Library Years: 2011 Systems: Telephone System Years: 2010 Systems: Fluorescent Lighting in Students Toilet Rooms Years: 2009 Systems: Science Lab 215, Science Prep Room 214 (Except Lighting) Years: 2006 Systems: Partial Molded Case Circuit Breaker Panel Boards Years: 1995, 2006 Systems: IPDVS/CCTV System Years: 2008 Systems: Intrusion Alarm System Years: 1999 Systems: Security Lights, Emergency Lights/Exit Lights Years: 1995
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image	
		No condition recorded						

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Condition	Inspected
Pendant Mounted	
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Condition	Does not exist
Lighting Fixture - Incandescent	
Condition	Does not exist
Lighting Fixture - LED	
Condition	Inspected
Pendant Mounted	
Condition	Does not exist
Recessed Mounted	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
COMPUTER LAB	
Instance on Room G23A	Inspected
Power Panel?	Yes
Instance on Room 305	Inspected
Power Panel?	No
Lighting	
Instance on Room G23A	Inspected
Instance on Room 305	Inspected
Lighting Fixture - Fluorescent	
Instance on Room G23A	Inspected
Instance on Room 305	Inspected
Pendant Mounted	
Instance on Room G23A	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room G23A	Does not exist
Instance on Room 305	Does not exist
Surface Mounted	
Instance on Room G23A	Does not exist
Instance on Room 305	Does not exist
Lighting Fixture - HID	
Instance on Room G23A	Does not exist
Instance on Room 305	Does not exist
Lighting Fixture - Incandescent	
Instance on Room G23A	Does not exist
Instance on Room 305	Does not exist
Lighting Fixture - LED	
Instance on Room G23A	Does not exist
Instance on Room 305	Does not exist
Raceway With Receptacles	
Instance on Room G23A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 305	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
	Inspected
Battery Pack	
Condition	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Room 146, By Room 331
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	
Condition	Inspected
Deficiency	3- Fair
EXIT LIGHT	
Battery Pack	
Condition	Inspected
Deficiency	3- Fair
Non Battery Pack	
Condition	Inspected
Deficiency	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Library
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 5
Violations	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	
	Does not exist
FIRE ALARM SYSTEM	
Area Smoke Detector	
Condition	Inspected
Deficiency	1- Good
Bell/Horn	
Condition	Inspected
Deficiency	1- Good
CO Detector	
Condition	Inspected
Deficiency	1- Good
Duct Smoke Detector	
Condition	Inspected
Deficiency	1- Good
Elevator Recall	
Condition	Inspected
Deficiency	1- Good
Fan Shutdown Control	
Condition	Inspected
Deficiency	1- Good
Fire Alarm Digital Communicator	
	Does not exist
Fused Cutout Panel	
Condition	Inspected
Deficiency	1- Good
Heat Detector	
Condition	Inspected
Deficiency	1- Good
Magnetic Door Holder/Contactor	
	Does not exist
Main Panel	
Condition	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	32
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Diagram
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
LAN	
Local Distribution Frame (I/LDF)	
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 139	Inspected
Lighting	
Instance on Room 139	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 139	Inspected
Pendant Mounted	
Instance on Room 139	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 139	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 139	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 139	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 139	Does not exist
Lighting Fixture - LED	
Instance on Room 139	Does not exist
Projection System	
Instance on Room 139	Does not exist
Raceway With Receptacles	
Instance on Room 139	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Basement Corridor By Staircase F
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Closet Between Rooms (102 and 103)
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Closet Between Rooms (102 and 103)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	
Instance on Room 215	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 215	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
SCIENCE LAB	
Emergency Gas Shut-Off Valve	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 215	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 215	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 215	Inspected
Pendant Mounted	
Instance on Room 215	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 215	Does not exist
Surface Mounted	
Instance on Room 215	Does not exist
Lighting Fixture - HID	
Instance on Room 215	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 215	Inspected
Pendant Mounted	
Instance on Room 215	Does not exist
Recessed Mounted	
Instance on Room 215	Does not exist
Surface Mounted	
Instance on Room 215	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on Room 215	Does not exist
Power Supply	
Instance on Room 215	Inspected
Instructor Unit	
Instance on Room 215	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 215	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 215	Does not exist
Projection System	
Instance on Room 215	Does not exist
SCIENCE PREP ROOM	
Instance on Room 214	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
SCIENCE PREP ROOM	
Emergency Gas Shut-Off Valve	
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 214	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 214	Inspected
Pendant Mounted	
Instance on Room 214	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 214	Does not exist
Surface Mounted	
Instance on Room 214	Does not exist
Lighting Fixture - HID	
Instance on Room 214	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 214	Does not exist
Lighting Fixture - LED	
Instance on Room 214	Does not exist
Power Supply	
Instance on Room 214	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - 101
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1999
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	4- Between Fair and Poor
Deficiency	SIREN/STROBE NOT OPERATIONAL
Deficiency Location/Instance	Outside wall facing 77th Street

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2008
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Replacement Quantity	10
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Switchboard Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	Main Switch Service A
Capacity/Size Quantity	750
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Switchboard Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Switchboard Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	Main Switch Service Basement
Capacity/Size Quantity	750
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Electrical Inspection

M044

Question	Response
SERVICE SWITCH	
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Switchboard Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Switchboard Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	Main Switchboard Sec A
Capacity/Size Quantity	750
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Switchboard Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Switchboard Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	Main Switchboard Sec B
Capacity/Size Quantity	750
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Switchboard Meter Room
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M044

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Does not exist