

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

School: P.S. 133 - MANHATTAN, 2121 5TH AVENUE, MANHATTAN, NY, 10037

InspectionId	Inspection Type	Time In	Last Edited
2490	ELECTRICAL	2019-02-15 09:03AM	2019-04-18 03:48PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Public Address System, Local Sound System in Cafeteria and Gymnasium, Fire Alarm System Years: 2015 Systems: Main Service Switches Years: 2004 Systems: Auditorium Local Sound System, Theater Lighting and Projection System Years: 2009 Systems: Interior Lighting, Non Battery Emergency Lights Years: 2013 Systems: LAN, Telephone System Years: 2010 Systems: Outside Security Lights Years: 1990, 2007 Systems: Partial Circuit Breaker Panelboards Years: 2000, 2004, 2013 Systems: Surface Mounted Lights in Gymnasium Years: 2019 Systems: Intrusion Alarm System Years: 1998
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Emergency Lighting - Not Operational	Emergency Lights Not Operational	Emergency Lighting	Gymnasium	Kerwin Blades	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
CAFETERIA	
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Condition	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Condition	Inspected
Pendant Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	Does not exist
Surface Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Condition	Does not exist
Lighting Fixture - Incandescent	
Condition	Does not exist
Lighting Fixture - LED	
Condition	Inspected
Pendant Mounted	
Condition	Does not exist
Recessed Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	Does not exist
COMPUTER LAB	
Instance on Room 232	Inspected
Power Panel?	Yes

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
COMPUTER LAB	
Lighting	
Instance on Room 232	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 232	Inspected
Pendant Mounted	
Instance on Room 232	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 232	Does not exist
Surface Mounted	
Instance on Room 232	Does not exist
Lighting Fixture - HID	
Instance on Room 232	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 232	Does not exist
Lighting Fixture - LED	
Instance on Room 232	Does not exist
Raceway With Receptacles	
Instance on Room 232	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
EMERGENCY LIGHTING	
	Inspected
Battery Pack	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Non Battery Pack	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency Location/Instance	FIXTURE NOT OPERATIONAL Gymnasium and Outside Gymnasium
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
EXIT LIGHT	
	Inspected
Battery Pack	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Non Battery Pack	
	Does not exist
EXIT/EMERGENCY LIGHT	
	Does not exist
FIRE ALARM SYSTEM	
	Inspected
Area Smoke Detector	
Condition	Inspected
Deficiency	1- Good
	No deficiencies recorded
Bell/Horn	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
FIRE ALARM SYSTEM	
Bell/Horn	
Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	FX - 2000
EquipmentId	Fire Alarm Control
Capacity/Size Quantity	20
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
INTERCOM SYSTEM	
Instance on 1st Floor	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 129	Inspected
Lighting	
Instance on Room 129	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 129	Inspected
Pendant Mounted	
Instance on Room 129	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 129	Does not exist
Surface Mounted	
Instance on Room 129	Does not exist
Lighting Fixture - HID	
Instance on Room 129	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 129	Does not exist
Lighting Fixture - LED	
Instance on Room 129	Does not exist
Projection System	
Instance on Room 129	Does not exist
Raceway With Receptacles	
Instance on Room 129	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	
Instance on 1st Floor Boys, 1st Floor Girls	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
LOCKER ROOM	
Alternative Use	Yes
Lighting	
Instance on 1st Floor Boys, 1st Floor Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor Boys, 1st Floor Girls	Inspected
Pendant Mounted	
Instance on 1st Floor Boys, 1st Floor Girls	Does not exist
Recessed Mounted	
Instance on 1st Floor Boys, 1st Floor Girls	Does not exist
Surface Mounted	
Instance on 1st Floor Boys, 1st Floor Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor Boys, 1st Floor Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor Boys, 1st Floor Girls	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor Boys, 1st Floor Girls	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse Fan Rooms, Fan Rooms 251, 147, 164, Boiler Room
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors, Gymnasium, Boiler Room
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	General Office
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA250A
Installation Year	2015
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SECURITY	
	Inspected
Intrusion Alarm System	
	Inspected
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1998
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria and Exit 6
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	
	Does not exist
Remote Annunciator	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
	Does not exist
Lighting - Security	
	Inspected
Condition	3- Fair
Replacement Quantity	19
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Roof and Building Perimeter
Deficiency Quantity	6

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
SECURITY	
Lighting - Security	
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Service A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Service B
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E.
EquipmentId	Emergency Lights Main Switch
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	PP-Kitchen
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
SERVICE SWITCH	
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	ACPP-2
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	ACPP-3
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	AC PP CPP
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Switch Co.
EquipmentId	Oil Burner Disconnect A
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Switch Co.
EquipmentId	Oil Burner Disconnect B
Capacity/Size Quantity	100

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eaton
EquipmentId	Fire Alarm Fuse Disconnect
Capacity/Size Quantity	60
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Westinghouse
EquipmentId	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1948
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M133

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not exist