

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

School: **P.S. 155 - MANHATTAN, 319 EAST 117 STREET, MANHATTAN, NY, 10035**

InspectionId	Inspection Type	Time In	Last Edited
3697	MECHANICAL	2019-04-10 07:16AM	2019-06-11 11:23AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Kitchen - Grease Trap (1 of 2) Years: 2015 Systems: Science Lab; Electric Domestic Water Heater for Science Lab (1 of 3, in Crawlspace below Cafeteria) Years: 2014 Systems: MDF Room - Dedicated A/C Equipment (1 of 2, DX Split System) Years: 2013 Systems: Boiler #1 re-tubed Years: 2012 Systems: Kitchen - Hood Exhaust Fan Years: 2018 Systems: Electric Domestic Water Heaters (2 of 3) Years: 2019
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	15,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	Basement MER, Pump Room B16
Are there any spaces with Missing or Defective CO Detectors?	Science Lab
Are there any Painted/Obstructed Sprinkler Heads?	Room 402 (painted, 2)
Are there any Emergency Stop Switches with Missing Hammers?	Component: Boiler Room - Entrances Location: Boiler Emergency Stop Switch

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Electric System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	41-60%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Various Locations
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
CLIMATE CONTROL SYSTEM	
Electric System	
Deficiency	DEFECTIVE TERMINAL UNIT CONTROL VALVE
Deficiency Location/Instance	Various Locations
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Pneumatic System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Ash Hoist	Does not exist
Dumbwaiter	Inspected
Condition	3- Fair
Are all the existing dumbwaiters operable?	Yes
Deficiency	No deficiencies recorded
Elevator	Does not exist
Escalator	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Gas/Water Meter Room B8, Crawlspace below Cafeteria
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - Gas/Water Meter Room B8, Crawlspace below Cafeteria
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement - Crawlspace below Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Electric Domestic Water Heater	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE DOMESTIC HOT WATER CIRCULATING PUMP
Deficiency Location/Instance	Basement - Crawlspace below Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room @ Sump Pumps
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sump Pump	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
Does not exist	
Enclosed IDF Room	
Instance on Rooms 213, 313	Inspected
Dedicated A/C Equipment	
Instance on Rooms 213, 313	Not required
FIXTURES	
Inspected	
Staff And Other	
Inspected	
Janitor Sink	
Inspected	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
FIXTURES	
Staff And Other	
Janitor Sink	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Janitor Closets 111, 211
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Custodian's Office 126
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Cafeteria; Cafeteria - Toilet Room; Toilet Rooms 207, 307, 407, 419
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Inspected
Instance on 2nd Floor - Boys	Inspected
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Alternative Use	Yes
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Girls	Inspected
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
FIXTURES	
Student	
Locker Room Shower	
Instance Quantity Uom	EACH
Alternative Use	Yes
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Room 205
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Toilet Rooms 219, 319
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
CO/Gas Leak Detection	Does not exist
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convactor/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
HEATING	
Steam Heating	
MER Steam and Condensate Piping	
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	
Condition	Inspected
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	
Condition	Inspected
Deficiency	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Piping	
Condition	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	3rd Floor Stair "A", Room 424
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	
Condition	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Various Locations
Deficiency Quantity	40
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam supplied by External Sources	
Unit Heater/Cabinet Heater	
Does not exist	
Does not exist	
HEATING PLANT	
Replacement Quantity	8,106
Replacement Uom	MBH NET
Instance on Basement	Inspected
Burner Type	Oil
Heating Plant Oil Number	4
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE BLOWDOWN PIPING
Deficiency Location/Instance	Boiler Room @ Boiler #1, #2
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Auxiliary Piping	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	MISSING HAMMER
Deficiency Location/Instance	Boiler Room - Entrances
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler Feedwater System	
Instance on Basement	Does not exist
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Does not exist
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Does not exist
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room @ Boiler #1, #2
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Boiler Room @ Boiler #1, #2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
HEATING PLANT	
Boiler System	
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,053
Instance Quantity Uom	MBH NET
Manufacturer	Burnham
EquipmentId	49346-1
Capacity/Size Quantity	45
Capacity/Size UOM	Burner GPH
Source of Capacity/Size	Documented
Installation Year	1961
Source of Installation Year	Documented
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED REFRACTORY
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	4,053
Instance Quantity Uom	MBH NET
Manufacturer	Burnham
EquipmentId	49346-2
Capacity/Size Quantity	45
Capacity/Size UOM	Burner GPH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Source of Capacity/Size	Documented
Installation Year	1961
Source of Installation Year	Documented
Deficiency	LEAKY/PLUGGED TUBES
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED REFRACTORY
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FUEL OIL LEVEL GAUGE:DEFECTIVE
Deficiency Location/Instance	Boiler Room outside Oil Tank Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
HEATING PLANT	
Fuel System	
Fuel Oil Storage/Supply System	
Deficiency	FUEL OIL TRANSFER PUMP:DEFECTIVE
Deficiency Location/Instance	Boiler Room outside Oil Tank Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	
Instance on Room 414B	Inspected
Dedicated A/C Equipment	
Instance on Room 414B	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
MDF Room	
Dedicated A/C Equipment	
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	
Instance on Room 404	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room 404	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	
Instance on Room 404	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Room 404
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Emergency Shower	
Instance on Room 404	Does not exist
Eye Wash	
Instance on Room 404	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Fixed Laboratory Hood	
Instance on Room 404	Does not exist
Hood Exhaust Ductwork	
Instance on Room 404	Does not exist
Hood Exhaust Fan	
Instance on Room 404	Does not exist
Laboratory Sink	
Instance on Room 404	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 404	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Room 402 (painted, 2)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M155

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	
Condition	Inspected
Deficiency	3- Fair
Standpipe System	
Condition	No deficiencies recorded
Water Gong	
Condition	Does not exist
Wet Sprinkler Alarm Valve Assembly	
Condition	Inspected
Deficiency	3- Fair
Violations	No deficiencies recorded
SWIMMING POOL	
Condition	Does not exist
VENTILATION	
Condition	Inspected
Exhaust Fan	
Condition	Inspected
Approximate Total # of Fans	3- Fair
Deficiency	1-25
Deficiency Location/Instance	DEFECTIVE MOTOR
Deficiency Quantity	Lower Roof / Cafeteria Exhaust Fan
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	DEFECTIVE CONTROLS
Deficiency Quantity	Kitchen Office
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Violations	No violations recorded
Metal Ductwork	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	DAMAGED FLEXIBLE CONNECTION
Deficiency Quantity	Basement - MER @ Auditorium Supply Fan
Quantity Uom	2
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE VOLUME DAMPER
Deficiency Location/Instance	Basement - MER
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	
Condition	Inspected
Violations	3- Fair

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Mechanical Inspection

M155

Question	Response
VENTILATION	
Supply Fan	
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Does not exist