

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

School: P.S. 161 - MANHATTAN, 499 WEST 133 STREET, MANHATTAN, NY, 10027

InspectionId	Inspection Type	Time In	Last Edited
684	ELECTRICAL	2018-12-10 12:58PM	2018-12-10 04:03PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Service Switch, Switchboard, Grounding System, Most Molded Case Circuit Breaker Panel Board, Fire Alarm System (Fused Cutout Panel), Lightning Protection, Science Lab Room 209, Interior Lighting, Partial Fused Disconnect Switch Type Panel Board Years: 2014 Systems: Gymnasium (Scoreboard) Years: 2011 Systems: Most Security Lights, Public Address System, Local Sound System, Auditorium (Projection System), LAN, Telephone System Years: 2008 Systems: Exit Lights (Battery Pack), Emergency Lighting (Battery Pack), Computer Lab Room 106 (Raceway With Receptacles) Years: 2006 Systems: Emergency Light/Exit Light Panel Years: 2003 Systems: Intrusion Alarm System Years: 1993 Systems: Auditorium (Theater Lighting System) Years: 2016 Below Ground
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Sprinkler Flow/Air Pressure Switch	Main Electrical Room	David Copeland	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on Ground Floor	Inspected
House Lighting	
Instance on Ground Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Ground Floor	Does not exist
Surface Mounted	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Ground Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not exist
Lighting Fixture - LED	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Does not exist
Recessed Mounted	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Ground Floor	Does not exist
Local Sound System	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Ground Floor	Inspected
Dimming System	
Instance on Ground Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on Ground Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Mezzanine	Inspected
Lighting	
Instance on Mezzanine	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Mezzanine	Inspected
Pendant Mounted	
Instance on Mezzanine	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Mezzanine	Does not exist
Surface Mounted	
Instance on Mezzanine	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Mezzanine	Does not exist
Lighting Fixture - Incandescent	
Instance on Mezzanine	Does not exist
Lighting Fixture - LED	
Instance on Mezzanine	Does not exist
Local Sound System	
Instance on Mezzanine	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on Mezzanine	Does not exist
Theater Lighting System	
Instance on Mezzanine	Does not exist
CITY FIRE ALARM SYSTEM	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - LED	Does not exist
COMPUTER LAB	
Instance on Rooms 106, 225	Inspected
Power Panel?	Yes
Lighting	
Instance on Rooms 106, 225	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 106, 225	Inspected
Pendant Mounted	
Instance on Rooms 106, 225	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 106, 225	Does not exist
Surface Mounted	
Instance on Rooms 106, 225	Does not exist
Lighting Fixture - HID	
Instance on Rooms 106, 225	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 106, 225	Does not exist
Lighting Fixture - LED	
Instance on Rooms 106, 225	Does not exist
Raceway With Receptacles	
Instance on Rooms 106, 225	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Ground Floor Corridor By Locker Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Mezzanine and Ground Floor Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
EMERGENCY LIGHTING	
Non Battery Pack	
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor By Staircase B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Does not exist
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Does not exist
Elevator Recall	Does not exist
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	10
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	95,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	5- Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Main Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Strobe	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	95,000
Quantity Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	1- Good
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on Ground Floor	Inspected
Lighting	
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Does not exist
Lighting Fixture - HID	
Instance on Ground Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not exist
Lighting Fixture - LED	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Does not exist
Recessed Mounted	
Instance on Ground Floor	Does not exist
Surface Mounted	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on Ground Floor	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on Ground Floor	Does not exist
Scoreboard	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Ground Floor	Does not exist
INTERCOM SYSTEM	
	Does not exist
KITCHEN	
Instance on Mezzanine	Inspected
Lighting	
Instance on Mezzanine	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Mezzanine	Inspected
Pendant Mounted	
Instance on Mezzanine	Does not exist
Recessed Mounted	
Instance on Mezzanine	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Mezzanine	Does not exist
Lighting Fixture - HID	
Instance on Mezzanine	Does not exist
Lighting Fixture - Incandescent	
Instance on Mezzanine	Does not exist
Lighting Fixture - LED	
Instance on Mezzanine	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 108	Inspected
Lighting	
Instance on Room 108	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 108	Inspected
Pendant Mounted	
Instance on Room 108	Does not exist
Recessed Mounted	
Instance on Room 108	Does not exist
Surface Mounted	
Instance on Room 108	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 108	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 108	Does not exist
Lighting Fixture - LED	
Instance on Room 108	Does not exist
Projection System	
Instance on Room 108	Does not exist
Raceway With Receptacles	
Instance on Room 108	Does not exist
LIGHTNING PROTECTION	
Condition	1- Good
Deficiency	No deficiencies recorded
LOCKER ROOM	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
LOCKER ROOM	
Instance on Ground Floor	Inspected
Alternative Use	Yes
Lighting	
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Does not exist
Recessed Mounted	
Instance on Ground Floor	Does not exist
Surface Mounted	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Ground Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not exist
Lighting Fixture - LED	
Instance on Ground Floor	Does not exist
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	
	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room M16, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	
	Does not exist
Fused Toggle Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Inspected
Condition	1- Good
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	General Office - Room 117
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2008
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
Instance on Room 209	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 209	Does not exist
Emergency Shut-Off Power	
Instance on Room 209	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 209	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 209	Inspected
Pendant Mounted	
Instance on Room 209	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 209	Does not exist
Surface Mounted	
Instance on Room 209	Does not exist
Lighting Fixture - HID	
Instance on Room 209	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 209	Does not exist
Lighting Fixture - LED	
Instance on Room 209	Does not exist
Power Supply	
Instance on Room 209	Does not exist
Projection System	
Instance on Room 209	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT2
Installation Year	1993
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Does not exist
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	41
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M161

Question	Response
SERVICE SWITCH	
EquipmentId	Service Switch #1
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Number of Spares	4
Air Circuit Breaker Type	
	Does not exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Does not exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
	Does not exist
Surface Mounted	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Electrical Inspection

M161

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Does not exist