

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M194

Asset: P.S. 194 - MANHATTAN, 244 WEST 144 STREET, New York, 10030

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|---------------------|---------------------|
| EE : M194 | Electrical | 2017-12-12 10:51 AM | 2017-12-26 12:11 PM |

Asset Data

| Question | Answer |
|---|--|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: Interior Fluorescent Lighting and LED Lighting, Exit Lights (Battery Pack), IPDVS/CCTV System, Partial Emergency Lighting (Non Battery Pack) |
| | Years: 2016 |
| | Systems: Fused Disconnect Switch Type Panel Board, Lightning Protection |
| | Years: 2010 |
| | Systems: Service Switch, Switchboard, Public Address System, Local Sound System, Telephone System, LAN, Auxiliary Signal/Bell System, Security Lights, Molded Case Circuit Breaker Panel Board |
| | Years: 2008 |
| | Systems: Fire Alarm System |
| | Years: 2002 |
| | Systems: Intrusion Alarm System, Emergency Light/Exit Light Panel |
| | Years: 2000 |
| | Systems: Auditorium (House Lighting) |
| | Years: 1999 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|---------------------------------------|-----------------------|--------------------|--|--------------------|-----------------|-------------|------------|
| Yes | Water Leaks onto Electrical Equipment | N/A | Electrical | Boiler Room by Junction Box for Water Main | Derek Stewart | Fireman | Sent to DSF | |

Inspection

| Question | Response |
|---------------------------------------|----------------|
| Electrical | |
| AUDITORIUM | Inspected |
| Instance on 1st Floor | Inspected |
| House Lighting | Inspected |
| Does a Chandelier exist? | Yes |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Inspected |
| Instance on 1st Floor | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M194

| Question | Response |
|--|------------------------------------|
| AUDITORIUM | |
| House Lighting | |
| Lighting Fixture - HID | |
| Pendant Mounted | |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 8 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Surface Mounted | |
| Instance on 1st Floor | Does not Exist |
| Recessed Mounted | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | |
| Instance on 1st Floor | Inspected |
| Installation Year | 2008 |
| Source of Installation | Documented |
| Condition | 4 - Between Fair and Poor |
| Deficiency | MICROPHONE / JACK NOT OPERATIONAL |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Projection System | |
| Instance on 1st Floor | Does not Exist |
| Theater Lighting System | |
| Instance on 1st Floor | Does not Exist |
| CAFETERIA | |
| Instance on Basement | Inspected |
| Lighting | Inspected |

NYC Department of Education
 Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|--|--------------------------|
| CAFETERIA | |
| Lighting | |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | |
| Instance on Basement | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Basement | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not Exist |
| Local Sound System | |
| Instance on Basement | Inspected |
| Installation Year | 2008 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Basement | Does not Exist |
| Theater Lighting System | |
| Instance on Basement | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Does not Exist | |
| Lighting Fixture - HID | |
| Does not Exist | |
| Lighting Fixture - Incandescent | |
| Does not Exist | |
| Lighting Fixture - LED | |
| Inspected | |
| Pendant Mounted | |
| Does not Exist | |
| Surface Mounted | |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|--|--------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | |
| Lighting Fixture - LED | |
| Recessed Mounted | Does not Exist |
| COMPUTER LAB | Does not Exist |
| GYMNASIUM | Inspected |
| Instance on 3rd Floor | Inspected |
| Lighting | Inspected |
| Instance on 3rd Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 3rd Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 3rd Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Surface Mounted | Inspected |
| Instance on 3rd Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on 3rd Floor | Inspected |
| Installation Year | 2008 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Scoreboard | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| KITCHEN | Inspected |
| Instance on Basement | Inspected |
| Lighting | Inspected |
| Instance on Basement | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Basement | Inspected |
| Pendant Mounted | Inspected |
| Instance on Basement | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Basement | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M194

| Question | Response |
|--|--------------------------|
| KITCHEN | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | Does not Exist |
| Instance on Basement | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Basement | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Basement | Does not Exist |
| LIBRARY | Inspected |
| Instance on Room 311 | Inspected |
| Lighting | Inspected |
| Instance on Room 311 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 311 | Inspected |
| Pendant Mounted | Inspected |
| Instance on Room 311 | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Room 311 | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on Room 311 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 311 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 311 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 311 | Does not Exist |
| Raceway With Receptacles | Does not Exist |
| Instance on Room 311 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Room 311 | Does not Exist |
| LOCKER ROOM | Does not Exist |
| MULTIPURPOSE ROOM | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting | Inspected |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|--|--------------------------|
| MULTIPURPOSE ROOM | |
| Lighting | |
| Lighting Fixture - LED | |
| Pendant Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Surface Mounted | Inspected |
| Instance on 1st Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on 1st Floor | Inspected |
| Installation Year | 2008 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on 1st Floor | Does not Exist |
| SCIENCE DEMO ROOM | Does not Exist |
| SCIENCE LAB | Does not Exist |
| SCIENCE PREP ROOM | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|---|--------------------------------------|
| TOILET ROOM - STUDENT | Inspected |
| Lighting | |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 75,000 |
| Replacement Uom | S.F. |
| Condition | 2 - Between Good and Fair |
| Deficiency | DOOR PUSH BUTTON NOT OPERATIONAL |
| Deficiency Location/Instance | Wall facing Playground |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LESS THAN 20% SPARE CIRCUIT BREAKERS |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | Gymnasium |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Non Battery Pack | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | Gymnasium |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|-------------------------------|------------------------------|
| EMERGENCY LIGHTING | Inspected |
| Non Battery Pack | |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 1 - Good |
| Deficiency | FIXTURE LAMP NOT OPERATIONAL |
| Deficiency Location/Instance | By Room 402 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT/EMERGENCY LIGHT | Does not Exist |
| CITY FIRE ALARM SYSTEM | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| FIRE ALARM SYSTEM | Inspected |
| Replacement Quantity | 75,000 |
| Replacement Uom | S.F. |
| Bell/Horn | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Manual Pull Station | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Duct Smoke Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Area Smoke Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| CO Detector | Does not Exist |
| Heat Detector | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Elevator Recall | Does not Exist |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M194

| Question | Response |
|--|------------------------------------|
| FIRE ALARM SYSTEM | |
| Elevator Recall | Does not Exist |
| Magnetic Door Holder/Contactor | Does not Exist |
| Fused Cutout Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | Does not Exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Edwards System Technology |
| Equipment | Fire Alarm Control Panel |
| Model | EST 2 |
| Capacity/Size Quantity | 24 |
| Capacity/Size UOM | Zones |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 2002 |
| Source of Installation | Documented |
| Deficiency | PANEL DIRECTION/DIAGRAM IS MISSING |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fire Alarm Control Panel (Standard) | Does not Exist |
| Sub-Panel | Does not Exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not Exist |
| Panel | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not Exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|---|--|
| FIRE ALARM SYSTEM | Inspected |
| Tamper Flow Switch/Chain | |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | Does not Exist |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| MOTOR CONTROL CENTER | Does not Exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3 - Fair |
| Deficiency | MOTOR STARTER NOT OPERATIONAL |
| Deficiency Location/Instance | Roof Mechanical Room (TOILET SHOWER EXH) |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PANEL BOARD DOOR LOCK IS MISSING |
| Deficiency Location/Instance | Gymnasium |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | By Rooms (314, 411) |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|---|--|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Location/Instance | By Room 214, Gymnasium, Basement Mechanical Room |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 75,000 |
| Replacement Uom | S.F. |
| Instance | General Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Dukane 250 |
| Installation Year | 2008 |
| Source of Installation | Documented |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | 4th Floor Classrooms |
| Deficiency Quantity | 12 |
| Quantity Uom | EACH |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Replacement Quantity | 75,000 |
| Replacement Uom | S.F. |
| Installation Year | 2016 |
| Source of Installation | Custodial Staff |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | Inspected |
| Replacement Quantity | 75,000 |
| Replacement Uom | S.F. |

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

M194

| Question | Response |
|-------------------------------------|---------------------------|
| SECURITY | |
| Intrusion Alarm System | |
| Central Control Panel | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 50P |
| Installation Year | 2000 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Ultrasonic Sensor | Does not Exist |
| Lighting - Security | Inspected |
| Replacement Quantity | 26 |
| Replacement Uom | EACH |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| SERVICE SWITCH | Inspected |
| Instance | Electrical Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Galaxy Switchgear |
| Equipment | N/A |
| Capacity/Size Quantity | 1,600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 2008 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| SWITCHBOARD | Inspected |
| Number of Spares | 7 |
| Air Circuit Breaker Type | Does not Exist |
| Fused Disconnect Switch Type | Inspected |
| Instance | Electrical Room |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

M194

| Question | Response |
|---|---------------------------|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | |
| Instance Manufacturer | Galaxy Switchgear |
| Equipment | MDB Section 1, 2, 3 |
| Capacity/Size Quantity | 1,600 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 3 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Service Switch Size |
| Installation Year | 2008 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Does not Exist |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | Does not Exist |
| TV SYSTEM | Does not Exist |