

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Asset: P.S. 32 - QUEENS, 171-11 35 AVENUE, New York, 11358

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q032	Electrical	2018-09-24 7:57 AM	2018-10-19 11:09 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Telephone System
	Years: 2018
	Systems: Auditorium (Local Sound System, Projection System)
	Years: 2017
	Systems: Gymnasium (LED Lighting)
	Years: 2015
	Systems: Auditorium (Projection System)
	Years: 2013
	Systems: Interior Fluorescent Lighting (Except Toilet Rooms)
	Years: 2011
	Systems: Fire Alarm System, Security Lights
	Years: 2009
	Systems: Most Exit/Emergency Lights
	Years: 2008
	Systems: Local Sound System, Public Address System
	Years: 2007
	Systems: Toilet Room (Fluorescent Lighting)
	Years: 2004
	Systems: Emergency Light/Exit Light Panel
	Years: 2001
	Systems: Fire Alarm System (Remote Annunciator)
	Years: 1997, 2009
	Systems: Intrusion Alarm System
	Years: 1997
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 1986, 2006, 2009

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Emergency Lighting - Battery Not Operational	Majority of the Batteries are Not Operational in Corridors and Stairways	EMERGENCY LIGHTING Battery Pack	2nd Floor Stairs (C/D, G, H), 3rd Floor Stairs (C/D, E, F, G, H), By Rooms (203, 206, 303, 306), Cafeteria, Electrical Room, Library, Exit 3 by Auditorium	Kathleen Luebkert	Custodian	Sent to DSF	

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Yes	Exit/Emergency Light - Battery Not Operational	Majority of the Batteries are Not Operational in Corridors and Stairways	EXIT/EMERGE NCY LIGHT	By Rooms (100, 106, 156, 209, 255, 261, 300, 310, 350, 353, 356, 358), Cafeteria	Kathleen Luebker	Custodian	Sent to DSF
-----	--	--	-----------------------	--	------------------	-----------	-------------

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2017
Source of Installation	Custodial Staff
Condition	1 - Good

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Question	Response
AUDITORIUM	
Local Sound System	
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Inspected
Instance on 1st Floor	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Installation Year	2007
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Inspected
Instance on Room 311	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 311	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 311	Inspected
Pendant Mounted	Inspected
Instance on Room 311	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 311	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 311	Does not Exist
Lighting Fixture - HID	
Instance on Room 311	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 311	Does not Exist
Lighting Fixture - LED	
Instance on Room 311	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 311	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q032

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2007
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not Exist
Scoreboard	
Instance on 1st Floor	Does not Exist
Theater Lighting System	
Instance on 1st Floor	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	
Instance on Room 315	Inspected
Lighting	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q032

Question	Response
LIBRARY	
Lighting	
Instance on Room 315	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 315	Inspected
Pendant Mounted	
Instance on Room 315	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 315	Does not Exist
Recessed Mounted	
Instance on Room 315	Does not Exist
Lighting Fixture - HID	
Instance on Room 315	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 315	Does not Exist
Lighting Fixture - LED	
Instance on Room 315	Does not Exist
Raceway With Receptacles	
Instance on Room 315	Does not Exist
Projection System	
Instance on Room 315	Does not Exist
LOCKER ROOM	
	Does not Exist
MULTIPURPOSE ROOM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2007
Source of Installation	Custodial Staff
Condition	3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q032

Question	Response
MULTIPURPOSE ROOM	
Local Sound System	Inspected
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	71,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q032

Question	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Condition	4 - Between Fair and Poor
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	2nd Floor Stairs (C/D, G, H), 3rd Floor Stairs (C/D, E, F, G, H), By Rooms (203, 206, 303, 306), Cafeteria, Electrical Room, Library, Exit 3 by Auditorium
Deficiency Quantity	19
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	35322409P
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	By Rooms (100, 106, 156, 209, 255, 261, 300, 310, 350, 353, 356, 358), Cafeteria
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	35322409P
CITY FIRE ALARM SYSTEM	
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
Replacement Quantity	71,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Question	Response
FIRE ALARM SYSTEM	
Fan Shutdown Control	Inspected
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Hallway Next to Room 148
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Fire Alarm Control Panel
Model	EST 2
Capacity/Size Quantity	10
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2009
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	
	Does not Exist
Sprinkler Flow/Air Pressure Switch	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
	Does not Exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
	Does not Exist
MOTOR CONTROL CENTER	
	Does not Exist
MOTOR STARTER/CONTACTOR	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, By Electrical Room
Deficiency Quantity	2

**NYC Department of Education
Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

Q032

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
	Does not Exist
Fused Toggle Switch Type	
	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room 148
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	By Room 351
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	By Rooms (102, 154, 204, 254, 261, 302, 356), Gymnasium, Cafeteria, Multipurpose Room, 2nd Building Addition Fan Room, Room 148
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Question	Response
PANEL BOARD	Inspected
Molded Case Circuit Breaker Type	
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	71,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2007
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	71,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1997
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not Exist
Lighting - Security	Inspected
Replacement Quantity	31
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Walls facing (35th Avenue, 171st Street, 172nd Street, Courtyard), Roof facing Courtyard
Deficiency Quantity	9

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Question	Response
SECURITY	
Lighting - Security	
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Meter Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Standard Switchboard
Equipment	N/A
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1962
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not Exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Standard Switchboard
Equipment	N/A
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1962
Source of Installation	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Electrical Inspection

Q032

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	
	Does not Exist
Molded Case Circuit Breaker Type	
	Does not Exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not Exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	
	Does not Exist