

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**Q910**

**Asset:** P.S. 95 TRANSPORTABLE - Q, 179-01 90TH AVENUE, New York, 11432

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q910	Electrical	2017-10-26 8:46 AM	2017-10-31 1:34 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Electrical Systems and Components
	Years: 1996

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Exit/Emergency Light - Not Operational	N/A	EXIT/EMERGE NCY LIGHT	T-1, T-2, T-3	Ariel Valle	Fireman	Sent to DSF	
Yes	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM   Main Panel   Fire Alarm Control Panel (Electronic)	T-2	Ariel Valle	Fireman	Sent to DSF	

Inspection

Question	Response
<b>Electrical</b>	
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>COMPUTER LAB</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**Q910**

<b>Question</b>	<b>Response</b>
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Does not Exist
<b>EXIT LIGHT</b>	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	T-1, T-2, T-3
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	2,600
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Does not Exist
<b>Duct Smoke Detector</b>	Does not Exist
<b>Area Smoke Detector</b>	Does not Exist
<b>CO Detector</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inaccessible
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	T-2
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST
Capacity/Size Quantity	4
Capacity/Size UOM	Zones

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q910

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1996
Source of Installation	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Remote Annunciator</b>	Does not Exist
<b>GROUNDING SYSTEM</b>	
	Inaccessible
<b>LAN</b>	
	Inspected
<b>Local Distribution Frame (I/LDF)</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	
	Does not Exist
<b>PANEL BOARD</b>	
	Inspected
<b>Molded Case Circuit Breaker Type</b>	
	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	T-4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	
	Inspected
Replacement Quantity	2,600
Replacement Uom	S.F.
Instance	Connected to Main Asset Q095
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

Q910

Question	Response
<b>PUBLIC ADDRESS SYSTEM</b>	
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1996
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Does not Exist
<b>Intrusion Alarm System</b>	Does not Exist
<b>Lighting - Security</b>	Inspected
Replacement Quantity	4
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Inaccessible
<b>SWITCHBOARD</b>	Inaccessible
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Does not Exist