#### **Building Condition Assessment Survey 2018-2019**

		- STATEN ISLAND, 58 SUN	IVIII SIKEEI,	, STATEN ISLA	ND, NY, 10307		
Inspectio	nId Inspection Type				Time 1	[n	Last Edited
	2314 MECHANICAL				2019-0	02-11 09:46AN	M 2019-02-15 01:21PM
sset Data							
Question				Answer			
Have any	Systems/Major Building	Components been upgraded?		Systems:	Fixtures - Toile	ets	
				Years:	2015		
				Systems:	Sprinkler Head	ls	
				Years:	2018		
	fuel tanks?			No			
	water main service entri-	es to the asset		1			
	n Rooms Locations			N/A			
Are there	any Emergency Stop Swi	itches with Missing Hammers?		No compo	onents		
Priority Co	ndition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded						
Inspection	!						
Question				Response			
Mechani	cal						
AIR CO	ONDITIONING			Does not e	exist		
CENTI	RAL ACID WASTE NE	UTRALIZING TANK		Does not e	exist		
CLIMA	ATE CONTROL SYSTE	EM		Inspected			
BMS				Does not e	exist		
Electr	ric System			Does not e	exist		
Hybr	id System			Does not e	exist		
Pneu	matic System			Inspected			
	Instance			Througho	ut		
	Instance Condition			3- Fair			
	Instance Quantity			1			
	Instance Quantity Uo			EACH			
		ed by Operational System		61-80%			
	Deficiency	w .				URE CONTR	OL THERMOSTAT
	Deficiency Location Deficiency Quantit			Gymnasıu 2	m, Room 3		
	Quantity Uom	У		EACH			
	Potential Action			MAINTE	NANCE		
	Urgency of Action			PRIORIT			
	Purpose of Action			LEVEL 2			
	Violations			No violati	ons recorded		
	Deficiency			DEFECTI	VE TERMINAL	UNIT CONT	ROL VALVE
	Deficiency Location			Room 3			
	Deficiency Quantit	у		1			
	Quantity Uom			EACH			
	Potential Action			MAINTE			
	Urgency of Action Purpose of Action			PRIORIT LEVEL 2	1 3		
Violations  Deficiency					ons recorded		
					TIC TUBING:D	EEECTIVE/F	EAKS AID
	Deficiency Location	n/Instance		Basement	TIC TODING:D	LIECTIVE/L	LAKSAIK
	Deficiency Quantit			20			
	Quantity Uom	<del>.</del>		L.F.			
	Potential Action			MAINTE	NANCE		
	Urgency of Action			PRIORIT	Y 3		

#### **Building Condition Assessment Survey 2018-2019**

Mechanical Inspection	K802

Question	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected Inspected
Domestic Cold Water System	Does not exist
Gravity System	Does not exist  Does not exist
Pressure Booster System Water Service	Inspected
Instance	Basement
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency I costion/Instance	Basement Basement
Deficiency Location/Instance Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
Enclosed IDF Room	
Instance on Closet inside Room 8	Inspected
·	•

#### **Building Condition Assessment Survey 2018-2019**

Mechanical Inspection R802

nunicui Inspection	Ro
Question	Response
Enclosed IDF Room	
Dedicated A/C Equipment	
Instance on Closet inside Room 8	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Closet inside Room 8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	1st Floor Corridor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Does not exist
	Does not exist
GAS FIRED FURNACE	
GAS SERVICE	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR: DEFECTIVE

#### **Building Condition Assessment Survey 2018-2019**

Mechanical Inspection	R802
Question	Response

stion	Response		
EATING			
Radiator/Convector/Fin Tube			
Deficiency Location/Instance	Basement		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
team Heating	Inspected		
F&T/Steam Drip Trap	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
MER Steam and Condensate Piping	Does not exist		
Steam Condensate Return Piping	Inspected		
Condition	3- Fair		
Deficiency	DEFECTIVE ISOLATION VALVE		
Deficiency Location/Instance	Basement		
Deficiency Quantity	)		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Deficiency	DEFECTIVE/LEAKS		
Deficiency Location/Instance Deficiency Quantity	Basement		
	40		
Quantity Uom	L.F.		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Steam Condensate Return Pumping System	Does not exist		
Steam Piping	Inspected		
Condition	3- Fair		
Deficiency	DEFECTIVE ISOLATION VALVE		
Deficiency Location/Instance	Basement		
Deficiency Quantity	4		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Deficiency	DEFECTIVE/LEAKS		
Deficiency Location/Instance	Basement		
Deficiency Quantity	10		
Quantity Uom	L.F.		
Potential Action	REPLACE		
1 otential 7 tetion	PRIORITY 3		
Urgency of Action	LEVEL 2		
	LEVEL 2 No violations recorded		
Urgency of Action Purpose of Action Violations	No violations recorded		
Urgency of Action Purpose of Action Violations  Terminal Unit Thermostatic Trap	No violations recorded  Inspected		
Urgency of Action Purpose of Action Violations	No violations recorded		

# **Building Condition Assessment Survey 2018-2019**

#### Mechanical Inspection R802

Question	Response	
HEATING		
Unit Heater/Cabinet Heater	Does not exist	
HEATING PLANT	Does not exist	
KITCHEN	Does not exist	
MDF Room	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Does not exist	