

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

School: **I.S. 98 - BRONX, 1619 BOSTON RD, BRONX, NY, 10460**

InspectionId	Inspection Type	Time In	Last Edited
1892	ELECTRICAL	2019-01-29 12:39PM	2019-05-22 03:10PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Public Address System, Local Sound System, Auxiliary Signal/Bell System, Emergency Light/Exit Light Panel, Battery Type Exit Lights, Interior Lighting Except Chandeliers Years: 2006 Systems: Science Labs Equipment, Telephone System Years: 2009 Systems: Partial Molded Case Circuit Breaker Panels Years: 2000, 2006 Systems: Intrusion Alarm System Years: 1998 Systems: IPDVS/CCTV System, Intrusion Alarm Central Control Panel Years: 2014 Systems: Security Lights Years: 2000 Systems: Auditorium Theater Lighting System, Partial Switchboard Years: 2008 Systems: Fire Alarm System, LAN Years: 2007 Systems: Exit/Emergency Lights, Emergency Lighting (Battery Pack) Years: 2018 Systems: Fire Alarm System (Sprinkler Flow Switch) Years: 2019
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Fire Alarm System - Components Not Operational	Not Operational	Fire Alarm System - Magnetic Door Holder/Contact	Corridors Throughout the Building	Sander Quarri	Fireman	No Photo Taken
No	Public Address System - Speakers Not Operational	35 Speakers Not Operational	Public Address System	4th Floor Gymnasium, Classrooms, Kitchen	Sander Quarri	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
AUDITORIUM	
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
CAFETERIA	
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	5- Poor
Deficiency Location/Instance	NOT OPERATIONAL
Deficiency Quantity	Outside General Office
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPAIR
Purpose of Action	PRIORITY 5
Violations	LEVEL 2
	No violations recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Condition	Inspected
Lighting	
Does a Chandelier Exist?	Inspected
	Yes
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	Does not exist
COMPUTER LAB	
Instance on Room 227	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 227	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 227	Inspected
Pendant Mounted	
Instance on Room 227	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 227	Does not exist
Surface Mounted	
Instance on Room 227	Does not exist
Lighting Fixture - HID	
Instance on Room 227	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 227	Does not exist
Lighting Fixture - LED	
Instance on Room 227	Does not exist
Raceway With Receptacles	
Instance on Room 227	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
	Inspected
Battery Pack	
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	
	Does not exist
EXIT/EMERGENCY LIGHT	
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
EXIT/EMERGENCY LIGHT	
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35317209Y
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	5- Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridors Throughout the Building
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	32
Capacity/Size UOM	Zones

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Diagram
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	
	Does not exist
Manual Pull Station	
	Inspected
Condition	2- Between Good and Fair
Deficiency	PULL STATION COVER IS MISSING
Deficiency Location/Instance	3rd Floor Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL COVER
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	
	Inspected
Display Monitor	
	Does not exist
Panel	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	
	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	
	Does not exist
Sprinkler Flow/Air Pressure Switch	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	
	Does not exist
Tamper Flow Switch/Chain	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 3rd Floor	Inspected
Instance on 4th Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Instance on 4th Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Instance on 4th Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Surface Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 4th Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 4th Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Scoreboard	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
Theater Lighting System	
Instance on 3rd Floor	Does not exist
Instance on 4th Floor	Does not exist
INTERCOM SYSTEM	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 319	Inspected
Lighting	
Instance on Room 319	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 319	Inspected
Pendant Mounted	
Instance on Room 319	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 319	Does not exist
Surface Mounted	
Instance on Room 319	Does not exist
Lighting Fixture - HID	
Instance on Room 319	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 319	Does not exist
Lighting Fixture - LED	
Instance on Room 319	Does not exist
Projection System	
Instance on Room 319	Does not exist
Raceway With Receptacles	
Instance on Room 319	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors Throughout the Building
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors, Mechanical Spaces and Cafeteria
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Computer Lab Room 227
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 123
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC2105
Installation Year	2006
Source of Installation Year	Documented

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Room 123
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors, Classrooms
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	4th Floor Gymnasium, Kitchen, Classrooms
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
SCIENCE DEMO ROOM	
Instance on Rooms 209, 306	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Rooms 307, 409	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
Emergency Shut-Off Power	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
Lighting	
Instance on Rooms 209, 306	Inspected
Instance on Rooms 307, 409	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 209, 306	Inspected
Instance on Rooms 307, 409	Inspected
Pendant Mounted	
Instance on Rooms 209, 306	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 307, 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
Lighting Fixture - HID	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
Lighting Fixture - LED	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
Power Supply	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
Projection System	
Instance on Rooms 209, 306	Does not exist
Instance on Rooms 307, 409	Does not exist
SCIENCE LAB	
Instance on Room 207	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 403	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 407	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 207	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 207	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 207	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
SCIENCE LAB	
Lighting	
Instance on Room 403	Inspected
Instance on Room 407	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 207	Inspected
Instance on Room 403	Inspected
Instance on Room 407	Inspected
Pendant Mounted	
Instance on Room 207	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 207	Does not exist
Instance on Room 403	Does not exist
Instance on Room 407	Does not exist
Surface Mounted	
Instance on Room 207	Does not exist
Instance on Room 403	Does not exist
Instance on Room 407	Does not exist
Lighting Fixture - HID	
Instance on Room 207	Does not exist
Instance on Room 403	Does not exist
Instance on Room 407	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 207	Inspected
Instance on Room 403	Does not exist
Instance on Room 407	Does not exist
Pendant Mounted	
Instance on Room 207	Does not exist
Recessed Mounted	
Instance on Room 207	Does not exist
Surface Mounted	
Instance on Room 207	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on Room 207	Does not exist
Instance on Room 403	Does not exist
Instance on Room 407	Does not exist
Power Supply	
Instance on Room 207	Inspected
Instance on Room 403	Inspected
Instance on Room 407	Inspected
Instructor Unit	
Instance on Room 207	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 207	Does not exist
Instance on Room 403	Does not exist
Instance on Room 407	Does not exist
Student Unit	
Instance on Room 207	Does not exist
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Does not exist
Projection System	
Instance on Room 207	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 403	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance on Room 400	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 405	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 400	Does not exist
Instance on Room 405	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 400	Does not exist
Instance on Room 405	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 400	Inspected
Instance on Room 405	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 400	Inspected
Instance on Room 405	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 400	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 405	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 400	Does not exist
Instance on Room 405	Does not exist
Surface Mounted	
Instance on Room 400	Does not exist
Instance on Room 405	Does not exist
Lighting Fixture - HID	
Instance on Room 400	Does not exist
Instance on Room 405	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 400	Does not exist
Instance on Room 405	Does not exist
Lighting Fixture - LED	
Instance on Room 400	Does not exist
Instance on Room 405	Does not exist
Power Supply	
Instance on Room 400	Does not exist
Instance on Room 405	Does not exist
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Custodian's Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2014
Source of Installation Year	Custodial Staff
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Exits 4 and 5
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
SECURITY	
Intrusion Alarm System	
Infrared Sensor	
Violations	No violations recorded
Panic Switch	
Condition	Inspected
Deficiency	3- Fair
Remote Annunciator	
Condition	No deficiencies recorded
Deficiency	Inspected
Siren/Strobe	
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
Condition	Inspected
Installation Year	1- Good
Source of Installation Year	2014
Deficiency	Documented
	No deficiencies recorded
Lighting - Security	
Condition	Inspected
Replacement Quantity	3- Fair
Replacement Uom	36
Deficiency	EACH
Deficiency Location/Instance	LIGHTING FIXTURE PHOTOCCELL NOT OPERATIONAL
Deficiency Quantity	Roof and Building Perimeter
Quantity Uom	5
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 3
	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Roof and Building Perimeter
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	
Instance	Inspected
Instance Condition	Electrical Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Standard Switchboard
Capacity/Size Quantity	2000A 3P&SN Press. Service Switch 1600A KRP-C Hi Cap
Capacity/Size UOM	Fuses
Source of Capacity/Size	1600
Installation Year	Amps
Source of Installation Year	Fuse Size
Deficiency	1963
Deficiency Location/Instance	Inspector Estimate
Deficiency Quantity	BEYOND USEFUL LIFE
	Electrical Room
	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
SERVICE SWITCH	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	1
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Standard Switchboard
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1963
Source of Installation Year	Inspector Estimate
Deficiency	FUSED DISCONNECT NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room Adjacent to Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	MDP
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2008
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X098

Question	Response
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	
	Does not exist
TV SYSTEM	
Cable System Exist?	Inspected
Operational?	Yes
Main Equipment Rack	Yes
	Does not exist