

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

School: I.S. 127 - BRONX, 1560 PURDY STREET, BRONX, NY, 10462

InspectionId	Inspection Type	Time In	Last Edited
1577	ELECTRICAL	2019-01-17 08:48AM	2019-06-19 01:42PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	<p>Systems: Science Demo - Rooms 350, 354 (Projection System) Years: 2018</p> <p>Systems: Auditorium (Projection System), Science Lab Room 152 (Projection System), LAN Years: 2017</p> <p>Systems: Telephone System Years: 2015</p> <p>Systems: Interior Fluorescent Lighting (Except Auditorium, Cafeterias, Kitchen, Toilet Rooms, Gymnasiums, Library, Boiler Room) Years: 2013</p> <p>Systems: IPDVS/CCTV System, Partial Emergency Lights (Battery Pack), Gymnasiums (Scoreboard) Years: 2012</p> <p>Systems: Science Rooms 150, 152 (Except Lighting) Years: 2007</p> <p>Systems: Computer Lab Room 149 (Raceway with Receptacles) Years: 2006</p> <p>Systems: Auditorium (Partial Theater Lighting) Years: 2003, 2009</p> <p>Systems: Public Address System, Local Sound System, Auditorium (Dimming System) Years: 2003</p> <p>Systems: Fire Alarm System (Electronic Sub-Panel, Partial Fuse Cutout Panel, Area Smoke Detectors, Elevator Recall) Years: 2002</p> <p>Systems: Security Lights Years: 2000</p> <p>Systems: Intrusion Alarm System Years: 1996</p> <p>Systems: Emergency Light/Exit Light Panel Years: 1995</p> <p>Systems: Partial Molded Case Circuit Breaker Panel Boards Years: 1995, 2003</p> <p>Systems: Interior Fluorescent Lighting (Library, Auditorium, Boiler Room, Cafeterias, Kitchen, Toilet Rooms) Interior LED Lighting (Auditorium, Gymnasiums), Most Exit Lights (Battery Pack) Years: 2016</p>
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Thomas Silverbird	Fireman	No Photo Taken

Inspection

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
AUDITORIUM	
Theater Lighting System	
Theater Lighting	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	Inspected
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
Lighting	
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
Pendant Mounted	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
Recessed Mounted	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement - Staff	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Basement - Students	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
Lighting Fixture - LED	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
Local Sound System	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	2003
Source of Installation Year	Custodial Staff
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
CAFETERIA	
Local Sound System	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
Theater Lighting System	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	3- Fair
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Condition	Inspected
Lighting	
Does a Chandelier Exist?	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Recessed Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Surface Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
COMPUTER LAB	
Instance on Room 149	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 149	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 149	Inspected
Pendant Mounted	
Instance on Room 149	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 149	Does not exist
Surface Mounted	
Instance on Room 149	Does not exist
Lighting Fixture - HID	
Instance on Room 149	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 149	Does not exist
Lighting Fixture - LED	
Instance on Room 149	Does not exist
Raceway With Receptacles	
Instance on Room 149	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
COMPUTER LAB	
Raceway With Receptacles	
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Does not exist
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Basement Corridor Original Building
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	N/A
Capacity/Size Quantity	9

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1953
Source of Installation Year	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Corridor Original Building
Deficiency Quantity	130,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Does not exist
Printer	Does not exist
Punch Register	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Basement Corridor Original Building
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	AFP - 300
EquipmentId	Elevator Smoke Detection Panel
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Diagram
Installation Year	2002
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	
Instance	Basement Corridor Original Building
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	SPKLR. CONT. DB.
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1953
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Corridor Original Building
Deficiency Quantity	130,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement Corridor Original Building
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	REGISTER CONTROL BOARD
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1953
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Corridor Original Building
Deficiency Quantity	130,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	Inspected
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor - Boys	Inspected
Instance on 1st Floor - Girls	Inspected
Lighting	
Instance on 1st Floor - Boys	Inspected
Instance on 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Girls	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Boys	Does not exist
Instance on 1st Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys	Does not exist
Instance on 1st Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys	Inspected
Instance on 1st Floor - Girls	Inspected
Pendant Mounted	
Instance on 1st Floor - Boys	Does not exist
Instance on 1st Floor - Girls	Does not exist
Recessed Mounted	
Instance on 1st Floor - Boys	Does not exist
Instance on 1st Floor - Girls	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor - Boys	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls	Does not exist
Local Sound System	
Instance on 1st Floor - Boys	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Custodial Staff
Deficiency	SPEAKER POORLY PROTECTED FROM PHYSICAL DAMAGE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Girls	Inspected
Instance Condition	3- Fair
Installation Year	2003
Source of Installation Year	Custodial Staff
Deficiency	SPEAKER POORLY PROTECTED FROM PHYSICAL DAMAGE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor - Boys	Does not exist
Instance on 1st Floor - Girls	Does not exist
Scoreboard	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
GYMNASIUM	
Scoreboard	
Instance on 1st Floor - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor - Boys	Does not exist
Instance on 1st Floor - Girls	Does not exist
INTERCOM SYSTEM	
Elevator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	
Does not exist	
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LAN	
Inspected	
Local Distribution Frame (I/LDF)	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Inspected	
Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 1B/1C	Inspected
Lighting	
Instance on Room 1B/1C	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 1B/1C	Inspected
Pendant Mounted	
Instance on Room 1B/1C	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on Room 1B/1C	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 1B/1C	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 1B/1C	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 1B/1C	Does not exist
Lighting Fixture - LED	
Instance on Room 1B/1C	Does not exist
Projection System	
Instance on Room 1B/1C	Does not exist
Raceway With Receptacles	
Instance on Room 1B/1C	Does not exist
LIGHTNING PROTECTION	
	Does not exist
LOCKER ROOM	
	Does not exist
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
MULTIPURPOSE ROOM	
	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
	Does not exist
Fused Knife Switch Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE Basement Corridor By Boiler Room (Original building), Mechanical Room B4, Basement Corridor - By Room B10
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE Auditorium, Kitchen, Corridor near Rooms 148, 206, 250, Basement Corridor - By Boiler Room (Original Building), Projection Room
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Gymnasium Boys
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
Instance	Inspected
Instance Condition	General Office - Room 103
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC2100
Installation Year	2003
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Instance on Rooms 246, 250, 254	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Rooms 350, 354	Inspected
Power Panel?	No
Alternative Use	Yes
Emergency Gas Shut-Off Valve	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Emergency Shut-Off Power	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Lighting	
Instance on Rooms 246, 250, 254	Inspected
Instance on Rooms 350, 354	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 246, 250, 254	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Rooms 350, 354	Inspected
Pendant Mounted	
Instance on Rooms 246, 250, 254	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 350, 354	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Surface Mounted	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Lighting Fixture - HID	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Lighting Fixture - LED	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Power Supply	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Does not exist
Projection System	
Instance on Rooms 246, 250, 254	Does not exist
Instance on Rooms 350, 354	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance on Room 152	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 152	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 152	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 152	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 152	Inspected
Pendant Mounted	
Instance on Room 152	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 152	Does not exist
Surface Mounted	
Instance on Room 152	Does not exist
Lighting Fixture - HID	
Instance on Room 152	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 152	Inspected
Pendant Mounted	
Instance on Room 152	Does not exist
Recessed Mounted	
Instance on Room 152	Does not exist
Surface Mounted	
Instance on Room 152	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on Room 152	Does not exist
Power Supply	
Instance on Room 152	Inspected
Instructor Unit	
Instance on Room 152	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 152	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 152	Does not exist
Projection System	
Instance on Room 152	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance on Room 150	Inspected
Power Panel?	No
Alternative Use	No
Instance on Rooms 252, 352	Inspected
Power Panel?	No
Alternative Use	Yes
Emergency Gas Shut-Off Valve	
Instance on Room 150	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 352	Does not exist
Emergency Shut-Off Power	
Instance on Room 150	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
SCIENCE PREP ROOM	
Emergency Shut-Off Power	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 352	Does not exist
Lighting	
Instance on Room 150	Inspected
Instance on Rooms 252, 352	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 150	Inspected
Instance on Rooms 252, 352	Inspected
Pendant Mounted	
Instance on Room 150	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 252, 352	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 150	Does not exist
Instance on Rooms 252, 352	Does not exist
Surface Mounted	
Instance on Room 150	Does not exist
Instance on Rooms 252, 352	Does not exist
Lighting Fixture - HID	
Instance on Room 150	Does not exist
Instance on Rooms 252, 352	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 150	Does not exist
Instance on Rooms 252, 352	Does not exist
Lighting Fixture - LED	
Instance on Room 150	Does not exist
Instance on Rooms 252, 352	Does not exist
Power Supply	
Instance on Room 150	Does not exist
Instance on Rooms 252, 352	Does not exist
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Custodian's Office - Room 109
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1996
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Service Switch A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1953
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Service Switch B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1953
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
SWITCHBOARD	Inspected
Number of Spares	2
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric
EquipmentId	Main Distribution Board Section A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1953
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric
EquipmentId	Main Distribution Board Section B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1953
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X127

Question	Response
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not exist