

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

School: **I.S. 129 (PAIRED W P234) - BRONX, 2055 MAPES AVENUE, BRONX, NY, 10460**

InspectionId	Inspection Type	Time In	Last Edited
4192	ELECTRICAL	2019-04-30 08:06AM	2019-04-30 04:24PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Intrusion Alarm System Years: 2016 Systems: Kitchen (Fluorescent Lighting) Years: 2014 Systems: Interior Fluorescent Lighting (Except Science Lab - Room 431, Science Prep Room 429, Auditorium, Kitchen), Exit/Emergency Lights Years: 2013 Systems: Science Lab - Room 431, Science Prep Room 429 Years: 2012 Systems: IPDVS/CCTV System Years: Under Construction Systems: Telephone System Years: 2010 Systems: Fire Alarm System, Local Sound System, Public Address System Years: 2009 Systems: Auditorium (House Lighting, Theatre Lighting System, Projection System), Auxiliary Signal/Bell System Years: 2008 Systems: Security Lights Years: 2018 Systems: Partial Molded Case Circuit Breaker Panel Board Years: 1990, 2000, 2011 Systems: Emergency Light/Exit Light Panel Years: 1990
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Leaks onto Electrical Equipment	N/A	Other (Non-PBS Related)	Electrical Room, Room 223	Joseph Lopez	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Rooms 127, 134	Inspected
Lighting	
Instance on Rooms 127, 134	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 127, 134	Inspected
Pendant Mounted	
Instance on Rooms 127, 134	Does not exist
Recessed Mounted	
Instance on Rooms 127, 134	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 127, 134	Does not exist
Lighting Fixture - HID	
Instance on Rooms 127, 134	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 127, 134	Does not exist
Lighting Fixture - LED	
Instance on Rooms 127, 134	Does not exist
Local Sound System	
Instance on Rooms 127, 134	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 127, 134	Does not exist
Theater Lighting System	
Instance on Rooms 127, 134	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	20
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE
Quantity Uom	20
Potential Action	EACH
Urgency of Action	REPLACE BALLAST
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	
Instance on Room 233	Inspected
Power Panel?	No
Instance on Room 333	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 233	Inspected
Instance on Room 333	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 233	Inspected
Instance on Room 333	Inspected
Pendant Mounted	
Instance on Room 233	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 333	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Surface Mounted	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Lighting Fixture - HID	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Lighting Fixture - LED	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Raceway With Receptacles	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
COMPUTER LAB	
Raceway With Receptacles	
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 333	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	Inspected
	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	
	Inspected
Battery Pack	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
	Inspected
Area Smoke Detector	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	
	Does not exist
Duct Smoke Detector	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
FIRE ALARM SYSTEM	
Fan Shutdown Control	
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Diagram
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIBRARY	Does not exist
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance	By Rooms (C10, 112, 134, 143, 212, 238, 310, 334), Auditorium, Kitchen
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	By Room C10
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 143
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2009
Source of Installation Year	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	
Instance on Room 431	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 431	Does not exist
Emergency Shut-Off Power	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 431	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 431	Inspected
Pendant Mounted	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 431	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 431	Does not exist
Lighting Fixture - HID	
Instance on Room 431	Inspected
Pendant Mounted	
Instance on Room 431	Does not exist
Recessed Mounted	
Instance on Room 431	Does not exist
Surface Mounted	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - Incandescent	
Instance on Room 431	Does not exist
Lighting Fixture - LED	
Instance on Room 431	Does not exist
Power Supply	
Instance on Room 431	Does not exist
Projection System	
Instance on Room 431	Does not exist
SCIENCE PREP ROOM	
Instance on Room 429	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 429	Does not exist
Emergency Shut-Off Power	
Instance on Room 429	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 429	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 429	Inspected
Pendant Mounted	
Instance on Room 429	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 429	Does not exist
Surface Mounted	
Instance on Room 429	Does not exist
Lighting Fixture - HID	
Instance on Room 429	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 429	Does not exist
Lighting Fixture - LED	
Instance on Room 429	Does not exist
Power Supply	
Instance on Room 429	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 102
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Under construction
Lighting - Security	Inspected
Condition	1- Good
Replacement Quantity	43
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C12
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1971
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X129

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C12
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1971
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Electrical Inspection

X129

Question	Response
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not exist