

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

School: **I.S. 131 - BRONX, 885 BOLTON AVENUE, BRONX, NY, 10473**

InspectionId	Inspection Type	Time In	Last Edited
2007	ELECTRICAL	2019-01-31 09:50AM	2019-02-01 02:49PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Fire Alarm System, Public Address System, Local Sound System, Auxiliary Signal/Bell System, Telephone System Years: 2007 Systems: Gymnasium (Scoreboard) Years: 2008 Systems: Intrusion Alarm System, Security Lights, LAN, Most Motor Starter/Contactor Years: 2011 Systems: Interior Lighting (Except Library) Years: 2014 Systems: IPDVS/CCTV System, Library Years: 2013 Systems: Emergency Light/Exit Light Panel Years: 1992 Systems: Fire Alarm System (Sprinkler Flow/Air Pressure Switch) Years: 2017 Systems: Fire Alarm System (Sub Panel, CO Detector) Years: Under Construction Systems: Transformer Years: 2016 Systems: Auditorium (Theater Lighting System) Years: 1999 Systems: Partial Molded Case Circuit Breaker Panel Board Years: 1994, 2000, 2013 Systems: Gymnasium (Most LED Lighting), Partial Emergency Lighting (Battery Pack) Years: 2018
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Public Address System - Speakers Not Operational	N/A	Public Address System	Gymnasium, Students Cafeteria	Fernando Adorno	Fireman	No Photo Taken

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	
Instance on 1st Floor	Inspected
<b>House Lighting</b>	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	CASSETTE/CD PLAYER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE CASSETTE/CD PLAYER
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Projection System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Lighting</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor - Students	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

<b>Question</b>	<b>Response</b>
<b>CAFETERIA</b>	
<b>Local Sound System</b>	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Staff	Does not exist
<b>Projection System</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Theater Lighting System</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
Condition	Inspected
<b>Lighting</b>	
Does a Chandelier Exist?	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Condition	Inspected
<b>Pendant Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Condition	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Condition	Does not exist
<b>Lighting Fixture - LED</b>	
Condition	Does not exist
<b>COMPUTER LAB</b>	
Condition	Does not exist
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	
Condition	Does not exist
<b>EMERGENCY GENERATOR SET</b>	
Condition	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>EMERGENCY LIGHTING</b>	
Condition	Inspected
<b>Battery Pack</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
Condition	Inspected
<b>Battery Pack</b>	
Condition	Inspected
Deficiency	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

<b>Question</b>	<b>Response</b>
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	Does not exist
<b>FIRE ALARM SYSTEM</b>	Inspected
<b>Area Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Bell/Horn</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Under construction
<b>Duct Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Does not exist
<b>Fan Shutdown Control</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not exist
<b>Fused Cutout Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	Fire Alarm Control
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fire Alarm Control Panel (Standard)</b>	
	Does not exist
<b>Manual Pull Station</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Remote Annunciator</b>	
	Inspected
<b>Display Monitor</b>	
	Does not exist
<b>Panel</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Printer</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Punch Register</b>	
	No deficiencies recorded
<b>Sprinkler Flow/Air Pressure Switch</b>	
Condition	Inspected
Deficiency	1- Good
<b>Strobe</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Sub-Panel</b>	
	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>GROUNDING SYSTEM</b>	
Condition	Inspected
Deficiency	3- Fair
<b>GYMNASIUM</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	2007
Source of Installation Year	Custodial Staff
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not exist
<b>Scoreboard</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Does not exist
<b>INTERCOM SYSTEM</b>	
	Does not exist
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>LAN</b>	
	Inspected
<b>Local Distribution Frame (I/LDF)</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	
Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

<b>Question</b>	<b>Response</b>
<b>LAN</b>	
<b>Main Equipment Rack (MDF)</b>	
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance on Room 202	Inspected
<b>Lighting</b>	
Instance on Room 202	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 202	Inspected
<b>Pendant Mounted</b>	
Instance on Room 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 202	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 202	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 202	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 202	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 202	Does not exist
<b>Projection System</b>	
Instance on Room 202	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Raceway With Receptacles</b>	
Instance on Room 202	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not exist
<b>LOCKER ROOM</b>	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inaccessible
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Basement Mechanical Room, Mechanical Room 276
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

Question	Response
<b>PANEL BOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room, Basement Mechanical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room 412
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	3rd Floor Corridor By Room 318
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD BEYOND USEFUL LIFE

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Deficiency Location/Instance	Corridors, Gymnasium, Auditorium, Students Cafeteria, Kitchen, Basement Mechanical Room, Mechanical Room 276
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>PUBLIC ADDRESS SYSTEM</b>	
	Inspected
Instance	General Office - Room 109
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	
Installation Year	2007
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Students Cafeteria
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>SCIENCE DEMO ROOM</b>	
	Does not exist
<b>SCIENCE LAB</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Inspected
Power Panel?	Yes
Alternative Use	Yes
Instance on Rooms 230, 240	Inspected
Power Panel?	Yes
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 230, 240	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>Lighting</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Inspected
Instance on Rooms 230, 240	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Inspected
Instance on Rooms 230, 240	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 230, 240	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>Surface Mounted</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>Power Supply</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>Projection System</b>	
Instance on Rooms 225, 226, 227, 228, 231, 244	Does not exist
Instance on Rooms 230, 240	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 232	Inspected
Power Panel?	No
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 232	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 232	Does not exist
<b>Lighting</b>	
Instance on Room 232	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 232	Inspected
<b>Pendant Mounted</b>	
Instance on Room 232	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 232	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Room 232	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 232	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 232	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 232	Does not exist
<b>Power Supply</b>	
Instance on Room 232	Does not exist
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance	General Office - Room 109
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2011
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
Condition	2- Between Good and Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Room 115
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Panic Switch</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	2- Between Good and Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Ultrasonic Sensor</b>	
	Does not exist
<b>IPDVS/CCTV System</b>	
Condition	2- Between Good and Fair
Installation Year	2013

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	
Source of Installation Year	Custodial Staff
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	E116 - 1st Floor By Exit 2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Lighting - Security</b>	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	88
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Outside By Bolton Avenue
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room B15
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main SW. NO. 1
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B15
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main SW. NO. 2
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B15

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SWIMMING POOL</b>	
	Does not exist
<b>SWITCHBOARD</b>	
	Inspected
Number of Spares	0
<b>Air Circuit Breaker Type</b>	
	Does not exist
<b>Fused Disconnect Switch Type</b>	
	Inspected
Instance	Electrical Room B15
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main Switchboard NO.1
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B15
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement Mechanical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	Main Switchboard NO.2
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1966
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fused Knife Switch Type</b>	
	Does not exist
<b>Molded Case Circuit Breaker Type</b>	
	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X131**

<b>Question</b>	<b>Response</b>
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TRANSFORMER</b>	Inspected
Instance	Room B13
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Hammond
EquipmentId	N/A
Capacity/Size Quantity	225
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>TV SYSTEM</b>	Inspected
Cable System Exist?	Yes
Operational?	No
<b>Main Equipment Rack</b>	Does not exist