

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X951

School: **P.S.15 ANNEX (PLAY YARD) - BRONX, 2195 ANDREWS AVENUE, BRONX, NY, 10453**

| InspectionId | Inspection Type | Time In | Last Edited |
|--------------|-----------------|--------------------|--------------------|
| 2778 | ELECTRICAL | 2019-03-05 09:21AM | 2019-03-05 02:12PM |

Asset Data

| Question | Answer |
|---|---|
| Have any Systems/Major Building Components been upgraded? | Systems: Security Lights Years: 1995 |
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | No |
| Water Penetration In Electrical Room? | No |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
|-----------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|-------------|
| No condition recorded | | | | | | | |

Inspection

| Question | Response |
|--|----------------|
| Electrical | |
| ATHLETIC FIELD | Does not exist |
| AUDITORIUM | Does not exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Does not exist |
| CAFETERIA | Does not exist |
| CITY FIRE ALARM SYSTEM | Does not exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Does not exist |
| COMPUTER LAB | Does not exist |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not exist |
| EMERGENCY LIGHTING | Does not exist |
| EXIT LIGHT | Does not exist |
| EXIT/EMERGENCY LIGHT | Does not exist |
| FIRE ALARM SYSTEM | Does not exist |
| GROUNDING SYSTEM | Does not exist |
| GYMNASIUM | Does not exist |
| INTERCOM SYSTEM | Does not exist |
| KITCHEN | Does not exist |
| LAN | Does not exist |
| LIBRARY | Does not exist |
| LIGHTNING PROTECTION | Does not exist |
| LOCKER ROOM | Does not exist |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Does not exist |
| MULTIPURPOSE ROOM | Does not exist |
| PANEL BOARD | Does not exist |
| PUBLIC ADDRESS SYSTEM | Does not exist |
| SCIENCE DEMO ROOM | Does not exist |
| SCIENCE LAB | Does not exist |
| SCIENCE PREP ROOM | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X951

| Question | Response |
|-------------------------------|----------------------------------|
| SECURITY | Inspected |
| Intrusion Alarm System | Does not exist |
| IPDVS/CCTV System | Does not exist |
| Lighting - Security | Inspected |
| Condition | 5- Poor |
| Replacement Quantity | 5 |
| Replacement Uom | EACH |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Fence Around Play Yard |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| SERVICE SWITCH | Does not exist |
| SWIMMING POOL | Does not exist |
| SWITCHBOARD | Does not exist |
| TELEPHONE SYSTEM | Does not exist |
| TOILET ROOM - STAFF | Does not exist |
| TOILET ROOM - STUDENT | Does not exist |
| TRANSFORMER | Does not exist |
| TV SYSTEM | Does not exist |