

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K157**

**Asset:** P.S. 157 - BROOKLYN, 850 KENT AVENUE, New York, 11205

Inspection Id	Inspection Type	Time In	Last Edited
EE : K157	Electrical	2018-05-31 9:02 AM	2018-06-05 11:40 AM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Intrusion Alarm System (Partial Remote Annunciator, Central Control Panel, Partial Infrared Sensors)
	Years: 2017
	Systems: Interior Lighting, Fire Alarm System ( Sprinkler Flow/Air Pressure Switch, Tamper Flow Switch/Chain)
	Years: 2015
	Systems: Telephone System
	Years: 2013
	Systems: Security Lights
	Years: 2012
	Systems: Auditorium (Projection System)
	Years: 2009
	Systems: Computer Lab - Room 310 (Raceway With Receptacles)
	Years: 2008
	Systems: Fire Alarm System, Public Address System, Local Sound System, Molded Case Circuit Breaker Panel Board, Fused Disconnect Switch Type Panel Board, Emergency Light/Exit Light Panel, Service Switch, Switchboard, Exit Lights (Battery Pack)
	Years: 2007
	Systems: Motor Control Center
	Years: 2000
	Systems: Intrusion Alarm System
	Years: 1998

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Motor Control Center	Basement - Fan Room	Bryan Steiger	Fireman	Sent to DSF	

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on Basement	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement	Does not Exist
<b>Recessed Mounted</b>	
Instance on Basement	Does not Exist
<b>Local Sound System</b>	
Instance on Basement	Inspected
Installation Year	2007
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Is the projector on a cart or installed on the ceiling?	Cart
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on Basement	Inspected
<b>Dimming System</b>	
Instance on Basement	Does not Exist
<b>Theater Lighting</b>	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>CAFETERIA</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	2007
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>COMPUTER LAB</b>	Inspected
Instance on Room 310	Inspected
Power Panel	No

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	Inspected
Instance on Room 310	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 310	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 310	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 310	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 310	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 310	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 310	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 310	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 310	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>LIBRARY</b>	Inspected
Instance on Room 413	Inspected
<b>Lighting</b>	Inspected
Instance on Room 413	Inspected
<b>Lighting Fixture - Fluorescent</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 413	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 413	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 413	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 413	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 413	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 413	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 413	Does not Exist
<b>Raceway With Receptacles</b>	Does not Exist
Instance on Room 413	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 413	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Inspected
Instance on 1st Floor - East, 1st Floor - West	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor - East, 1st Floor - West	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - East, 1st Floor - West	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor - East, 1st Floor - West	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
<b>Local Sound System</b>	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on 1st Floor - East, 1st Floor - West	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 509	Inspected
Power Panel	No
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Room 509	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 509	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 509	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 509	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 509	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 509	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>Power Supply</b>	Does not Exist
Instance on Room 509	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 509A	Inspected
Power Panel	No
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on Room 509A	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 509A	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 509A	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 509A	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 509A	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 509A	Does not Exist
<b>Lighting Fixture - Incandescent</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

<b>Question</b>	<b>Response</b>
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	Inspected
Instance on Room 509A	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 509A	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Does not Exist
Instance on Room 509A	Does not Exist
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Room 509A	Does not Exist
<b>Power Supply</b>	Does not Exist
Instance on Room 509A	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
Replacement Quantity	102,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	
Does not Exist	
<b>EMERGENCY GENERATOR SET</b>	
Does not Exist	
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

<b>Question</b>	<b>Response</b>
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Location/Instance	Main Entrance Lobby
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	102,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Does not Exist
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not Exist
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Does not Exist
<b>Magnetic Door Holder/Contactor</b>	Does not Exist



**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Fire Alarm Control Panel
Model	EST 2
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	1 - Good

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	Inspected
<b>Tamper Flow Switch/Chain</b>	
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROL CENTER</b>	Inspected
Instance	Basement - Fan Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	5th Floor Corridor by Room 557
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	Inspected
<b>Molded Case Circuit Breaker Type</b>	
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	102,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2007
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Does not Exist
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	102,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BPT
Installation Year	2017
Source of Installation	Custodial Staff
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Infrared Sensor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K157

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Remote Annunciator</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not Exist
<b>Lighting - Security</b>	Inspected
Replacement Quantity	8
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Meter Room - Back of The Auditorium
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Service Switch #1
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	3
<b>Air Circuit Breaker Type</b>	Does not Exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room - Inside Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	MDB Section #1, 2
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

**K157**

Question	Response
<b>TELEPHONE SYSTEM</b>	
<b>PBX/Intercom</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist
<b>TV SYSTEM</b>	Inspected
Cable System Exist?	Yes
Operational?	No
<b>Main Equipment Rack</b>	Does not Exist