NYC Department of Education

Building Condition Assessment Survey 2018 - 2019

	spection							
Asset:	GRAND	ST CAMPUS AF	COLD E.D. HS)-K, 850 GRA	ND STREET, N	New York, 11225		
Inspection I	d Inspection	on Type				Time In		Last Edited
ME : K4	51 Mechanic	cal				2019-04-03	8:16 AM	2019-04-05 3:04 PM
Asset Data								
Question					Answer			
Are there fuel tanks?					No			
Total # of water main service entries to the asset					0			
MERs/Fan Rooms Locations					None			
Are there any spaces with Missing or Defective CO Detectors?					No			
Are there any Emergency Stop Switches with Missing Hammers?					No			
Are there any Painted/Obstructed Sprinkler Heads?					No			
Have any Systems/Major Building Components been upgraded?					No			
Priority Condit	ion							
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title S	tatus	PhotoImage
No condition rec	orded							
nspection								
Question				Response				
Mechanical								
AIR CONDITIONING				Does not Exist				
CLIMATE CONTROL SYSTEM				Does not Exist				
COMPACTOR				Does not Exist				
CONVEYING				Does not Exist				
DOMESTIC WATER SYSTEM				Does not Exist				
DRAIN/WASTE/VENT AND STORM SYSTEM				Does not Exist				
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)				Does not Exist				
FIXTURES				Does not Exist				
GAS FIRED FURNACE				Does not Exist				
GAS SERVICE				Does not Exist				
HEATING				Does not Exist				
HEATING PLANT				Does not Exist				
Enclosed IDF Room				Does not Exist				
MDF Room				Does not Exist				
SPRINKLERS, STANDPIPE, FIRE SYSTEM				Does not Exist				
SPRINKLE	RS, STANDPI	PE, FIRE SYSTEN	VI.		Does no	JI EXIST		