

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

K482

Asset: BUSHWICK AF - BROOKLYN, 400 IRVING AVENUE, New York, 11237

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| EE : K482 | Electrical | 2017-11-28 7:58 AM | 2017-11-28 9:47 PM |

Asset Data

| Question | Answer |
|---|--------------|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | No |
| Water Penetration in Electrical Room? | No |
| Have any Systems/Major Building Components been upgraded? | No |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|--------|------------|
| No condition recorded | | | | | | | | |

Inspection

| Question | Response |
|--|----------------|
| Electrical | |
| ATHLETIC FIELD | Inspected |
| Exterior Lighting | Does not Exist |
| Local Sound System | Does not Exist |
| Scoreboard | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Does not Exist |
| LOCKER ROOM | Does not Exist |
| TOILET ROOM - STAFF | Does not Exist |
| TOILET ROOM - STUDENT | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Does not Exist |
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not Exist |
| EMERGENCY LIGHTING | Does not Exist |
| EXIT LIGHT | Does not Exist |
| EXIT/EMERGENCY LIGHT | Does not Exist |
| FIRE ALARM SYSTEM | Does not Exist |
| GROUNDING SYSTEM | Does not Exist |
| LAN | Does not Exist |
| MOTOR CONTROL CENTER | Does not Exist |
| MOTOR STARTER/CONTACTOR | Does not Exist |
| PANEL BOARD | Does not Exist |
| PUBLIC ADDRESS SYSTEM | Does not Exist |
| SECURITY | Does not Exist |
| SERVICE SWITCH | Does not Exist |
| SWITCHBOARD | Does not Exist |
| TELEPHONE SYSTEM | Does not Exist |
| TRANSFORMER | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

K482

| Question | Response |
|-----------|----------------|
| TV SYSTEM | Does not Exist |
