

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Mechanical Inspection

K672

Asset: PRE-K CENTER @ 1223 CONEY ISLAND AVENUE - BROOKLYN, 1223 CONEY ISLAND AVENUE, New York, 11230

Inspection Id	Inspection Type	Time In	Last Edited
ME : K672	Mechanical	2021-01-14 9:24 AM	2021-05-06 3:41 PM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not Exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist
Cooling Coil in Ductwork	Does not Exist
Cooling Tower	Does not Exist
DX Split System	Does not Exist
Dry Cooler	Does not Exist
Packaged / Rooftop Unit	Inspected
Instance	Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	Gas
Instance Manufacturer	Trane
Equipment	AC-1
Capacity/Size Quantity	25
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Does not Exist
Refrigerant Piping	Does not Exist
Return Fan	Does not Exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not Exist
Pneumatic System	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Mechanical Inspection

K672

Question	Response
CLIMATE CONTROL SYSTEM	
Hybrid System	Does not Exist
Electric System	Inspected
Instance	Offices and Main Entrance
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not Exist
CONVEYING	Does not Exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not Exist
Pressure Booster System	Does not Exist
Water Service	Inspected
Instance	Gas Meter Room
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN: MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Gas Meter Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not Exist
Domestic Water Heat Exchanger	Does not Exist
Electric Domestic Water Heater	Does not Exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Laars
Equipment	N/A
Capacity/Size Quantity	125
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	60
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K672

Question	Response
DOMESTIC WATER SYSTEM	Inspected
Domestic Hot Water System	Inspected
Oil Fired Domestic Water Heater	Does not Exist
Domestic Water Distribution Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not Exist
Sump Pump	Does not Exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Urinal	Does not Exist
Student	Inspected
Drinking Fountain	Does not Exist
Lavatory/Sink	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Locker Room Shower	Does not Exist
Sink And Fountain Combo Unit	Does not Exist
Toilet	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Urinal	Does not Exist
GAS FIRED FURNACE	Does not Exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not Exist
Gas Meter Room Vent	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Mechanical Inspection

K672

Question	Response
GAS SERVICE	
Gas Pressure Booster	
Instance	Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Ametek
Equipment	N/A
Capacity/Size Quantity	1
Capacity/Size UOM	HP
Source of Capacity/Size	Documented
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
CO/Gas Leak Detection	
Instance	Boiler Room, Gas Meter Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
HEATING	
Heating Coil In Ductwork	
	Does not Exist
Hydronic Heating	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	
Condition	1 - Good
Deficiency	No deficiencies recorded
Backflow Preventer	
	Does not Exist
Hot Water Heat Exchanger	
Condition	1 - Good
Deficiency	No deficiencies recorded
Radiator/Convactor/Fin Tube	
Condition	1 - Good
Deficiency	No deficiencies recorded
Steam Heating	
	Does not Exist
Steam supplied by External Sources	
	Does not Exist
Unit Heater/Cabinet Heater	
Condition	1 - Good
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Boiler Room / EUH-2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
HEATING PLANT	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Mechanical Inspection

K672

Question	Response
HEATING PLANT	
Replacement Quantity	183
Replacement Uom	MBH Net
Instance on 1st Floor	Inspected
Burner Type	Gas
Heating Plant Oil Number	N/A
Boiler Auxiliaries	Inspected
Instance on 1st Floor	Inspected
Boiler Auxiliary Piping	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on 1st Floor	Does not Exist
Boiler Feedwater Treatment(Automatic)	
Instance on 1st Floor	Does not Exist
Boiler Flue Exhaust	
Instance on 1st Floor	Does not Exist
Boiler Make-up Water Backflow Preventer	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on 1st Floor	Does not Exist
Boiler Safety Valve	
Instance on 1st Floor	Does not Exist
Boiler System	
Instance on 1st Floor	Inspected
Coal-fired Boiler	
Instance on 1st Floor	Does not Exist
Hot Water Boiler	
Instance on 1st Floor	Does not Exist
Modular Boiler	
Instance on 1st Floor	Inspected
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	183
Instance Quantity Uom	MBH Net
Instance Manufacturer	Weil-McLain
Equipment	202996-01
Capacity/Size Quantity	183
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2020 - 2021

Mechanical Inspection

K672

Question	Response
HEATING PLANT	
Boiler System	Inspected
Steam Boiler	
Instance on 1st Floor	Does not Exist
Fuel System	Inspected
Instance on 1st Floor	Inspected
Boiler Fresh Air Louver/Damper	
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on 1st Floor	Does not Exist
Fuel Oil Storage/Supply System	
Instance on 1st Floor	Does not Exist
Gas Trains And Vent At The Boiler	
Instance on 1st Floor	Does not Exist
Enclosed IDF Room	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
CO Detector	Not Required
Instance on 1st Floor	Not Required
Gas System	Does not Exist
Instance on 1st Floor	Does not Exist
Grease Trap	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Hood	Does not Exist
Instance on 1st Floor	Does not Exist
Hood Exhaust Ductwork	Does not Exist
Instance on 1st Floor	Does not Exist
Hood Exhaust Fan	Does not Exist
Instance on 1st Floor	Does not Exist
Hood Fire Suppression System	Does not Exist
Instance on 1st Floor	Does not Exist
Hot Water Temperature Booster	Does not Exist
Instance on 1st Floor	Does not Exist
Kitchen Sink	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
MDF Room	Inspected
Instance on Room 124	Inspected
Dedicated A/C Equipment	Inspected
Instance on Room 124	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2020 - 2021**

Mechanical Inspection

K672

Question	Response
SCIENCE PREP ROOM	Does not Exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not Exist
Wet Sprinkler Alarm Valve Assembly	Does not Exist
Fire Booster Pump Assembly	Does not Exist
Roof Tank	Does not Exist
Siamese Connection	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standpipe System	Does not Exist
Water Gong	Does not Exist
SWIMMING POOL	Does not Exist
VENTILATION	Inspected
Exhaust Fan	Inspected
Approximate Total # of Fans	1-25
Condition	1 - Good
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not Exist
Metal Ductwork	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Supply Fan	Does not Exist
Unit Ventilator	Does not Exist