

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K682

**Asset: P.S. @ 736 48TH STREET - BROOKLYN, 736 48TH STREET, New York, 11220**

Inspection Id	Inspection Type	Time In	Last Edited
EE : K682	Electrical	2019-02-28 1:18 PM	2019-05-23 11:02 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: All Electrical Systems and Components
	Years: Under construction

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Under Construction
<b>COMPUTER LAB</b>	Does not Exist
<b>GYMNASIUM</b>	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Under Construction
<b>LIBRARY</b>	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Inspected
Instance on 1st Floor	Under Construction
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Under Construction
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Under Construction
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Under Construction
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Under Construction
<b>EXIT LIGHT</b>	Under Construction

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Electrical Inspection

K682

<b>Question</b>	<b>Response</b>
<b>EXIT/EMERGENCY LIGHT</b>	Under Construction
<b>CITY FIRE ALARM SYSTEM</b>	Does not Exist
<b>FIRE ALARM SYSTEM</b>	Under Construction
<b>GROUNDING SYSTEM</b>	Under Construction
<b>INTERCOM SYSTEM</b>	Does not Exist
<b>LAN</b>	Under Construction
<b>LIGHTNING PROTECTION</b>	Under Construction
<b>MOTOR CONTROL CENTER</b>	Does not Exist
<b>MOTOR STARTER/CONTACTOR</b>	Under Construction
<b>PANEL BOARD</b>	Under Construction
<b>PUBLIC ADDRESS SYSTEM</b>	Under Construction
<b>SECURITY</b>	Under Construction
<b>SERVICE SWITCH</b>	Under Construction
<b>SWITCHBOARD</b>	Under Construction
<b>TELEPHONE SYSTEM</b>	Under Construction
<b>TRANSFORMER</b>	Does not Exist
<b>TV SYSTEM</b>	Does not Exist