

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Mechanical Inspection

K921

Asset: P.S. 179 TRANSPORTABLE - K, 202 AVENUE C, New York, 11218

Inspection Id	Inspection Type	Time In	Last Edited
ME : K921	Mechanical	2017-12-21 9:02 AM	2018-01-12 10:43 AM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	Yes
Systems:	Electric Domestic Water Heater (2 of 3)
Years:	2012

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Packaged Terminal A/C	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
DOMESTIC WATER SYSTEM	Inspected
Domestic Hot Water System	Inspected
Electric Domestic Water Heater	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Domestic Water Distribution Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Sewage/Waste/Vent Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not Exist
FIXTURES	Inspected
Staff And Other	Does not Exist
Student	Inspected
Drinking Fountain	Does not Exist
Lavatory/Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	Does not Exist
Toilet	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Mechanical Inspection

K921

Question	Response
FIXTURES	
Student	
Urinal	Does not Exist
HEATING	
Enclosed IDF Room	Does not Exist
VENTILATION	
Exhaust Fan	Inspected
Approximate Total # of Fans	1-25
Condition	3 - Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	T1 - T6
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Metal Ductwork	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded