

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Mechanical Inspection

K958

Asset: P.S. 202 TRANSPORTABLE - K, 982 HEGEMAN AVENUE, New York, 11208

Inspection Id	Inspection Type	Time In	Last Edited
ME : K958	Mechanical	2019-01-02 8:47 AM	2019-01-02 3:17 PM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Packaged Terminal A/C	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
DOMESTIC WATER SYSTEM	Inspected
Domestic Hot Water System	Inspected
Electric Domestic Water Heater	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Domestic Water Distribution Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Sewage/Waste/Vent Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not Exist
FIXTURES	Inspected
Staff And Other	Does not Exist
Student	Inspected
Drinking Fountain	Does not Exist
Lavatory/Sink	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Toilet Room in T-2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Mechanical Inspection

K958

Question	Response
FIXTURES	
Student	
Lavatory/Sink	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Sink And Fountain Combo Unit	
	Does not Exist
Toilet	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Urinal	
	Does not Exist
HEATING	
	Does not Exist
Enclosed IDF Room	
	Does not Exist
VENTILATION	
Exhaust Fan	
Approximate Total # of Fans	1-25
Condition	3 - Fair
Deficiency	No deficiencies recorded
Metal Ductwork	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded