

**NYC Department of Education**  
**Building Condition Assessment Survey 2017 - 2018**

Mechanical Inspection

M207

**Asset: P.S. 207 (TANDEM M149) - MANHATTAN, 41 WEST 117TH STREET, New York, 10026**

Inspection Id	Inspection Type	Time In	Last Edited
ME : M207	Mechanical	2018-01-18 8:48 AM	2018-01-18 1:44 PM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	--------	------------

No condition recorded

Inspection

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Not Required
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Not Required
<b>CLIMATE CONTROL SYSTEM</b>	Not Required
<b>COMPACTOR</b>	Not Required
<b>CONVEYING</b>	Not Required
<b>DOMESTIC WATER SYSTEM</b>	Not Required
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Not Required
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Not Required
<b>FIXTURES</b>	Not Required
<b>GAS FIRED FURNACE</b>	Not Required
<b>GAS SERVICE</b>	Not Required
<b>HEATING</b>	Not Required
<b>HEATING PLANT</b>	Not Required
<b>Enclosed IDF Room</b>	Not Required
<b>KITCHEN</b>	Not Required
<b>MDF Room</b>	Not Required
<b>SCIENCE DEMO ROOM</b>	Not Required
<b>SCIENCE LAB</b>	Not Required
<b>SCIENCE PREP ROOM</b>	Not Required
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Not Required
<b>SWIMMING POOL</b>	Not Required
<b>VENTILATION</b>	Not Required