

**NYC Department of Education**  
**Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

School: P.S./I.S. 276 - MANHATTAN, 55 BATTERY PLACE, MANHATTAN, NY, 10280

InspectionId	Inspection Type	Time In	Last Edited
809	ELECTRICAL	2018-12-14 07:03AM	2018-12-20 09:36AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Other Electrical Systems and Components Years: 2010 Systems: Fire Alarm Printer Years: 2018
Type of Service	Above Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Electrical Room Used as Storage	N/A	Electrical Equipment	Room 111	Theresa DiCristi	Custodian	No Photo Taken
Yes	Fire Alarm System - Defective	N/A	Fire Alarm System - Main Panel	Main Entrance Lobby	Theresa DiCristi	Custodian	No Photo Taken
No	Local Sound System - Not Connected to Public Address System	N/A	Local Sound System	Auditorium, Gymnasium	Fateh Bouhadja	Fireman	No Photo Taken
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Elevator Recall	Elevator Device IDs: 1P46144, 1P46145, 1P46146	Theresa DiCristi	Custodian	No Photo Taken
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contact	1st Floor Corridor - By Room 105	Theresa DiCristi	Custodian	No Photo Taken
No	Intercom - Not Operational	Intercom not Operational	Intercom System - Elevator	Elevator IDs 1P46144, 1P46145, 1P46146	Theresa DiCristi	Custodian	No Photo Taken

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	
Instance on 1st Floor	Inspected
<b>House Lighting</b>	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Projection System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 5th Floor	Inspected
<b>Lighting</b>	
Instance on 5th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on 5th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 5th Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 5th Floor	Does not exist
<b>Local Sound System</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 5th Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 5th Floor	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>COMPUTER LAB</b>	Does not exist
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Instance	Room 120
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metron Inc
EquipmentId	Fire Pump Automatic Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 906
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	N/A
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 906
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Room 903
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	Battery Charger
Capacity/Size Quantity	12
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	Room 903
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Diesel</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Power Generation
EquipmentId	Emergency Generator
Capacity/Size Quantity	375
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	300
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	1,041
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	Does not exist
<b>Non Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	
<b>FIRE ALARM SYSTEM</b>	
<b>Area Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Bell/Horn</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not exist
<b>Duct Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	5- Poor
Deficiency	SYSTEM NOT OPERATIONAL
Deficiency Location/Instance	Elevator Device IDs: 1P46144, 1P46145, 1P46146
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Fan Shutdown Control</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Inspected
Instance	Room 225A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Ademco
EquipmentId	Fire Alarm Communicator
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Cutout Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor by Room 105
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 3
EquipmentId	Fire Alarm Control Panel, MEA 13-92-E
Capacity/Size Quantity	48
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Diagram
Installation Year	2010
Source of Installation Year	Documented
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12070313H
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Manual Pull Station</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sub-Panel</b>	Does not exist
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
<b>Pendant Mounted</b>	
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not exist
<b>Scoreboard</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Does not exist
<b>INTERCOM SYSTEM</b>	
<b>Elevator</b>	
Condition	5- Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Elevator Device IDs: 1P46144, 1P46145, 1P46146
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Holding Area</b>	
Does not exist	
<b>KITCHEN</b>	
Instance on 5th Floor	Inspected
<b>Lighting</b>	



**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	
<b>Lighting</b>	
Instance on 5th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 5th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 5th Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 5th Floor	Does not exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance on Room 601	Inspected
<b>Lighting</b>	
Instance on Room 601	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 601	Inspected
<b>Pendant Mounted</b>	
Instance on Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 601	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 601	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 601	Does not exist
<b>Projection System</b>	
Instance on Room 601	Does not exist
<b>Raceway With Receptacles</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	
<b>Raceway With Receptacles</b>	
Instance on Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LOCKER ROOM</b>	
Instance on Room 108B - Girls	Inspected
Alternative Use	No
Instance on Room 108C - Boys	Inspected
Alternative Use	No
<b>Lighting</b>	
Instance on Room 108B - Girls	Inspected
Instance on Room 108C - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 108B - Girls	Inspected
Instance on Room 108C - Boys	Inspected
<b>Pendant Mounted</b>	
Instance on Room 108B - Girls	Does not exist
Instance on Room 108C - Boys	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 108B - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 108C - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 108B - Girls	Does not exist
Instance on Room 108C - Boys	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 108B - Girls	Does not exist
Instance on Room 108C - Boys	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 108B - Girls	Does not exist
Instance on Room 108C - Boys	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 108B - Girls	Does not exist
Instance on Room 108C - Boys	Does not exist
<b>MOTOR CONTROL CENTER</b>	
	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	
	Does not exist
<b>PANEL BOARD</b>	
	Inspected
<b>Fused Disconnect Switch Type</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
<b>Fused Knife Switch Type</b>	
	Does not exist
<b>Fused Toggle Switch Type</b>	
	Does not exist
<b>Molded Case Circuit Breaker Type</b>	
	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	
Instance	Room 225A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	
	Does not exist
<b>SCIENCE LAB</b>	
Instance on Room 410	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 807	Inspected
Power Panel?	Yes
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting</b>	
Instance on Room 410	Inspected
Instance on Room 807	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 410	Inspected
Instance on Room 807	Inspected
<b>Pendant Mounted</b>	
Instance on Room 410	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 807	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Does not exist
<b>Surface Mounted</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Does not exist
<b>Power Supply</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Inspected
<b>Instructor Unit</b>	
Instance on Room 807	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 807	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 807	Does not exist
<b>Projection System</b>	
Instance on Room 410	Does not exist
Instance on Room 807	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 412	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 803	Inspected
Power Panel?	No
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting</b>	
Instance on Room 412	Inspected
Instance on Room 803	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 412	Inspected
Instance on Room 803	Inspected
<b>Pendant Mounted</b>	
Instance on Room 412	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 803	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Does not exist
<b>Surface Mounted</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Does not exist
<b>Power Supply</b>	
Instance on Room 412	Does not exist
Instance on Room 803	Inspected
<b>Instructor Unit</b>	
Instance on Room 803	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance	Room 206 - Custodian's Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2010
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Infrared Sensor</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Siren/Strobe</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not exist
<b>IPDVS/CCTV System</b>	Inspected
Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	14
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Room 126
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 126
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	SSWB
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not exist
<b>SWITCHBOARD</b>	Inspected
Number of Spares	15
<b>Air Circuit Breaker Type</b>	Does not exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Room 126
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	MDB
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 904
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	HDBR
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 906
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	EDBR
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 126
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Instance	Room 126
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	HDB
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TRANSFORMER</b>	Inspected
Instance	Room 902
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH



**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M276**

<b>Question</b>	<b>Response</b>
<b>TRANSFORMER</b>	
Manufacturer	Jefferson Electric
EquipmentId	N/A
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 902
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Jefferson Electric
EquipmentId	S1
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 902
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Jefferson Electric
EquipmentId	2
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>TV SYSTEM</b>	Inspected
Cable System Exist?	Yes
Operational?	No
<b>Main Equipment Rack</b>	Does not exist