

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M474

School: PRE-K CENTER @ 252 EAST 57 STREET - MANHATTAN, 252 EAST 57 STREET, MANHATTAN, NY, 10022

InspectionId	Inspection Type	Time In	Last Edited
1044	MECHANICAL	2018-12-28 08:08AM	2019-01-15 06:09PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	MERs 206, 223
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
Dry Cooler	Does not exist
DX Split System	Does not exist
Packaged / Rooftop Unit	Inspected
Instance	MER 206
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	AAON
EquipmentId	AC-2
Capacity/Size Quantity	30
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2018
Source of Installation Year	Documented
Source of Heating	Hydronic
Deficiency	No deficiencies recorded
Instance	MER 223
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	AAON
EquipmentId	AC-1
Capacity/Size Quantity	30
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2018
Source of Installation Year	Documented
Source of Heating	Hydronic
Deficiency	No deficiencies recorded
Instance	First Floor Lobby (Ceiling Mounted)

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M474

Question	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	AC-3
Capacity/Size Quantity	3
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	2018
Source of Installation Year	Documented
Source of Heating	Hydronic
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Does not exist
Refrigerant Piping	Does not exist
Return Fan	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Inspected
Instance	Throughout
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Electric System	Does not exist
Hybrid System	Does not exist
Pneumatic System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Ash Hoist	Does not exist
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	1- Good
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M474

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Does not exist
Sewage Ejector Pump	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
Enclosed IDF Room	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Does not exist
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Does not exist
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Inspected
Backflow Preventer	Does not exist
Hot Water Heat Exchanger	Does not exist
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M474

Question	Response
HEATING	
Radiator/Convactor/Fin Tube	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
HEATING PLANT	Does not exist
KITCHEN	
Instance on Room 208	Inspected
CO Detector	
Instance on Room 208	Not required
Gas System	
Instance on Room 208	Does not exist
Grease Trap	
Instance on Room 208	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood	
Instance on Room 208	Does not exist
Hood Exhaust Ductwork	
Instance on Room 208	Does not exist
Hood Exhaust Fan	
Instance on Room 208	Does not exist
Hood Fire Suppression System	
Instance on Room 208	Does not exist
Hot Water Temperature Booster	
Instance on Room 208	Does not exist
Kitchen Sink	
Instance on Room 208	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
MDF Room	
Instance on Room 201	Inspected
Dedicated A/C Equipment	
Instance on Room 201	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

M474

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Piping	
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Exhaust Fan	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist