

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

School: **J. K. ONASSIS HS FOR INT CAREERS-M, 120 WEST 46 STREET, MANHATTAN, NY, 10036**

InspectionId	Inspection Type	Time In	Last Edited
2334	ELECTRICAL	2019-02-11 08:21AM	2019-04-17 02:48PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: IPDVS/CCTV System Years: 2013 Systems: Auditorium - Local Sound System, Theater Lights, House Lights (except Incandescent) Years: 2009 Systems: Interior Fluorescents Lights, Exit Lights, Emergency Lights, Science Rooms, Projection Systems, LAN System, Telephone System Years: 2009 Systems: Intrusion Alarm System Years: 2005 Systems: Security Lights Years: 2009, 1993 Systems: Fire Alarm System, Emergency Generator, Service Switch, Switchboard, Motor Starters, Panelboards, Public Address System, Local Sound System - Cafeteria and Multipurpose Room, Incandescent Lights Years: 1993
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	No
Which rooms or areas have non-operational dedicated intercoms?	Rooms 508, 408, 308, 208

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Penetration in Electrical Room	Water Penetration in Electrical Room	Electrical Equipment	Electrical Room	Noel DeLaCruz	Fireman	No Photo Taken
No	Intercom - Not Connected to Remote Monitoring Station	Intercom not connected to Remote Monitoring Station	Intercom System - Elevator	Elevator 1P36812	Noel DeLaCruz	Fireman	No Photo Taken
Yes	Electrical Room Used as Storage	Electrical Room Used as Storage	Electrical Equipment	Electrical Room	Noel DeLaCruz	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	1993
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	Does not exist
COMPUTER LAB	
Instance on Room 401	Inspected
Power Panel?	No
Instance on Room 409	Inspected
Power Panel?	Yes
Instance on Room 411	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 401	Inspected
Instance on Room 409	Inspected
Instance on Room 411	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 401	Inspected
Instance on Room 409	Inspected
Instance on Room 411	Inspected
Pendant Mounted	
Instance on Room 401	Does not exist
Instance on Room 409	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 401	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 409	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 401	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 409	Does not exist
Instance on Room 411	Does not exist
Lighting Fixture - HID	
Instance on Room 401	Does not exist
Instance on Room 409	Does not exist
Instance on Room 411	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 401	Does not exist
Instance on Room 409	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 411	Does not exist
Lighting Fixture - LED	
Instance on Room 401	Does not exist
Instance on Room 409	Does not exist
Instance on Room 411	Does not exist
Raceway With Receptacles	
Instance on Room 401	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 409	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 411	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Inspected
Automatic Transfer Switch (ATS)	
	Inspected
Instance	Room B6A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	ATS #3
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room B6A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	Fire Alarm Sys. Automatic Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Mechanical Room Inside B10
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Firetrol
EquipmentId	Fire Pump Automatic Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	1993

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	
Instance	Courtyard - Generator Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	SENS
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	12
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Diesel	
Instance	Courtyard - Generator Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Kohler Power Systems
EquipmentId	Emergency Generator
Capacity/Size Quantity	225
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	180
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	625
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Natural Gas	
Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
Inspected	
Battery Pack	
Does not exist	
Non Battery Pack	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
Inspected	
Battery Pack	
Inspected	
Condition	2- Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Stair C, Main Lobby
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
EXIT LIGHT	
Battery Pack	
Violations	35334342H
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Room B10 - Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Faraday
Model	19000A
EquipmentId	Fire Alarm Control Panel #1, 2, 3
Capacity/Size Quantity	112
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	6
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Does not exist
Printer	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Auditorium Stage
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Faraday
Model	MPC - 2000
EquipmentId	Theater Emergency Panel Auditorium Deluge Control Panel
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not exist
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator ID: 1P36812
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
INTERCOM SYSTEM	
Elevator	
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Does not exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 504	Inspected
Lighting	
Instance on Room 504	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 504	Inspected
Pendant Mounted	
Instance on Room 504	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 504	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 504	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 504	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 504	Does not exist
Lighting Fixture - LED	
Instance on Room 504	Does not exist
Projection System	
Instance on Room 504	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	
Instance on Room 504	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Does not exist	
LOCKER ROOM	
Instance on 2nd Floor - Boys	Inspected
Alternative Use	No
Instance on 2nd Floor - Girls	Inspected
Alternative Use	No
Lighting	
Instance on 2nd Floor - Boys	Inspected
Instance on 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Boys	Inspected
Instance on 2nd Floor - Girls	Inspected
Pendant Mounted	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Recessed Mounted	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Surface Mounted	
Instance on 2nd Floor - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - LED	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - LED	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
MULTIPURPOSE ROOM	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	1993
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Multipurpose Room-2nd Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Fused Knife Switch Type	
	Does not exist
Fused Toggle Switch Type	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	Room 206B
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter IV
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Instance on Room 307	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 309	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 307	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 307	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 307	Inspected
Instance on Room 309	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 307	Inspected
Instance on Room 309	Inspected
Pendant Mounted	
Instance on Room 307	Does not exist
Instance on Room 309	Does not exist
Recessed Mounted	
Instance on Room 307	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 307	Does not exist
Instance on Room 309	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Room 307	Does not exist
Instance on Room 309	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 307	Does not exist
Instance on Room 309	Does not exist
Lighting Fixture - LED	
Instance on Room 307	Does not exist
Instance on Room 309	Does not exist
Power Supply	
Instance on Room 307	Inspected
Instance on Room 309	Inspected
Instructor Unit	
Instance on Room 307	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 307	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 307	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	
Instance on Room 311	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 311	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 311	Inspected
Pendant Mounted	
Instance on Room 311	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 311	Does not exist
Surface Mounted	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 311	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 311	Does not exist
Lighting Fixture - LED	
Instance on Room 311	Does not exist
Power Supply	
Instance on Room 311	Inspected
Instructor Unit	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance on Room 305A	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 305A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 305A	Does not exist
Lighting	
Instance on Room 305A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 305A	Inspected
Pendant Mounted	
Instance on Room 305A	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 305A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 305A	Does not exist
Lighting Fixture - HID	
Instance on Room 305A	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 305A	Does not exist
Lighting Fixture - LED	
Instance on Room 305A	Does not exist
Power Supply	
Instance on Room 305A	Does not exist
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Room B4C
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2005
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	5- Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Principal's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Remote Annunciator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
SECURITY	
Intrusion Alarm System	
Siren/Strobe	
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not exist
IPDVS/CCTV System	
	Inspected
Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	
	Inspected
Condition	4- Between Fair and Poor
Replacement Quantity	21
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Perimeter of Building
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	
	Inspected
Instance	Room B6A - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	Service Switchboard W/ CT
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	
	Does not exist
SWITCHBOARD	
	Inspected
Number of Spares	3
Air Circuit Breaker Type	
	Does not exist
Fused Disconnect Switch Type	
	Inspected
Instance	Room B6A - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M486

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	Inspected
Instance	Room B6A - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	American Switchboard Co.
EquipmentId	Emergency Distribution Panel
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not exist