

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

**School:** MIDTOWN EAST CAMPUS - MANHATTAN, 231-249 EAST 56 STREET, MANHATTAN, NY, 10019

InspectionId	Inspection Type	Time In	Last Edited
99	ELECTRICAL	2018-11-08 09:02AM	2019-06-25 02:39PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Electrical Systems/Components Years: 2012 Systems: Computer Lab - Room 801 (Raceway With Receptacles) Years: 2017
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Defective	N/A		Main Entrance Lobby (High School), Main Entrance Lobby (P.S 59)	Dimitrious Myers	Custodian	No Photo Taken
Yes	Fire Alarm System - Components Not Operational	Magnetic Door Holder/Contactor not Operational	Fire Alarm System - Magnetic Door Holder/Contactor	5th Floor Corridor By Room 510, 513	Dimitrious Myers	Custodian	No Photo Taken

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	
Instance on Sub Basement	Inspected
<b>House Lighting</b>	
Instance on Sub Basement	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Instance on Sub Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Sub Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Sub Basement	Does not exist
<b>Surface Mounted</b>	
Instance on Sub Basement	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Sub Basement	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Sub Basement	Does not exist
<b>Local Sound System</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on Sub Basement	Inspected
<b>Dimming System</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on Room 501	Inspected
Instance on Room 511	Inspected
<b>Lighting</b>	
Instance on Room 501	Inspected
Instance on Room 511	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 501	Inspected
Instance on Room 511	Inspected
<b>Pendant Mounted</b>	
Instance on Room 501	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on Room 511	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 501	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 501	Does not exist
Instance on Room 511	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 501	Inspected
Instance on Room 511	Does not exist
<b>Pendant Mounted</b>	
Instance on Room 501	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 501	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 501	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 501	Does not exist
Instance on Room 511	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 501	Does not exist
Instance on Room 511	Does not exist
<b>Local Sound System</b>	
Instance on Room 501	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 501	Does not exist
Instance on Room 511	Does not exist
<b>Theater Lighting System</b>	
Instance on Room 501	Does not exist
Instance on Room 511	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	
Condition	Inspected
Deficiency	4- Between Fair and Poor
Deficiency Location/Instance	NOT OPERATIONAL
Deficiency Quantity	6th Floor By General Office, Public School Main Entrance Lobby 2

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>CITY FIRE ALARM SYSTEM</b>	
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>COMPUTER LAB</b>	
Instance on Rooms 617, 619, 624	Inspected
Power Panel?	Yes
Instance on Rooms 611, 1007, 1103, 1105, 1107	Inspected
Power Panel?	No
Instance on Room 801	Inspected
Power Panel?	No
<b>Lighting</b>	
Instance on Rooms 617, 619, 624	Inspected
Instance on Rooms 611, 1007, 1103, 1105, 1107	Inspected
Instance on Room 801	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 617, 619, 624	Inspected
Instance on Rooms 611, 1007, 1103, 1105, 1107	Inspected
Instance on Room 801	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 617, 619, 624	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 611, 1007, 1103, 1105, 1107	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 801	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Rooms 617, 619, 624	Does not exist
Instance on Rooms 611, 1007, 1103, 1105, 1107	Does not exist
Instance on Room 801	Does not exist
<b>Surface Mounted</b>	
Instance on Rooms 617, 619, 624	Does not exist
Instance on Rooms 611, 1007, 1103, 1105, 1107	Does not exist
Instance on Room 801	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 617, 619, 624	Does not exist
Instance on Rooms 611, 1007, 1103, 1105, 1107	Does not exist
Instance on Room 801	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 617, 619, 624	Does not exist
Instance on Rooms 611, 1007, 1103, 1105, 1107	Does not exist
Instance on Room 801	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 617, 619, 624	Does not exist
Instance on Rooms 611, 1007, 1103, 1105, 1107	Does not exist
Instance on Room 801	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Rooms 617, 619, 624	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 611, 1007, 1103, 1105, 1107	Does not exist
Instance on Room 801	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room 1201B (Inside Boiler Room)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	ATS-1
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 1201B (Inside Boiler Room)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	ATS-FA
Capacity/Size Quantity	30
Capacity/Size UOM	Amps

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Fire Pump Room 022
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Firetrol
EquipmentId	Fire Pump Power Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Mechanical Room L207
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	ATS-2
Capacity/Size Quantity	150
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Roof - Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Generac
EquipmentId	Battery Charger
Capacity/Size Quantity	12
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	Roof - Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Emergency Generator
Capacity/Size Quantity	1125
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	900
Capacity/Size 2 UOM	kW

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Diesel</b>	
Capacity/Size 3 Quantity	1,353
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
	Does not exist
<b>EMERGENCY LIGHTING</b>	
	Inspected
<b>Battery Pack</b>	Does not exist
<b>Non Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
	Inspected
<b>Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Mechanical Room L207, 4th Floor By Stair D
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Non Battery Pack</b>	Does not exist
<b>EXIT/EMERGENCY LIGHT</b>	
	Does not exist
<b>FIRE ALARM SYSTEM</b>	
	Inspected
<b>Area Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Bell/Horn</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Inspected
Instance	Room 023
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	N/A

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Fire Alarm Digital Communicator</b>	
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Cutout Panel</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	
	Inspected
Condition	4- Between Fair and Poor
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	5th Floor Corridor By Rooms 510, 513
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Main Panel</b>	
	Inspected
<b>Bell At Panel</b>	
	Does not exist
<b>Fire Alarm Control Panel (Electronic)</b>	
	Inspected
Instance	Main Entrance Lobby (High School)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	
EquipmentId	Fire Command Station
Capacity/Size Quantity	64
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12072348R
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Entrance Lobby (P.S 59)



**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	
EquipmentId	Fire Command Station Public School
Capacity/Size Quantity	64
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Manual Pull Station</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Does not exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	FireFinder
EquipmentId	Fire Alarm Smoke Control Panel (High School)
Capacity/Size Quantity	80
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Main Entrance Lobby (P.S 59)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
Model	FireFinder
EquipmentId	Fire Alarm Smoke Control Panel (Public School)
Capacity/Size Quantity	80
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room L210B by Auditorium Stage
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
Model	
EquipmentId	Deluge Control Panel
Capacity/Size Quantity	2
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation Year	Inspector Estimate
Deficiency	PANEL DIRECTION/DIAGRAM IS MISSING
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Violations	No violations recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 5th Floor	Inspected
Instance on Sub Basement	Inspected
<b>Lighting</b>	
Instance on 5th Floor	Inspected
Instance on Sub Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 5th Floor	Inspected
Instance on Sub Basement	Inspected
<b>Pendant Mounted</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Sub Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 5th Floor	Does not exist
Instance on Sub Basement	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 5th Floor	Does not exist
Instance on Sub Basement	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 5th Floor	Does not exist
Instance on Sub Basement	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 5th Floor	Does not exist
Instance on Sub Basement	Does not exist
<b>Local Sound System</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on Sub Basement	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Local Sound System</b>	
Instance Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 5th Floor	Does not exist
Instance on Sub Basement	Does not exist
<b>Scoreboard</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Sub Basement	Does not exist
<b>Theater Lighting System</b>	
Instance on 5th Floor	Does not exist
Instance on Sub Basement	Does not exist
<b>INTERCOM SYSTEM</b>	
<b>Elevator</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	
Does not exist	
<b>KITCHEN</b>	
Instance on 5th Floor	Inspected
<b>Lighting</b>	
Instance on 5th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 5th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 5th Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 5th Floor	Does not exist
<b>LAN</b>	
<b>Local Distribution Frame (I/LDF)</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance on Room 601	Inspected
Instance on Room 112	Inspected
<b>Lighting</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>LIBRARY</b>	
<b>Lighting</b>	
Instance on Room 601	Inspected
Instance on Room 112	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 601	Inspected
Instance on Room 112	Inspected
<b>Pendant Mounted</b>	
Instance on Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 112	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 112	Does not exist
<b>Surface Mounted</b>	
Instance on Room 601	Does not exist
Instance on Room 112	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 601	Does not exist
Instance on Room 112	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 601	Does not exist
Instance on Room 112	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 601	Does not exist
Instance on Room 112	Does not exist
<b>Projection System</b>	
Instance on Room 601	Does not exist
Instance on Room 112	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 601	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 112	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LOCKER ROOM</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Inspected
Alternative Use	No
<b>Lighting</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 424 - Girls, 422 - Boys, 503 - Visitors	Does not exist
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not exist
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Instance	Room 220
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland MPA 250
Installation Year	2012
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Rooms 705, 720, 901, 1022
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
Power Panel?	Yes
Alternative Use	No
Instance on Room 204	Inspected
Power Panel?	Yes
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 204	Does not exist
<b>Emergency Shut-Off Power</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 204	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance on Room 204	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance on Room 204	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 204	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist
Instance on Room 204	Does not exist
<b>Surface Mounted</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist
Instance on Room 204	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance on Room 204	Does not exist
<b>Pendant Mounted</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist
<b>Recessed Mounted</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist
<b>Surface Mounted</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist
Instance on Room 204	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
Instance on Room 204	Does not exist
<b>Power Supply</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance on Room 204	Does not exist
<b>Instructor Unit</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist
<b>Projection System</b>	
Instance on Rooms 1102, 1111, 1117, 1002, 1009, 1017	Does not exist
Instance on Room 204	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Rooms 1011, 1113	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 206	Inspected
Power Panel?	No
Alternative Use	No
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Rooms 1011, 1113	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 206	Does not exist
<b>Emergency Shut-Off Power</b>	
Instance on Rooms 1011, 1113	Does not exist
Instance on Room 206	Does not exist
<b>Lighting</b>	
Instance on Rooms 1011, 1113	Inspected
Instance on Room 206	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 1011, 1113	Inspected
Instance on Room 206	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 1011, 1113	Does not exist
Instance on Room 206	Does not exist
<b>Recessed Mounted</b>	
Instance on Rooms 1011, 1113	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Rooms 1011, 1113	Does not exist



**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Room 206	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Rooms 1011, 1113	Does not exist
Instance on Room 206	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 1011, 1113	Does not exist
Instance on Room 206	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 1011, 1113	Does not exist
Instance on Room 206	Does not exist
<b>Power Supply</b>	
Instance on Rooms 1011, 1113	Does not exist
Instance on Room 206	Does not exist
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance	Custodian's Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 250BP
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	2- Between Good and Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	1st Floor External
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Ultrasonic Sensor</b>	
Does not exist	
<b>IPDVS/CCTV System</b>	
Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	
Inspected	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	
<b>Lighting - Security</b>	
Condition	2- Between Good and Fair
Replacement Quantity	49
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Outside By Main Entrance
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Atlas
EquipmentId	Main Service Switch
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 025
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Atlas
EquipmentId	Fire Pump Main Disconnect Normal Power
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	
	Does not exist
<b>SWITCHBOARD</b>	
	Inspected
Number of Spares	0
<b>Air Circuit Breaker Type</b>	
	Does not exist
<b>Fused Disconnect Switch Type</b>	
	Inspected
Instance	Electrical Room 025
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Atlas Switch
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2012
Source of Installation Year	Documented

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Deficiency	No deficiencies recorded
Instance	Electrical Room 1201B (Inside Boiler Room)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Atlas Switch
EquipmentId	EDP11 (Emergency Generator Switchboard)
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TRANSFORMER</b>	Inspected
Instance	Electrical Room 1016
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>TRANSFORMER</b>	
EquipmentId	Transformer # T9
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 1116
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer # T10
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 116
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer # TC
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 316
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer # T2
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 416
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer # T3
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>TRANSFORMER</b>	
Instance	Electrical Room 516
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	Transformer # T4K
Capacity/Size Quantity	150
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 516
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	Transformer # T4A
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 616
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer #T5
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 716
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer # T6
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 816
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer # T7
Capacity/Size Quantity	45

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**M488**

Question	Response
<b>TRANSFORMER</b>	
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 916
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer # T8
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room L216
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	Transformer #TSC
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Elevator Machine Room 818
Instance Condition	2- Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Jefferson Electric
EquipmentId	ID#1P46671, ID#1P46672
Capacity/Size Quantity	55
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Elevator Machine Room PE-1-2-3
Instance Condition	2- Between Good and Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Manufacturer	Jefferson Electric
EquipmentId	ID#1P46678, ID#1P46679, ID#1P46680
Capacity/Size Quantity	70
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 025
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Electrical Inspection***

**M488**

Question	Response
<b>TRANSFORMER</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	Transformer # TCA
Capacity/Size Quantity	150
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>TV SYSTEM</b>	
	Inspected
Cable System Exist?	Yes
Operational?	No
<b>Main Equipment Rack</b>	Does not exist