

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

School: **HARLEM PROMISE ACADEMY CHARTER - MANHATTAN, 245 WEST 129 STREET, MANHATTAN, NY, 10027**

InspectionId	Inspection Type	Time In	Last Edited
2546	ELECTRICAL	2019-02-19 09:46AM	2019-02-19 08:47PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Telephone System Years: 2017 Systems: Health Center (Recessed LED Lighting in CCA, Some Molded Case Circuit Breaker Type Panel Boards) Years: 2016 Systems: All Other Electrical Systems and Components Years: 2013
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Electrical Room Used as Storage	N/A	Electrical Equipment	Electrical Closets 210A, 310A, 410A, 510A; Electrical Rooms C10, 106, 207, 307, 407, 507	Stephen Nisbett	Director of Facilities	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	Inspected
Deficiency	5- Poor
Deficiency Location/Instance	NOT OPERATIONAL
Deficiency Quantity	Main Entrance Lobby
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPAIR
Purpose of Action	PRIORITY 5
Violations	LEVEL 2
	No violations recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	Inspected
	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
COMPUTER LAB	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Room C23 - ATS Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Emerson Network Power
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C23 - ATS Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Emerson Network Power
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C20 - Fire Pump Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metron Inc
EquipmentId	Fire Pump Automatic Transfer Switch
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Room C18 - Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	Battery Charger
Capacity/Size Quantity	12

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
EMERGENCY GENERATOR SET	
Battery Charger	
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Diesel	
	Inspected
Instance	Room C18 - Generator Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Power Generation
EquipmentId	Emergency Generator
Capacity/Size Quantity	375
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	300
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	1,040
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
	Does not exist
EMERGENCY LIGHTING	
	Inspected
Battery Pack	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	
	Does not exist
EXIT/EMERGENCY LIGHT	
	Does not exist
FIRE ALARM SYSTEM	
	Inspected
Area Smoke Detector	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
FIRE ALARM SYSTEM	
Elevator Recall	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	
Does not exist	
Fused Cutout Panel	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	
Does not exist	
Main Panel	
Inspected	
Bell At Panel	
Does not exist	
Fire Alarm Control Panel (Electronic)	
Inspected	
Instance	Main Entrance
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 3
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	
Does not exist	
Manual Pull Station	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Inspected	
Display Monitor	
Does not exist	
Panel	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	
Does not exist	
Sprinkler Flow/Air Pressure Switch	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	
Inspected	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	
Inspected	
Bell At Panel	
Does not exist	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 3
EquipmentId	Fire Alarm DGP
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
GYMNASIUM	
Local Sound System	
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Scoreboard	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	
Condition	1- Good
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
LAN	
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	Does not exist
LIGHTNING PROTECTION	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LOCKER ROOM	
Instance on Cellar - Boys	Inspected
Alternative Use	No
Instance on Cellar - Girls	Inspected
Alternative Use	No
Lighting	
Instance on Cellar - Boys	Inspected
Instance on Cellar - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Cellar - Boys	Inspected
Instance on Cellar - Girls	Inspected
Pendant Mounted	
Instance on Cellar - Boys	Does not exist
Instance on Cellar - Girls	Does not exist
Recessed Mounted	
Instance on Cellar - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Cellar - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Cellar - Boys	Does not exist
Instance on Cellar - Girls	Does not exist
Lighting Fixture - HID	
Instance on Cellar - Boys	Does not exist
Instance on Cellar - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on Cellar - Boys	Does not exist
Instance on Cellar - Girls	Does not exist
Lighting Fixture - LED	
Instance on Cellar - Boys	Does not exist
Instance on Cellar - Girls	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	
Instance on Room 101	Inspected
Lighting	
Instance on Room 101	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 101	Inspected
Pendant Mounted	
Instance on Room 101	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 101	Does not exist
Surface Mounted	
Instance on Room 101	Does not exist
Lighting Fixture - HID	
Instance on Room 101	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 101	Does not exist
Lighting Fixture - LED	
Instance on Room 101	Does not exist
Local Sound System	
Instance on Room 101	Does not exist
Projection System	
Instance on Room 101	Does not exist
Theater Lighting System	
Instance on Room 101	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Does not exist
Fused Toggle Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Kitchen Storage Room, Electrical Room, Rooms 106 and 408
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Kitchen Storage Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	Room C10 - MDF Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2013
Source of Installation Year	Documented

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
Instance on Rooms 408, 410	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 412	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms 408, 410	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 412	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 408, 410	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 412	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Rooms 408, 410	Inspected
Instance on Room 412	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 408, 410	Inspected
Instance on Room 412	Inspected
Pendant Mounted	
Instance on Rooms 408, 410	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 412	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 408, 410	Does not exist
Instance on Room 412	Does not exist
Surface Mounted	
Instance on Rooms 408, 410	Does not exist
Instance on Room 412	Does not exist
Lighting Fixture - HID	
Instance on Rooms 408, 410	Does not exist
Instance on Room 412	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 408, 410	Does not exist
Instance on Room 412	Does not exist
Lighting Fixture - LED	
Instance on Rooms 408, 410	Does not exist
Instance on Room 412	Does not exist
Power Supply	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
SCIENCE LAB	
Power Supply	
Instance on Rooms 408, 410	Inspected
Instance on Room 412	Does not exist
Instructor Unit	
Instance on Rooms 408, 410	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 408, 410	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms 408, 410	Does not exist
Projection System	
Instance on Rooms 408, 410	Does not exist
Instance on Room 412	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Room C11 - Facilities Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
IPDVS/CCTV System	
Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	
Condition	2- Between Good and Fair
Replacement Quantity	95
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
SERVICE SWITCH	
Instance	Room C22 - Main Electrical Service Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDB
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C22 - Main Electrical Service Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	HDB
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C22 - Main Electrical Service Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Fire Pump Disconnect
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	12
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Room C22 - Main Electrical Service Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDB Section 1, 2, 3
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance	Room C23 - ATS Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	EDB
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room R01 - Penthouse Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	HDB
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

M908

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Does not exist