

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**M913**

School: **ALTERNATIVE LEARNING CENTER - MANHATTAN, 50 BROADWAY, MANHATTAN, NY, 10004**

InspectionId	Inspection Type	Time In	Last Edited
2964	MECHANICAL	2019-03-11 11:44AM	2019-05-10 12:15PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	12th Floor - East and West MER's
Are there any Emergency Stop Switches with Missing Hammers?	No components

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

**Inspection**

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not exist
<b>Cooling Coil in Ductwork</b>	Does not exist
<b>Cooling Tower</b>	Does not exist
<b>Dry Cooler</b>	Does not exist
<b>DX Split System</b>	Does not exist
<b>Packaged / Rooftop Unit</b>	Inspected
Instance	12th Floor - East MER
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	United CoolAir
EquipmentId	N/A
Capacity/Size Quantity	12
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	2012
Source of Installation Year	Documented
Source of Heating	N/A
Deficiency	No deficiencies recorded
Instance	12th Floor - West MER
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	United CoolAir
EquipmentId	N/A
Capacity/Size Quantity	12
Capacity/Size UOM	Tons
Source of Capacity/Size	Custodial Staff
Installation Year	2012
Source of Installation Year	Documented
Source of Heating	N/A
Deficiency	No deficiencies recorded
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Piping</b>	Does not exist
<b>Return Fan</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**M913**

<b>Question</b>	<b>Response</b>
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>BMS</b>	Inspected
Instance	Throughout
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Electric System</b>	Does not exist
<b>Hybrid System</b>	Does not exist
<b>Pneumatic System</b>	Does not exist
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Does not exist
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Fired Domestic Water Heater</b>	Does not exist
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Does not exist
<b>Sewage Ejector Pump</b>	Does not exist
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Sump Pump</b>	Does not exist
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not exist
<b>Enclosed IDF Room</b>	
Instance on 12th Floor - Room next to West MER	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on 12th Floor - Room next to West MER	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	12th Floor - Room next to West MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	1- Good

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**M913**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>Staff And Other</b>	
<b>Janitor Sink</b>	
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	1- Good
<b>Toilet</b>	
Condition	No deficiencies recorded
Deficiency	Inspected
<b>Urinal</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Student</b>	
<b>Drinking Fountain</b>	
Condition	Inspected
Deficiency	1- Good
<b>Lavatory/Sink</b>	
Condition	No deficiencies recorded
Deficiency	Inspected
<b>Locker Room Shower</b>	
<b>Sink And Fountain Combo Unit</b>	
<b>Toilet</b>	
Condition	Does not exist
Deficiency	Does not exist
<b>Urinal</b>	
Condition	Inspected
Deficiency	1- Good
<b>GAS FIRED FURNACE</b>	
<b>GAS SERVICE</b>	
<b>HEATING</b>	
<b>Heating Coil In Ductwork</b>	
<b>Hydronic Heating</b>	
<b>Radiator/Convactor/Fin Tube</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Steam Heating</b>	
<b>F&amp;T/Steam Drip Trap</b>	
<b>MER Steam and Condensate Piping</b>	
<b>Steam Condensate Return Piping</b>	
Condition	Does not exist
Deficiency	Does not exist
<b>Steam Condensate Return Pumping System</b>	
<b>Steam Piping</b>	
Condition	Inspected
Deficiency	3- Fair
<b>Terminal Unit Thermostatic Trap</b>	
Condition	No deficiencies recorded
Deficiency	Inspected
<b>Steam supplied by External Sources</b>	
<b>Unit Heater/Cabinet Heater</b>	
Condition	Does not exist
Deficiency	Inspected
Condition	1- Good

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**M913**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Unit Heater/Cabinet Heater</b>	
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	Does not exist
<b>KITCHEN</b>	Does not exist
<b>MDF Room</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	Does not exist
<b>Fire Booster Pump Assembly</b>	Does not exist
<b>Roof Tank</b>	Does not exist
<b>Siamese Connection</b>	Does not exist
<b>Sprinkler Head</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Inspected
<b>Hose Valve Assembly</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Water Gong</b>	Does not exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Inspected
<b>Exhaust Fan</b>	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Does not exist
<b>Metal Ductwork</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Does not exist
<b>Unit Ventilator</b>	Does not exist