

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

**Asset:** MASPETH HIGH SCHOOL - QUEENS, 54-40 74TH STREET, New York, 11373

Inspection Id	Inspection Type	Time In	Last Edited
ME : Q585	Mechanical	2018-11-01 8:01 AM	2018-11-27 8:19 AM

Asset Data

Question	Answer
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	275
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Science Labs 329, 332, 429, 432
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Sewage Ejector Pumps
	Years: 2017

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not Exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not Exist
<b>Cooling Coil in Ductwork</b>	Does not Exist
<b>Cooling Tower</b>	Does not Exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Outdoor Unit</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Dry Cooler</b>	Does not Exist
<b>Packaged / Rooftop Unit</b>	Inspected
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	Gas
Instance Manufacturer	Seasons4
Equipment	RTU-1
Capacity/Size Quantity	132
Capacity/Size UOM	Tons

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>AIR CONDITIONING</b>	
<b>Packaged / Rooftop Unit</b>	
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	Gas
Instance Manufacturer	Seasons4
Equipment	RTU-2
Capacity/Size Quantity	52
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	Gas
Instance Manufacturer	Seasons4
Equipment	RTU-3
Capacity/Size Quantity	49
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	Gas
Instance Manufacturer	Seasons4
Equipment	RTU-4
Capacity/Size Quantity	75
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>AIR CONDITIONING</b>	
<b>Packaged / Rooftop Unit</b>	
Source of Heating	Electric
Instance Manufacturer	Seasons4
Equipment	RTU-5
Capacity/Size Quantity	92
Capacity/Size UOM	Tons
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Source of Heating	Gas
Instance Manufacturer	Seasons4
Equipment	RTU-6, RTU-8
Capacity/Size Quantity	36
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Main Roof
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Source of Heating	Gas
Instance Manufacturer	Seasons4
Equipment	RTU-7
Capacity/Size Quantity	83
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2012
Source of Installation	Documented
Deficiency	OVER 20 TONS: DEFECTIVE MOTOR
Deficiency Location/Instance	Main Roof/RTU-7
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Packaged Terminal A/C</b>	Does not Exist
<b>Refrigerant Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	Inspected
<b>Return Fan</b>	Does not Exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	LEAKS
Deficiency Location/Instance	Room 124KA
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>BMS</b>	Inspected
Instance	Throughout
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Installation Year	2012
Source of Installation	Documented
Deficiency	DEFECTIVE SYSTEM
Deficiency Location/Instance	Throughout
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Pneumatic System</b>	Does not Exist
<b>Hybrid System</b>	Does not Exist
<b>Electric System</b>	Does not Exist
<b>COMPACTOR</b>	Does not Exist
<b>CONVEYING</b>	Inspected
<b>Dumbwaiter</b>	Does not Exist
<b>Elevator</b>	Inspected
Are all the existing elevators operable?	Yes
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Escalator</b>	Does not Exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Does not Exist
<b>Non-auditorium Handicap Lift - Stair</b>	Does not Exist
<b>Ash Hoist</b>	Does not Exist
<b>Sidewalk Elevator</b>	Does not Exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Cold Water System</b>	
<b>Gravity System</b>	Does not Exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Inspected
Instance	Room B16C
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SyncroFlo
Equipment	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size2 Quantity	20
Capacity/Size2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Hydraulic/Pneumatic Booster System</b>	Does not Exist
<b>Water Service</b>	Inspected
Instance	Room B16C
Instance Condition	1 - Good
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Domestic Water Heat Exchanger</b>	Does not Exist
<b>Electric Domestic Water Heater</b>	Does not Exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Instance Manufacturer	Laars
Equipment	N/A
Capacity/Size Quantity	250
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	0
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not Exist
<b>Domestic Water Distribution Piping</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sump Pump</b>	Does not Exist
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not Exist
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Does not Exist
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Corridor near Room 419
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lavatory/Sink</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Inspected
Instance on Room B19A - Boys	Inspected
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Alternative use	No

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>FIXTURES</b>	
<b>Student</b>	
<b>Locker Room Shower</b>	
Deficiency	No deficiencies recorded
Instance on Room B21A- Girls	Inspected
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Alternative use	No
Deficiency	No deficiencies recorded
Instance on Room B26B - Visitors	Inspected
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Alternative use	No
Deficiency	No deficiencies recorded
<b>Sink And Fountain Combo Unit</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>GAS FIRED FURNACE</b>	Does not Exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Does not Exist
<b>Gas Meter Room Vent</b>	Does not Exist
<b>Gas Pressure Booster</b>	Does not Exist
<b>CO/Gas Leak Detection</b>	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>HEATING</b>	Inspected
<b>Heating Coil In Ductwork</b>	Does not Exist
<b>Hydronic Heating</b>	Inspected
<b>Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Backflow Preventer</b>	Does not Exist
<b>Hot Water Heat Exchanger</b>	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>HEATING</b>	
<b>Radiator/Convactor/Fin Tube</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Does not Exist
<b>Steam supplied by External Sources</b>	Does not Exist
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	
Replacement Quantity	2,543
Replacement Uom	MBH Net
Instance on Penthouse	Inspected
Burner Type	Gas
Heating Plant Oil Number	N/A
<b>Boiler Auxiliaries</b>	Inspected
Instance on Penthouse	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on Penthouse	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Penthouse	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Flue Exhaust</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Penthouse	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Penthouse	Does not Exist
<b>Boiler Safety Valve</b>	
Instance on Penthouse	Does not Exist
<b>Boiler System</b>	Inspected
Instance on Penthouse	Inspected
<b>Coal-fired Boiler</b>	
Instance on Penthouse	Does not Exist
<b>Hot Water Boiler</b>	
Instance on Penthouse	Does not Exist
<b>Modular Boiler</b>	
Instance on Penthouse	Inspected
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,500



**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler System</b>	
<b>Modular Boiler</b>	
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	44384-01
Capacity/Size Quantity	1,500
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1 - Good
Instance Quantity	1,043
Instance Quantity Uom	MBH Net
Instance Manufacturer	AERCO
Equipment	44384-02
Capacity/Size Quantity	1,500
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Steam Boiler</b>	
Instance on Penthouse	Does not Exist
<b>Fuel System</b>	Inspected
Instance on Penthouse	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Penthouse	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on Penthouse	Does not Exist
<b>Fuel Oil Storage/Supply System</b>	
Instance on Penthouse	Does not Exist
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Penthouse	Does not Exist
<b>Enclosed IDF Room</b>	Inspected
Instance on Rooms 311, 411	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Rooms 311, 411	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>CO Detector</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>KITCHEN</b>	
<b>CO Detector</b>	Inspected
Deficiency	No deficiencies recorded
<b>Gas System</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hot Water Temperature Booster</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Kitchen Sink</b>	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>MDF Room</b>	Inspected
Instance on Telecom Room 224	Inspected
<b>Dedicated A/C Equipment</b>	Inspected
Instance on Telecom Room 224	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Rooms 328, 428	Inspected
Alternative use	No
Instance on Rooms 329, 332, 429, 432	Inspected
Alternative use	No
<b>Acid Waste Neutralizing Tank</b>	Does not Exist
Instance on Rooms 329, 332, 429, 432	Does not Exist
Instance on Rooms 328, 428	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>SCIENCE LAB</b>	
<b>CO Detector</b>	Inspected
Instance on Rooms 329, 332, 429, 432	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Rooms 329, 332, 429, 432
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 328, 428	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shower</b>	Does not Exist
Instance on Rooms 329, 332, 429, 432	Does not Exist
Instance on Rooms 328, 428	Does not Exist
<b>Eye Wash</b>	Inspected
Instance on Rooms 329, 332, 429, 432	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 328, 428	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Does not Exist
Instance on Rooms 329, 332, 429, 432	Does not Exist
Instance on Rooms 328, 428	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Does not Exist
Instance on Rooms 329, 332, 429, 432	Does not Exist
Instance on Rooms 328, 428	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Laboratory Hood</b>	Does not Exist
Instance on Rooms 329, 332, 429, 432	Does not Exist
Instance on Rooms 328, 428	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Laboratory Sink</b>	Inspected
Instance on Rooms 329, 332, 429, 432	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms 328, 428	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	Does not Exist
Instance on Rooms 329, 332, 429, 432	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	Inspected
<b>Make-up Air Unit</b>	
Instance on Rooms 328, 428	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Rooms 330, 430	Inspected
Alternative use	No
<b>Acid Waste Neutralizing Tank</b>	Does not Exist
Instance on Rooms 330, 430	Does not Exist
<b>CO Detector</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shower</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Eye Wash</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Laboratory Hood</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Laboratory Sink</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Make-up Air Unit</b>	Inspected
Instance on Rooms 330, 430	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	Does not Exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	Does not Exist
<b>Fire Booster Pump Assembly</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Roof Tank</b>	Does not Exist
<b>Siamese Connection</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018 - 2019**

Mechanical Inspection

Q585

Question	Response
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
<b>Sprinkler Head</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Does not Exist
<b>Water Gong</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>VENTILATION</b>	Inspected
<b>Exhaust Fan</b>	Inspected
Approximate Total # of Fans	1-25
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Does not Exist
<b>Metal Ductwork</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Does not Exist
<b>Unit Ventilator</b>	Does not Exist