

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Mechanical Inspection

Q728

Asset: P.S. 41 TRANSPORTABLE - Q, 214-43 35 AVENUE, New York, 11361

Inspection Id	Inspection Type	Time In	Last Edited
ME : Q728	Mechanical	2019-01-02 8:18 AM	2019-01-02 3:14 PM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Packaged Terminal A/C	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
DOMESTIC WATER SYSTEM	Inspected
Domestic Hot Water System	Inspected
Electric Domestic Water Heater	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Room T1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Domestic Water Distribution Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Sewage/Waste/Vent Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not Exist
FIXTURES	Inspected
Staff And Other	Does not Exist
Student	Inspected
Drinking Fountain	Does not Exist
Lavatory/Sink	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018 - 2019

Mechanical Inspection

Q728

Question	Response
FIXTURES	
Student	
Lavatory/Sink	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	
	Does not Exist
Toilet	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	
	Does not Exist
HEATING	
	Does not Exist
Enclosed IDF Room	
	Does not Exist
VENTILATION	
	Inspected
Exhaust Fan	
	Inspected
Approximate Total # of Fans	1-25
Condition	3 - Fair
Deficiency	No deficiencies recorded
Metal Ductwork	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded