

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

**School:** THE KATHLEEN GRIMM SCHOOL FOR LEADERSHIP AND SUSTAINABILITY AT SANDY GROUND - STATEN ISLAND, 644 BLOOMINGDALE ROAD, STATEN ISLAND, NY, 10309

InspectionId	Inspection Type	Time In	Last Edited
2589	ELECTRICAL	2021-02-05 08:16AM	2021-02-19 02:12PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Other Electrical Systems and Components Years: 2015 Systems: Public Address System Years: 2020
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Does not exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>CAFETERIA</b>	
<b>Local Sound System</b>	
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 1st Floor	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	
Condition	Inspected
Deficiency	1- Good No deficiencies recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	Does not exist
<b>Surface Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Condition	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Condition	Does not exist
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair No deficiencies recorded
<b>Surface Mounted</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair No deficiencies recorded
<b>COMPUTER LAB</b>	
Condition	Does not exist
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	
Condition	Does not exist
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Instance	Inspected
Instance Condition	ATS Room 168
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	ASCO
Capacity/Size Quantity	ATS - 1
Capacity/Size UOM	1200
Source of Capacity/Size	Amps
Installation Year	Nameplate
Source of Installation Year	2015
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	ATS Room 168
Instance Quantity	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS - 2
Capacity/Size Quantity	260
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	ATS Room 168
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Fire Alarm ATS Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Fire Pump Room 170B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metron Inc
EquipmentId	Fire Pump ATS Switch
Capacity/Size Quantity	225
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Roof Emergency Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	N/A
EquipmentId	Battery Charger
Capacity/Size Quantity	12
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	Roof Emergency Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Power Generation

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Diesel</b>	
EquipmentId	Emergency Generator
Capacity/Size Quantity	312
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	250
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	867
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
	Does not exist
<b>EMERGENCY LIGHTING</b>	
	Inspected
<b>Battery Pack</b>	
	Does not exist
<b>Non Battery Pack</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
	Inspected
<b>Battery Pack</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	
	Does not exist
<b>EXIT/EMERGENCY LIGHT</b>	
	Does not exist
<b>FIRE ALARM SYSTEM</b>	
	Inspected
<b>Area Smoke Detector</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Bell/Horn</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	
	Does not exist
<b>Fused Cutout Panel</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	
	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Magnetic Door Holder/Contactor</b>	
Deficiency	No deficiencies recorded
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Security Desk
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	FX - 2000
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	16
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Diagram
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Manual Pull Station</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sub-Panel</b>	Does not exist
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	
Instance on 1st Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	
<b>Elevator</b>	
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>INTERCOM SYSTEM</b>	
<b>Holding Area</b>	Does not exist
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance on Room 161	Inspected
<b>Lighting</b>	
Instance on Room 161	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 161	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 161	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 161	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 161	Inspected
<b>Pendant Mounted</b>	
Instance on Room 161	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 161	Does not exist
<b>Surface Mounted</b>	
Instance on Room 161	Does not exist
<b>Projection System</b>	
Instance on Room 161	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 161	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>LIBRARY</b>	
<b>Raceway With Receptacles</b>	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>LOCKER ROOM</b>	Does not exist
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not exist
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Instance	MDF Room 270
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	NQ-E7030
Installation Year	2020
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	
Instance on Room 205	Inspected
Power Panel?	No
Alternative Use	Yes
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 205	Does not exist
<b>Emergency Shut-Off Power</b>	
Instance on Room 205	Does not exist
<b>Lighting</b>	
Instance on Room 205	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 205	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 205	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 205	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 205	Inspected
<b>Pendant Mounted</b>	
Instance on Room 205	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	



**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Instance on Room 205	Does not exist
<b>Surface Mounted</b>	
Instance on Room 205	Does not exist
<b>Power Supply</b>	
Instance on Room 205	Does not exist
<b>Projection System</b>	
Instance on Room 205	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 207	Inspected
Power Panel?	No
Alternative Use	Yes
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 207	Does not exist
<b>Emergency Shut-Off Power</b>	
Instance on Room 207	Does not exist
<b>Lighting</b>	
Instance on Room 207	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 207	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 207	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 207	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 207	Inspected
<b>Pendant Mounted</b>	
Instance on Room 207	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 207	Does not exist
<b>Surface Mounted</b>	
Instance on Room 207	Does not exist
<b>Power Supply</b>	
Instance on Room 207	Does not exist
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Instance	Custodian's Office - Room 133
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Panic Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not exist
<b>IPDVS/CCTV System</b>	
Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	
Condition	2- Between Good and Fair
Replacement Quantity	44
Replacement Uom	EACH
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
Instance	Electrical Room 170A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Fire Pump Service Switch
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 170A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	EDP - Gen (Emergency)
Capacity/Size Quantity	5000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 170A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	MDB
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>SERVICE SWITCH</b>	
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 170A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	MPP - G
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not exist
<b>SWITCHBOARD</b>	Inspected
Number of Spares	10
<b>Air Circuit Breaker Type</b>	Does not exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	ATS Room 168
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	EDP - Gen
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Instance	Roof Emergency Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	East Coast
EquipmentId	N/A (Emergency Generator Switchboard)
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 170A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Electrical Inspection**

**R062**

Question	Response
<b>SWITCHBOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Manufacturer	Square D
EquipmentId	MDB
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room 113
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	MPP - G
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2020-2021

*Electrical Inspection*

**R062**

---

Question	Response
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist

---