

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

R068

School: PRE-K CENTER @ 1 TELEPORT DRIVE - STATEN ISLAND, 1 TELEPORT DRIVE, STATEN ISLAND, NY, 10311

InspectionId	Inspection Type	Time In	Last Edited
3869	MECHANICAL	2019-04-17 11:20AM	2019-04-26 01:23PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	A/C MER 2, Fan Room 111
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Inspected
Absorption Chiller	Does not exist
Air Cooled Chiller	Does not exist
Air Cooled Condenser	Does not exist
Backflow Preventer	Does not exist
Central Station Air Handler	Inspected
Instance	A/C MER 2
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mammoth
EquipmentId	AHU-1
Capacity/Size Quantity	30
Capacity/Size UOM	Fan Motor HP
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation Year	Documented
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	A/C MER 2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Chilled Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Coil Unit	Does not exist
Packaged Air Cooled Chiller	Does not exist
Water Cooled Chiller	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
Dry Cooler	Does not exist
DX Split System	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

R068

Question	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Piping	Does not exist
Return Fan	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	
	Does not exist
CLIMATE CONTROL SYSTEM	
	Inspected
BMS	
Instance	Throughout
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Electric System	Does not exist
Hybrid System	Does not exist
Pneumatic System	Does not exist
COMPACTOR	
	Does not exist
CONVEYING	
	Does not exist
DOMESTIC WATER SYSTEM	
	Inspected
Domestic Cold Water System	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
	Inspected
Interior Storm Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sewage/Waste/Vent Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
	Does not exist
Enclosed IDF Room	Does not exist
FIXTURES	
	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

R068

Question	Response
FIXTURES	
Staff And Other	
Lavatory/Sink	
Condition	1- Good
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Does not exist
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Does not exist
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Hydronic Heating	Inspected
Backflow Preventer	Does not exist
Hot Water Heat Exchanger	Does not exist
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	1- Good
Deficiency	PIPING:DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	A/C MER 2 @ Unit Heater
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Radiator/Convactor/Fin Tube	Inspected
Condition	1- Good
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE
Deficiency Location/Instance	Custodian's Office, Room 104
Deficiency Quantity	2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

R068

Question	Response
HEATING	
Radiator/Convactor/Fin Tube	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
HEATING PLANT	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
CO Detector	
Instance on 1st Floor	Not required
Gas System	
Instance on 1st Floor	Does not exist
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Does not exist
Hood Exhaust Ductwork	
Instance on 1st Floor	Does not exist
Hood Exhaust Fan	
Instance on 1st Floor	Does not exist
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
MDF Room	
Instance on Room 123	Inspected
Dedicated A/C Equipment	
Instance on Room 123	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

R068

Question	Response
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Sprinkler Head	
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Exhaust Fan	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist