

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

**Mechanical Inspection**

**R100**

School: **3K CENTER @ 2389 RICHMOND AVENUE - STATEN ISLAND, 2389 RICHMOND AVENUE, STATEN ISLAND, NY, 10314**

InspectionId	Inspection Type	Time In	Last Edited
3818	MECHANICAL	2021-03-22 10:55AM	2021-05-20 08:08AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	None
Are there any Emergency Stop Switches with Missing Hammers?	No components

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	condition recorded						

**Inspection**

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not exist
<b>Cooling Coil in Ductwork</b>	Does not exist
<b>Cooling Tower</b>	Does not exist
<b>Dry Cooler</b>	Does not exist
<b>DX Split System</b>	Inspected
<b>Indoor Unit</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Outdoor Unit</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Packaged / Rooftop Unit</b>	Inspected
Instance	Roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Johnson Controls, Inc
EquipmentId	RTU-1
Capacity/Size Quantity	9
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2020
Source of Installation Year	Documented
Source of Heating	Gas
Deficiency	No deficiencies recorded
Instance	Roof
Instance Condition	1- Good
Instance Quantity	4
Instance Quantity Uom	EACH
Manufacturer	Johnson Controls, Inc
EquipmentId	RTU-2, RTU-3, RTU-4, RTU-5
Capacity/Size Quantity	10
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

***Mechanical Inspection***

**R100**

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	
<b>Packaged / Rooftop Unit</b>	
Installation Year	2020
Source of Installation Year	Documented
Source of Heating	Gas
Deficiency	No deficiencies recorded
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Return Fan</b>	Does not exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
<b>BMS</b>	Inspected
Instance	Throughout
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Electric System</b>	Does not exist
<b>Hybrid System</b>	Does not exist
<b>Pneumatic System</b>	Does not exist
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Inspected
<b>Ash Hoist</b>	Does not exist
<b>Dumbwaiter</b>	Does not exist
<b>Elevator</b>	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
<b>Escalator</b>	Does not exist
<b>Non-auditorium Handicap Lift - Stair</b>	Does not exist
<b>Non-auditorium Handicap Lift - Vertical</b>	Does not exist
<b>Sidewalk Elevator</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Does not exist
<b>Water Service</b>	Inspected
Instance	Building Exterior - Water/Sprinkler Service Room
Instance Condition	2- Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

***Mechanical Inspection***

**R100**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Hot Water System</b>	
<b>Gas Fired Domestic Water Heater</b>	Does not exist
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Does not exist
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Sump Pump</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not exist
<b>Enclosed IDF Room</b>	Does not exist
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Does not exist
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Does not exist
<b>Sink And Fountain Combo Unit</b>	Does not exist
<b>Toilet</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Does not exist
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>CO/Gas Leak Detection</b>	Does not exist
<b>Gas Distribution Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Does not exist
<b>Gas Meter Room Vent</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

***Mechanical Inspection***

**R100**

<b>Question</b>	<b>Response</b>
<b>GAS SERVICE</b>	
Gas Pressure Booster	Does not exist
<b>HEATING</b>	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convactor/Fin Tube	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	Does not exist
<b>KITCHEN</b>	
Instance on 2nd Floor	Inspected
<b>CO Detector</b>	
Instance on 2nd Floor	Not required
<b>Gas System</b>	
Instance on 2nd Floor	Does not exist
<b>Grease Trap</b>	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on 2nd Floor	Does not exist
<b>Hood Exhaust Ductwork</b>	
Instance on 2nd Floor	Does not exist
<b>Hood Exhaust Fan</b>	
Instance on 2nd Floor	Does not exist
<b>Hood Fire Suppression System</b>	
Instance on 2nd Floor	Does not exist
<b>Hot Water Temperature Booster</b>	
Instance on 2nd Floor	Does not exist
<b>Kitchen Sink</b>	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>MDF Room</b>	
Instance on Room 216	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Room 216	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Booster Pump Assembly</b>	Does not exist
<b>Roof Tank</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2020-2021**

***Mechanical Inspection***

**R100**

<b>Question</b>	<b>Response</b>
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
<b>Siamese Connection</b>	Does not exist
<b>Sprinkler Head</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Does not exist
<b>Water Gong</b>	Does not exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Building Exterior - Water/Sprinkler Service Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Inspected
<b>Exhaust Fan</b>	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	Does not exist
<b>Metal Ductwork</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Does not exist
<b>Unit Ventilator</b>	Does not exist