

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

School: **NEW DORP HS (NEW) - S. I., 465 NEW DORP LANE, STATEN ISLAND, NY, 10306**

InspectionId	Inspection Type	Time In	Last Edited
2599	ELECTRICAL	2019-02-19 08:09AM	2019-04-04 03:05PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Public Address System (Amplifier), Auditorium (Local Sound System) Years: 2018 Systems: Auditorium (Projection System, House Lighting) Years: 2017 Systems: Partial Lighting - Security Years: 1998, 2006 Systems: Cafeteria (Local Sound System), Fire Alarm System Years: 2013 Systems: IPDVS/CCTV System Years: 2007 Systems: Most Exit Lights (Battery Pack) Years: 2015 Systems: Interior Retrofitted Fluorescent Lighting Years: 1996 Systems: Auditorium (Theater Lighting System), North Gymnasium (Local Sound System) Years: 2009 Systems: Intercom System (Elevator) Years: 2011 Systems: LAN, Telephone System Years: 2010 Systems: Transformers Years: 1982, 2006, 2017 Systems: Gymnasium (Retrofitted HID Lighting) Years: 2002 Systems: Intrusion Alarm System Years: 2000 Systems: All other Electrical Systems and Components Years: 1982 Below Ground
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Rooms N213, W323

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contact	Corridors by Rooms C151M, S165, S201G, E201, N201, W203, C350M, C366M, N303M, E301	Sean Deahl	Custodian	No Photo Taken

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

R435

Electrical Inspection

No	Local Sound System - Not Connected to Public Address System	N/A	Local Sound System	Auditorium	Sean Deahl	Custodian	No Photo Taken
----	---	-----	-----------------------	------------	------------	-----------	----------------

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Installation Year	2018
Source of Installation Year	Documented
Deficiency	NOT CONNECTED TO PUBLIC ADDRESS SYSTEM
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
AUDITORIUM	
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Condition	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Inspected
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Condition	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	45
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
	Does not exist
COMPUTER LAB	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Inspected
Power Panel?	Yes
Instance on Room E204	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
COMPUTER LAB	
Power Panel?	No
Lighting	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Inspected
Instance on Room E204	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Inspected
Instance on Room E204	Inspected
Pendant Mounted	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Does not exist
Instance on Room E204	Does not exist
Recessed Mounted	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Does not exist
Instance on Room E204	Does not exist
Lighting Fixture - HID	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Does not exist
Instance on Room E204	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Does not exist
Instance on Room E204	Does not exist
Lighting Fixture - LED	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Does not exist
Instance on Room E204	Does not exist
Raceway With Receptacles	
Instance on Rooms W101, W102, W106, W115, W119, W123, E205	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room E204	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	
	Does not exist
EMERGENCY GENERATOR SET	
	Inspected
Automatic Transfer Switch (ATS)	
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS #1
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room G50MH
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS #4
Capacity/Size Quantity	80
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room G50MH
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS #3
Capacity/Size Quantity	80
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room G50MH
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS #2
Capacity/Size Quantity	225
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room G50MH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Battery Charger	
Instance	Room G50MF
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	SENS
EquipmentId	Regulated Battery Charger
Capacity/Size Quantity	6
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	20
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room G50MF
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Diesel	
Instance	Room G50MF
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Consolidated Power Inc
EquipmentId	Emergency Generator
Capacity/Size Quantity	313
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	250
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	392
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room G50MF
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Natural Gas	
Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Does not exist	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Old 2nd Floor Cafeteria, North Gymnasium
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridor by East Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Storage Room by Room G50MA
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Statewide Fire Corp
EquipmentId	Central Station Fire Alarm
Capacity/Size Quantity	5

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
FIRE ALARM SYSTEM	
Fire Alarm Digital Communicator	
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Cutout Panel	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	
	Inspected
Condition	3- Fair
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridors by Rooms (C151M, S165, S201G, E201, N201, W203, C350, C366M, N303M, E301
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12076076K
Main Panel	
	Inspected
Bell At Panel	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 3
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	60
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	
	Does not exist
Manual Pull Station	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Display Monitor	
	Does not exist
Panel	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	
	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency	No deficiencies recorded
Punch Register	
	Does not exist
Sprinkler Flow/Air Pressure Switch	
Condition	Inspected
Deficiency	2- Between Good and Fair
Strobe	
Condition	Inspected
Deficiency	2- Between Good and Fair
Sub-Panel	
	Does not exist
Tamper Flow Switch/Chain	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
GROUNDING SYSTEM	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
GYMNASIUM	
Instance on Ground Floor - North	Inspected
Instance on Ground Floor - East	Inspected
Lighting	
Instance on Ground Floor - North	Inspected
Instance on Ground Floor - East	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor - North	Inspected
Instance on Ground Floor - East	Inspected
Pendant Mounted	
Instance on Ground Floor - North	Does not exist
Instance on Ground Floor - East	Does not exist
Recessed Mounted	
Instance on Ground Floor - North	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor - East	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Ground Floor - North	Does not exist
Instance on Ground Floor - East	Does not exist
Lighting Fixture - HID	
Instance on Ground Floor - North	Inspected
Instance on Ground Floor - East	Inspected
Pendant Mounted	
Instance on Ground Floor - North	Does not exist
Instance on Ground Floor - East	Does not exist
Recessed Mounted	
Instance on Ground Floor - North	Does not exist
Instance on Ground Floor - East	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Recessed Mounted	
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Ground Floor - North	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Ground Floor - East	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor - North	Does not exist
Instance on Ground Floor - East	Does not exist
Lighting Fixture - LED	
Instance on Ground Floor - North	Does not exist
Instance on Ground Floor - East	Does not exist
Local Sound System	
Instance on Ground Floor - North	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on Ground Floor - East	Inspected
Instance Condition	3- Fair
Installation Year	1982
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-Ground Floor - East
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Ground Floor - North	Does not exist
Instance on Ground Floor - East	Does not exist
Scoreboard	
Instance on Ground Floor - North	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor - East	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Ground Floor - North	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
GYMNASIUM	
Theater Lighting System	
Instance on Ground Floor - East	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room C360	Inspected
Lighting	
Instance on Room C360	Inspected
Lighting Fixture - Fluorescent	
Instance on Room C360	Inspected
Pendant Mounted	
Instance on Room C360	Does not exist
Recessed Mounted	
Instance on Room C360	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room C360	Does not exist
Lighting Fixture - HID	
Instance on Room C360	Does not exist
Lighting Fixture - Incandescent	
Instance on Room C360	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Incandescent	
Pendant Mounted	
Instance on Room C360	Does not exist
Recessed Mounted	
Instance on Room C360	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room C360	Does not exist
Lighting Fixture - LED	
Instance on Room C360	Does not exist
Projection System	
Instance on Room C360	Does not exist
Raceway With Receptacles	
Instance on Room C360	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Does not exist	
LOCKER ROOM	
Instance on Ground Floor - Boys	Inspected
Alternative Use	No
Instance on Ground Floor - Girls	Inspected
Alternative Use	No
Instance on North Gymnasium - Boys	Inspected
Alternative Use	No
Lighting	
Instance on Ground Floor - Boys	Inspected
Instance on Ground Floor - Girls	Inspected
Instance on North Gymnasium - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor - Boys	Inspected
Instance on Ground Floor - Girls	Inspected
Instance on North Gymnasium - Boys	Inspected
Pendant Mounted	
Instance on Ground Floor - Boys	Does not exist
Instance on Ground Floor - Girls	Does not exist
Instance on North Gymnasium - Boys	Does not exist
Recessed Mounted	
Instance on Ground Floor - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Ground Floor - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on North Gymnasium - Boys	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Ground Floor - Boys	Does not exist
Instance on Ground Floor - Girls	Does not exist
Instance on North Gymnasium - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Ground Floor - Boys	Does not exist
Instance on Ground Floor - Girls	Does not exist
Instance on North Gymnasium - Boys	Does not exist
Lighting Fixture - Incandescent	
Instance on Ground Floor - Boys	Does not exist
Instance on Ground Floor - Girls	Inspected
Instance on North Gymnasium - Boys	Inspected
Pendant Mounted	
Instance on Ground Floor - Girls	Does not exist
Instance on North Gymnasium - Boys	Does not exist
Recessed Mounted	
Instance on Ground Floor - Girls	Does not exist
Instance on North Gymnasium - Boys	Does not exist
Surface Mounted	
Instance on Ground Floor - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on North Gymnasium - Boys	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on Ground Floor - Boys	Does not exist
Instance on Ground Floor - Girls	Does not exist
Instance on North Gymnasium - Boys	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridors by Rooms G12, G24
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room G50MH, Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room G50MH, Boiler Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms W333, S217, S117
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Rooms C251, W203, W227, W225, E205, W201, S235, W101, W115, W123, W119
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
Instance	Room S329
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
PUBLIC ADDRESS SYSTEM	
Instance Quantity Uom	EACH
Model	
Installation Year	1982
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors, Classrooms, Office Rooms, Public Assembly Areas
Deficiency Quantity	100
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Classrooms, Office Rooms
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room S329
Deficiency Quantity	320,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	
Instance on Rooms C256, C258, C263	Inspected
Power Panel?	Yes
Alternative Use	Yes
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room W219	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Emergency Shut-Off Power	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Lighting	
Instance on Rooms C256, C258, C263	Inspected
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Instance on Room W219	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Rooms C256, C258, C263	Inspected
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Instance on Room W219	Inspected
Pendant Mounted	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Recessed Mounted	
Instance on Rooms C256, C258, C263	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W219	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Lighting Fixture - HID	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms C256, C258, C263	Inspected
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Instance on Room W219	Inspected
Pendant Mounted	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Recessed Mounted	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Surface Mounted	
Instance on Rooms C256, C258, C263	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room W219	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Power Supply	
Instance on Rooms C256, C258, C263	Inspected
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Instance on Room W219	Inspected
Instructor Unit	
Instance on Rooms C256, C258, C263	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W219	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist
Projection System	
Instance on Rooms C256, C258, C263	Does not exist
Instance on Rooms C271, E219, N209, S209, E209, S207, S217, W211, N221, W227	Does not exist
Instance on Room W219	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SCIENCE DEMO ROOM	
Projection System	
SCIENCE LAB	
Instance on Rooms E201, N225, N227, S235	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room W203	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room N320	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room N320	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room N320	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance on Room W203	Inspected
Instance on Room N320	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance on Room W203	Inspected
Instance on Room N320	Inspected
Pendant Mounted	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Does not exist
Instance on Room N320	Does not exist
Recessed Mounted	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room N320	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Does not exist
Instance on Room N320	Does not exist
Lighting Fixture - HID	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Does not exist
Instance on Room N320	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance on Room W203	Inspected
Instance on Room N320	Does not exist
Pendant Mounted	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Does not exist
Recessed Mounted	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Does not exist
Surface Mounted	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room W203	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Does not exist
Instance on Room N320	Does not exist
Power Supply	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance on Room W203	Inspected
Instance on Room N320	Does not exist
Instructor Unit	
Instance on Rooms E201, N225, N227, S235	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Instance on Room W203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms E201, N225, N227, S235	Does not exist
Instance on Room W203	Does not exist
Instance on Room N320	Does not exist
SCIENCE PREP ROOM	
Instance on Room C251/C255	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room C270	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room W229	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room C251/C255	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room C270	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W229	Does not exist
Emergency Shut-Off Power	
Instance on Room C251/C255	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room C270	Does not exist
Instance on Room W229	Does not exist
Lighting	
Instance on Room C251/C255	Inspected
Instance on Room C270	Inspected
Instance on Room W229	Inspected
Lighting Fixture - Fluorescent	
Instance on Room C251/C255	Inspected
Instance on Room C270	Inspected
Instance on Room W229	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room C251/C255	Does not exist
Instance on Room C270	Does not exist
Instance on Room W229	Does not exist
Recessed Mounted	
Instance on Room C251/C255	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room C270	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room C251/C255	Does not exist
Instance on Room C270	Does not exist
Instance on Room W229	Does not exist
Lighting Fixture - HID	
Instance on Room C251/C255	Does not exist
Instance on Room C270	Does not exist
Instance on Room W229	Does not exist
Lighting Fixture - Incandescent	
Instance on Room C251/C255	Does not exist
Instance on Room C270	Does not exist
Instance on Room W229	Inspected
Pendant Mounted	
Instance on Room W229	Does not exist
Recessed Mounted	
Instance on Room W229	Does not exist
Surface Mounted	
Instance on Room W229	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - LED	
Instance on Room C251/C255	Does not exist
Instance on Room C270	Does not exist
Instance on Room W229	Does not exist
Power Supply	
Instance on Room C251/C255	Inspected
Instance on Room C270	Inspected
Instance on Room W229	Inspected
Instructor Unit	
Instance on Room C251/C255	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SCIENCE PREP ROOM	
Power Supply	
Instructor Unit	
Deficiency	No deficiencies recorded
Instance on Room C270	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room W229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Room S329
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
Does not exist	
IPDVS/CCTV System	
Condition	2- Between Good and Fair
Installation Year	2007
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	
Condition	3- Fair
Replacement Quantity	155
Replacement Uom	EACH
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Exterior Walls by (Parking Yards, New Dorp Lane)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE PHOTOCCELL NOT OPERATIONAL
Deficiency Location/Instance	Parking Lot, Exterior Wall by Exit 17
Deficiency Quantity	2

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SECURITY	
Lighting - Security	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Roof Perimeter, Exterior Walls
Deficiency Quantity	114
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Feed Transformer T1
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Feed Transformer T4
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Feed Transformer T3
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SERVICE SWITCH	
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Feed Transformer T2
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Main Switch Dist. Swbd #1
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher
EquipmentId	Main Switch Dist. Swbd #2
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	3
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G50MF
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Panel EGDG (Emergency Generator Switchboard)
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G42M
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Sub - Dist. Switchboard A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G42M
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Sub - Dist. Switchboard B
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	
	Inspected
Lighting Fixture - Fluorescent	
Pendant Mounted	
	Does not exist
Recessed Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
TRANSFORMER	
	Inspected
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
TRANSFORMER	
Instance Quantity Uom	EACH
Manufacturer	General Signal
EquipmentId	FA Transformer T8
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Transformer T4
Capacity/Size Quantity	1000
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Transformer T2
Capacity/Size Quantity	750
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Transformer T3
Capacity/Size Quantity	750
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room G50MH
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	Transformer T1
Capacity/Size Quantity	1000
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
TRANSFORMER	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G42M
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Signal
EquipmentId	T-10
Capacity/Size Quantity	45
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G42M
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Signal
EquipmentId	T-7
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G42M
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Signal
EquipmentId	T-11
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G42M
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Signal
EquipmentId	T-6
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room G42M
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R435

Question	Response
TRANSFORMER	
Manufacturer	General Signal
EquipmentId	T-5
Capacity/Size Quantity	500
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	1982
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Mechanical Room N303M
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Mechanical Room N205M
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Rex Power Magnetics
EquipmentId	TR - N304
Capacity/Size Quantity	30
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not exist