

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R456

School: TOTTENVILLE HS AF - STATEN ISLAND, 100 LUTEN AVENUE, STATEN ISLAND, NY, 10312

InspectionId	Inspection Type	Time In	Last Edited
2986	ELECTRICAL	2019-03-11 12:09PM	2019-03-20 01:53PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Partial Scoreboard Years: 2013, 2016 Systems: Athletic Field Exterior Lighting Years: 2000, 2016 Systems: Local Sound System Years: 2013 Systems: Interior Fluorescent Lighting, Lighting - Security, Grounding System, Molded Case Circuit Breaker Panel Board Years: 2000
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	No
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	condition recorded						

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Inspected
Exterior Lighting	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	111
Replacement Uom	EACH
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Condition	2- Between Good and Fair
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Scoreboard	Inspected
Instance	Softball Field
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Instance	Baseball Field
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
Instance	Football Field
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R456

Question	Response
ATHLETIC FIELD	
Scoreboard	
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
CAFETERIA	Does not exist
CITY FIRE ALARM SYSTEM	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Does not exist
EXIT LIGHT	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Does not exist
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not exist
INTERCOM SYSTEM	Does not exist
KITCHEN	Does not exist
LAN	Does not exist
LIBRARY	Does not exist
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Does not exist
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

R456

Question	Response
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Does not exist
IPDVS/CCTV System	Does not exist
Lighting - Security	Inspected
Condition	3- Fair
Replacement Quantity	4
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Panel #1
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Panel #2
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Does not exist
TELEPHONE SYSTEM	Does not exist
TOILET ROOM - STAFF	Does not exist
TOILET ROOM - STUDENT	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist