

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**R461**

**School:** WAGNER HS AF - STATEN ISLAND, 1200 MANOR ROAD, STATEN ISLAND, NY, 10314

InspectionId	Inspection Type	Time In	Last Edited
2683	ELECTRICAL	2019-02-27 08:41AM	2019-02-27 03:19PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Athletic Field Exterior Lighting Years: 2000 Systems: Local Sound System Years: 2005 Systems: Scoreboard Years: 2012
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	No
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Inspected
<b>Exterior Lighting</b>	Inspected
Condition	3- Fair
Replacement Quantity	8
Replacement Uom	EACH
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	Inspected
Condition	3- Fair
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	Inspected
Instance	By Brielle Avenue
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	No deficiencies recorded
<b>AUDITORIUM</b>	Does not exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Does not exist
<b>CAFETERIA</b>	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	Does not exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Does not exist
<b>COMPUTER LAB</b>	Does not exist
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not exist
<b>EMERGENCY LIGHTING</b>	Does not exist
<b>EXIT LIGHT</b>	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2018-2019

*Electrical Inspection*

R461

Question	Response
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Does not exist
GROUNDING SYSTEM	Does not exist
GYMNASIUM	Does not exist
INTERCOM SYSTEM	Does not exist
KITCHEN	Does not exist
LAN	Does not exist
LIBRARY	Does not exist
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Does not exist
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Does not exist
PUBLIC ADDRESS SYSTEM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Does not exist
SERVICE SWITCH	Does not exist
SWIMMING POOL	Does not exist
SWITCHBOARD	Does not exist
TELEPHONE SYSTEM	Does not exist
TOILET ROOM - STAFF	Does not exist
TOILET ROOM - STUDENT	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist