

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X039

Asset: NEW SCH FOR ARTS AND SCIENCE - X, 965 LONGWOOD AVENUE, New York, 10459

Inspection Id	Inspection Type	Time In	Last Edited
EE : X039	Electrical	2017-12-01 8:13 AM	2017-12-01 3:35 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Interior Fluorescent Lighting (Except Kitchen, Science Rooms), Exit Lights (Battery Pack), Emergency Lighting (Battery Pack)
	Years: 2013
	Systems: LAN
	Years: 2010
	Systems: Kitchen, Science Rooms, Most Security Lights, IPDVS/CCTV System, Grounding System
	Years: 2007
	Systems: Public Address System, Local Sound System, Intrusion Alarm System (Infrared Sensors)
	Years: 2004
	Systems: Fire Alarm System, Emergency Light/Exit Light Panel
	Years: 2003
	Systems: Molded Case Circuit Breaker Panel Board
	Years: 1992, 2007, 2009
	Systems: Service Switch
	Years: 1992, 2007
	Systems: Switchboard, Intrusion Alarm System
	Years: 1992

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	Photo/Image
Yes	Water Leaks onto Electrical Equipment	N/A	Electrical Outlet	Boiler Room	Anthony Fichera	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Inspected
Installation Year	2004
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not Exist
Theater Lighting System	
Instance on Basement	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
COMPUTER LAB	
Lighting	
Instance on Room 111	Inspected
Power Panel	No
Instance on Rooms 311, 318	Inspected
Power Panel	No
Lighting	
Instance on Rooms 311, 318	Inspected
Instance on Room 111	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X039

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Rooms 311, 318	Inspected
Instance on Room 111	Inspected
Pendant Mounted	Inspected
Instance on Rooms 311, 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 111	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 311, 318	Does not Exist
Instance on Room 111	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Rooms 311, 318	Does not Exist
Instance on Room 111	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 311, 318	Does not Exist
Instance on Room 111	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 311, 318	Does not Exist
Instance on Room 111	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 311, 318	Does not Exist
Instance on Room 111	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Rooms 311, 318	Does not Exist
Instance on Room 111	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Inspected
Instance on Room 318	Inspected
Lighting	Inspected
Instance on Room 318	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 318	Inspected
Pendant Mounted	Inspected
Instance on Room 318	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 318	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 318	Does not Exist
Lighting Fixture - HID	
Instance on Room 318	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 318	Does not Exist
Lighting Fixture - LED	
Instance on Room 318	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 318	Does not Exist
Projection System	Does not Exist
Instance on Room 318	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X039

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	
Instance on Basement	Does not Exist
Projection System	
Instance on Basement	Does not Exist
Theater Lighting System	
Instance on Basement	Does not Exist
SCIENCE DEMO ROOM	
Instance on Room 307	Inspected
Power Panel Alternative use	No No
Lighting	
Instance on Room 307	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 307	Inspected
Pendant Mounted	
Instance on Room 307	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 307	Does not Exist
Recessed Mounted	
Instance on Room 307	Does not Exist
Lighting Fixture - HID	
Instance on Room 307	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 307	Does not Exist
Lighting Fixture - LED	
Instance on Room 307	Does not Exist
Projection System	
Instance on Room 307	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Gas Shut-Off Valve	
Instance on Room 307	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 307	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 307	Inspected
Instructor Unit	
Instance on Room 307	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
SCIENCE DEMO ROOM	
Power Supply	
Instructor Unit	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 307	Does not Exist
SCIENCE LAB	
Instance on Room 301	Inspected
Power Panel	Yes
Alternative use	Yes
Instance on Room 302	Inspected
Power Panel	No
Alternative use	No
Lighting	
Instance on Room 302	Inspected
Instance on Room 301	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 302	Inspected
Instance on Room 301	Inspected
Pendant Mounted	
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 302	Does not Exist
Instance on Room 301	Does not Exist
Recessed Mounted	
Instance on Room 302	Does not Exist
Instance on Room 301	Does not Exist
Lighting Fixture - HID	
Instance on Room 302	Does not Exist
Instance on Room 301	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 302	Does not Exist
Instance on Room 301	Does not Exist
Lighting Fixture - LED	
Instance on Room 302	Does not Exist
Instance on Room 301	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	
	Inspected
Instance on Room 302	Inspected
Instance on Room 301	Inspected
Instructor Unit	
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 302	Does not Exist
Instance on Room 301	Does not Exist
Meter Demonstration Unit	
Instance on Room 302	Does not Exist
Instance on Room 301	Does not Exist
Projection System	
	Inspected
Instance on Room 302	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
	Inspected
Instance on Room 302A	Inspected
Power Panel	No
Alternative use	No
Lighting	
	Inspected
Instance on Room 302A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 302A	Inspected
Pendant Mounted	
	Inspected
Instance on Room 302A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
	Does not Exist
Instance on Room 302A	Does not Exist
Recessed Mounted	
	Does not Exist
Instance on Room 302A	Does not Exist
Lighting Fixture - HID	
Instance on Room 302A	Does not Exist
Lighting Fixture - Incandescent	

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X039

Question	Response
SCIENCE PREP ROOM	
Lighting	Inspected
Lighting Fixture - Incandescent	
Instance on Room 302A	Does not Exist
Lighting Fixture - LED	
Instance on Room 302A	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 302A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 302A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Power Supply	Does not Exist
Instance on Room 302A	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	84,000
Replacement Uom	S.F.
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Deficiency	INDICATOR PANEL NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2 - Between Good and Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Custodian's Workshop
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor by Stair B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CITY FIRE ALARM SYSTEM	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
CITY FIRE ALARM SYSTEM	Inspected
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	84,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Fire Alarm Control Panel
Model	MXL - IQ
Capacity/Size Quantity	14
Capacity/Size UOM	Zones
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Diagram
Installation Year	2003

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X039

Question	Response
FIRE ALARM SYSTEM	Inspected
Main Panel	Inspected
Fire Alarm Control Panel (Electronic)	Inspected
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROL CENTER	Does not Exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
PANEL BOARD	
Fused Toggle Switch Type	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
Condition	Inspected
	2 - Between Good and Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Cafeteria, Electrical Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Room B10, 1st Floor Corridor by Room 104A, Kitchen, Sub-Basement by Electrical Room
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	
	Inspected
Replacement Quantity	84,000
Replacement Uom	S.F.
Instance	Room B6
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA 250
Installation Year	2004
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Replacement Quantity	84,000

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X039

Question	Response
SECURITY	
IPDVS/CCTV System	
Replacement Uom	S.F.
Installation Year	2007
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	
Replacement Quantity	84,000
Replacement Uom	S.F.
Central Control Panel	
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1992
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	
	Does not Exist
Lighting - Security	
Replacement Quantity	22
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	On wall facing Kelly Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo 1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	On walls facing (Courtyard, Beck Street)
Deficiency Quantity	2
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2017 - 2018**

Electrical Inspection

X039

Question	Response
SECURITY	
Lighting - Security	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Main Switch
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2007
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Main Switch
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1992
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
	Inspected
Number of Spares	0
Air Circuit Breaker Type	
	Does not Exist
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1992
Source of Installation	Documented

NYC Department of Education
Building Condition Assessment Survey 2017 - 2018

Electrical Inspection

X039

Question	Response
SWITCHBOARD	Inspected
Fused Disconnect Switch Type	Inspected
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not Exist