

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

School: P.S. 96 - BRONX, 2385 OLINVILLE AVENUE, BRONX, NY, 10467

InspectionId	Inspection Type	Time In	Last Edited
1050	ELECTRICAL	2018-12-28 11:49AM	2019-01-24 12:39PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Toilet Rooms Years: 2015, 2018 Systems: Service Switch, Telephone System, New Addition (Interior Fluorescent Lighting), Original Building (Recessed Mounted Fluorescent Lighting), Auditorium (Fluorescent Lighting), Cafeteria, Kitchen, Multipurpose Room, Science Lab - Room 268, Auxiliary Signal/Bell System, Emergency Generator Set, Partial Emergency Lights, Partial Exit Lights (Battery Pack), Grounding System, Intercom System (Elevator), LAN, Lightning Protection, Most Motor Starters, Fused Disconnect Switch Type Panel Board, IPDVS/CCTV System, Intrusion Alarm System Years: 2015 Systems: Public Address System (Except Original Building - Speakers, Clocks) Years: 2016 Systems: Fire Alarm System Years: 2017 Systems: Library Years: 2008 Systems: Security Lights Years: 2008, 2015 Systems: Most Molded Case Circuit Breaker Panel Boards Years: 2001, 2009, 2015 Systems: Switchboard Years: 2010, 2015 Systems: Original Building (Pendant Mounted Fluorescent Lighting, Surface Mounted Fluorescent Lighting) Years: 1998
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Emergency Lighting - Not Operational	Emergency Lights Battery Not Operational	Emergency Lighting	Gymnasium, Staircase E	Michael Lydon	Custodian	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
AUDITORIUM	
House Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1960
Source of Installation Year	Inspector Estimate
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not exist
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	1- Good
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Cellar	Inspected
Lighting	
Instance on Cellar	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Cellar	Inspected
Pendant Mounted	
Instance on Cellar	Does not exist
Recessed Mounted	
Instance on Cellar	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Cellar	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Cellar	Does not exist
Lighting Fixture - Incandescent	
Instance on Cellar	Does not exist
Lighting Fixture - LED	
Instance on Cellar	Does not exist
Local Sound System	
Instance on Cellar	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Cellar	Does not exist
Theater Lighting System	
Instance on Cellar	Does not exist
CITY FIRE ALARM SYSTEM	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
	Inspected
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Does not exist
Lighting Fixture - LED	
	Does not exist
COMPUTER LAB	
Instance on Rooms 307, 419	Inspected
Power Panel?	No
Lighting	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
COMPUTER LAB	
Lighting	
Instance on Rooms 307, 419	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 307, 419	Inspected
Pendant Mounted	
Instance on Rooms 307, 419	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 307, 419	Does not exist
Surface Mounted	
Instance on Rooms 307, 419	Does not exist
Lighting Fixture - HID	
Instance on Rooms 307, 419	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 307, 419	Does not exist
Lighting Fixture - LED	
Instance on Rooms 307, 419	Does not exist
Raceway With Receptacles	
Instance on Rooms 307, 419	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Pump Room C21
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metron Inc
EquipmentId	Fire Pump Automatic Transfer Switch
Capacity/Size Quantity	260
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C73
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	80
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C73
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS SRP-T
Capacity/Size Quantity	225

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C73
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS ESB
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Generator Enclosure
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Generac
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Outside Generator Enclosure
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Generac
EquipmentId	Emergency Generator
Capacity/Size Quantity	625
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	500
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	1,735
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium, Staircase E
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	
	Does not exist
FIRE ALARM SYSTEM	
	Inspected
Area Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Instance	Main Entrance Lobby
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	36
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 3rd Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1960
Source of Installation Year	Inspector Estimate
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 3rd Floor	Does not exist
Scoreboard	
Instance on 3rd Floor	Does not exist
Theater Lighting System	
Instance on 3rd Floor	Does not exist
INTERCOM SYSTEM	
	Inspected
Elevator	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Holding Area	
	Does not exist
KITCHEN	
Instance on Cellar	Inspected
Lighting	
Instance on Cellar	Inspected
Lighting Fixture - Fluorescent	
Instance on Cellar	Inspected
Pendant Mounted	
Instance on Cellar	Does not exist
Recessed Mounted	
Instance on Cellar	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Cellar	Does not exist
Lighting Fixture - HID	
Instance on Cellar	Does not exist
Lighting Fixture - Incandescent	
Instance on Cellar	Does not exist
Lighting Fixture - LED	
Instance on Cellar	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 206	Inspected
Lighting	
Instance on Room 206	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 206	Inspected
Pendant Mounted	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 206	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 206	Inspected
Pendant Mounted	
Instance on Room 206	Does not exist
Recessed Mounted	
Instance on Room 206	Does not exist
Surface Mounted	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on Room 206	Does not exist
Projection System	
Instance on Room 206	Does not exist
Raceway With Receptacles	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
LIBRARY	
Raceway With Receptacles	
Instance on Room 206	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Does not exist
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Original Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
Instance	Inspected
Instance Condition	MDF Room 171
Instance Quantity	1- Good
Instance Quantity Uom	1
Model	EACH
Installation Year	Rauland MPA 250
Source of Installation Year	2016
Deficiency	Custodial Staff
Deficiency Location/Instance	CLOCK NOT OPERATIONAL
Deficiency Quantity	Classrooms and Corridors
Quantity Uom	22
Potential Action	EACH
Urgency of Action	REPAIR
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
	No violations recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
Instance on Room 268	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 268	Does not exist
Emergency Shut-Off Power	
Instance on Room 268	Does not exist
Lighting	
Instance on Room 268	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 268	Inspected
Pendant Mounted	
Instance on Room 268	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 268	Does not exist
Surface Mounted	
Instance on Room 268	Does not exist
Lighting Fixture - HID	
Instance on Room 268	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 268	Does not exist
Lighting Fixture - LED	
Instance on Room 268	Does not exist
Power Supply	
Instance on Room 268	Does not exist
Projection System	
Instance on Room 268	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SECURITY	
Intrusion Alarm System	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Instance	Custodian's Office - Room 118
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Exit 4, Exit 7
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Replacement Quantity	36
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room Old Wing
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
SERVICE SWITCH	
Instance	Electrical Room Old Wing
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDP
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room Old Wing
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Fire Pump
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	10
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room Old Wing
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	N/A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room C71
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MSB-A
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2015

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C71
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Room C73
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	ESB (Emergency Generator Switchboard)
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X096

Question	Response
TOILET ROOM - STUDENT	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist