

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

School: **I.S. 216 - BRONX, 977 FOX STREET, BRONX, NY, 10459**

InspectionId	Inspection Type	Time In	Last Edited
940	ELECTRICAL	2018-12-19 09:49AM	2019-05-09 02:12PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Emergency Light/ Exit Light Panel, Service Switch and Switchboard for Emergency Lighting Years: 1995 Systems: Partial Panel Boards Years: 1995, 2000, 2011 Systems: Intrusion Alarm System Years: 1996 Systems: Telephone System, Grounding System Years: 2003 Systems: Partial Motor Starters, Emergency DC Standby Battery Power Years: 2010 Systems: Public Address System, Local Sound Systems, Fire Alarm System, IPDVS/CCTV System, Elevator - Intercom Years: 2010 Systems: Security Lights Years: 2011, 1992 Systems: Library, Lightning Protection, Partial Panelboards - Fused Disconnect Type Years: 2012 Systems: Battery Pack Exit Lights Years: 2013 Systems: Computer Lab Room 312 Years: 2014 Systems: Interior Lighting (Except Library and Computer Room 312) Years: 2016 Systems: Battery Pack Emergency Lighting, Exit/Emergency Lights Years: Under Construction
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Emergency DC Standby Battery Power - Battery Bank Not Operational	N/A	Emergency DC Standby Battery Power	Room C8 - Electrical Room	Shane Snead	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
AUDITORIUM	
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	116
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Electrical Inspection

X116

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Lighting	
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Large	Inspected
Instance on 1st Floor - Small	Inspected
Pendant Mounted	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Recessed Mounted	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Surface Mounted	
Instance on 1st Floor - Large	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on 1st Floor - Small	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Local Sound System	
Instance on 1st Floor - Large	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 1st Floor - Small	Does not exist
Projection System	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
Theater Lighting System	
Instance on 1st Floor - Large	Does not exist
Instance on 1st Floor - Small	Does not exist
CITY FIRE ALARM SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected

NYC Department of Education
 Building Condition Assessment Survey 2018-2019

Electrical Inspection

X116

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	
Instance on Room 112	Inspected
Power Panel?	Yes
Instance on Room 312	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 112	Inspected
Instance on Room 312	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 112	Inspected
Instance on Room 312	Inspected
Pendant Mounted	
Instance on Room 112	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 312	Does not exist
Recessed Mounted	
Instance on Room 112	Does not exist
Instance on Room 312	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 112	Does not exist
Instance on Room 312	Does not exist
Lighting Fixture - HID	
Instance on Room 112	Does not exist
Instance on Room 312	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 112	Does not exist
Instance on Room 312	Does not exist
Lighting Fixture - LED	
Instance on Room 112	Does not exist
Instance on Room 312	Does not exist
Raceway With Receptacles	
Instance on Room 112	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 312	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
COMPUTER LAB	
Raceway With Receptacles	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Inspected
Condition	5- Poor
Deficiency	BATTERY BANK NOT OPERATIONAL
Deficiency Location/Instance	Room C8 - Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Room C8 - Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Under construction
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Under construction
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
FIRE ALARM SYSTEM	
Fan Shutdown Control	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 3
EquipmentId	Fire Alarm Control Panel MEA#1392E
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	Inspected
Deficiency	3- Fair
GYMNASIUM	
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
INTERCOM SYSTEM	
Elevator	Inspected
Condition	Inspected
Deficiency	2- Between Good and Fair
Holding Area	No deficiencies recorded
KITCHEN	
Instance on 1st Floor	Does not exist
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 315	Inspected
Lighting	
Instance on Room 315	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 315	Inspected
Pendant Mounted	
Instance on Room 315	Does not exist
Recessed Mounted	
Instance on Room 315	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 315	Does not exist
Lighting Fixture - HID	
Instance on Room 315	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 315	Does not exist
Lighting Fixture - LED	
Instance on Room 315	Does not exist
Projection System	
Instance on Room 315	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	
Instance on Room 315	Does not exist
LIGHTNING PROTECTION	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LOCKER ROOM	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
LOCKER ROOM	
Instance on Room 211 - Boys	Inspected
Alternative Use	Yes
Instance on Room 215 - Girls	Inspected
Alternative Use	Yes
Lighting	
Instance on Room 211 - Boys	Inspected
Instance on Room 215 - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 211 - Boys	Inspected
Instance on Room 215 - Girls	Inspected
Pendant Mounted	
Instance on Room 211 - Boys	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 215 - Girls	Does not exist
Recessed Mounted	
Instance on Room 211 - Boys	Does not exist
Instance on Room 215 - Girls	Does not exist
Surface Mounted	
Instance on Room 211 - Boys	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 215 - Girls	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 211 - Boys	Does not exist
Instance on Room 215 - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 211 - Boys	Does not exist
Instance on Room 215 - Girls	Does not exist
Lighting Fixture - LED	
Instance on Room 211 - Boys	Does not exist
Instance on Room 215 - Girls	Does not exist
MOTOR CONTROL CENTER	
Instance	Inspected
Instance	Room C12 - Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington Electric
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1975
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room C12 - Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
MOTOR CONTROL CENTER	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, 2nd Floor MER, 4th Floor MER
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 305
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
PUBLIC ADDRESS SYSTEM	
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
Instance on Room 214, 216, 314	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 316	Inspected
Power Panel?	Yes
Alternative Use	Yes
Emergency Gas Shut-Off Valve	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Does not exist
Emergency Shut-Off Power	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 214, 216, 314	Inspected
Instance on Room 316	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 214, 216, 314	Inspected
Instance on Room 316	Inspected
Pendant Mounted	
Instance on Room 214, 216, 314	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 316	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Does not exist
Surface Mounted	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Does not exist
Lighting Fixture - HID	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Does not exist
Lighting Fixture - LED	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Does not exist
Power Supply	
Instance on Room 214, 216, 314	Does not exist
Instance on Room 316	Does not exist
Projection System	
Instance on Room 214, 216, 314	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
SCIENCE LAB	
Projection System	
Instance on Room 316	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SECURITY	
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 121
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	23
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	
Instance	Room C8 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	Main Service Switch
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Diagram in Room
Installation Year	1975
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room C8 - Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
SERVICE SWITCH	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room C8 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	EMG LIGHT DISCONNECT SWITCH
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	1
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Room C8 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	5
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1975
Source of Installation Year	Documented
Deficiency	FUSED DISCONNECT NOT OPERATIONAL
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room C8 - Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Room C8 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gallagher Switchboard Co.
EquipmentId	DP-EM

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X116

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	
	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	
	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Does not exist
Surface Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	
	Does not exist
TV SYSTEM	
	Inspected
Cable System Exist?	Yes
Operational?	No
Main Equipment Rack	Does not exist