

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

School: **P.S. 140 - BRONX, 916 EAGLE AVENUE, BRONX, NY, 10456**

InspectionId	Inspection Type	Time In	Last Edited
2228	ELECTRICAL	2019-02-06 08:18AM	2019-03-27 02:26PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Emergency Light/Exit Light Panel Years: 1990 Systems: Service Switch, Switchboard, Grounding System, Panelboards, Fluorescents Lights - Gymnasium, Corridors and Staircases Years: 2008 Systems: Partial Motor Starters, Lightning Protection System, Fire Alarm System - Sprinkler Flow Switch Years: 2013 Systems: Intrusion Alarm System Years: 2002 Systems: Interior Lighting, Auditorium - LED Lights, Telephone System, Fire Alarm System - Partial Sub Panel, Heat and CO Detectors Years: 2014 Systems: Security Lights Years: 2019
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Defective	Panel Defective	Fire Alarm System - Sub Panel	Boiler Room	Lassana Fofana	Fireman	No Photo Taken

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	
Instance on Basement	Inspected
<b>House Lighting</b>	
Instance on Basement	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not exist
<b>Recessed Mounted</b>	
Instance on Basement	Does not exist
<b>Surface Mounted</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

Question	Response
<b>AUDITORIUM</b>	
<b>House Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not exist
<b>Recessed Mounted</b>	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement	Does not exist
<b>Local Sound System</b>	
Instance on Basement	Inspected
Instance Condition	5- Poor
Installation Year	1972
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Projection System</b>	
Instance on Basement	Does not exist
<b>Theater Lighting System</b>	
Instance on Basement	Inspected
<b>Dimming System</b>	
Instance on Basement	Does not exist
<b>Theater Lighting</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

Question	Response
<b>AUDITORIUM</b>	
<b>Theater Lighting System</b>	
<b>Theater Lighting</b>	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
Condition	Inspected
Deficiency	3- Fair
<b>CAFETERIA</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1972
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 1st Floor	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	
Condition	Inspected
Deficiency	5- Poor
Deficiency Location/Instance	NOT OPERATIONAL
Deficiency Quantity	Corridor 1st Floor
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 5
Violations	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

<b>Question</b>	<b>Response</b>
<b>CITY FIRE ALARM SYSTEM</b>	
Violations	No violations recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>COMPUTER LAB</b>	
Instance on Room 320	Inspected
Power Panel?	Yes
Instance on Room B24	Inspected
Power Panel?	No
<b>Lighting</b>	
Instance on Room 320	Inspected
Instance on Room B24	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 320	Inspected
Instance on Room B24	Inspected
<b>Pendant Mounted</b>	
Instance on Room 320	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room B24	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 320	Does not exist
Instance on Room B24	Does not exist
<b>Surface Mounted</b>	
Instance on Room 320	Does not exist
Instance on Room B24	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 320	Does not exist
Instance on Room B24	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 320	Does not exist
Instance on Room B24	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 320	Does not exist
Instance on Room B24	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 320	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

Question	Response
<b>COMPUTER LAB</b>	
<b>Raceway With Receptacles</b>	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room B24	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	
	Does not exist
<b>EMERGENCY GENERATOR SET</b>	
	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHTING</b>	
	Inspected
<b>Battery Pack</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
	Inspected
<b>Battery Pack</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	
	Does not exist
<b>FIRE ALARM SYSTEM</b>	
	Inspected
<b>Area Smoke Detector</b>	
	Does not exist
<b>Bell/Horn</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	
	Does not exist
<b>Elevator Recall</b>	
	Does not exist
<b>Fan Shutdown Control</b>	
	Does not exist
<b>Fire Alarm Digital Communicator</b>	
	Does not exist
<b>Fused Cutout Panel</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	
	Does not exist
<b>Main Panel</b>	
	Inspected
<b>Bell At Panel</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	
	Does not exist
<b>Fire Alarm Control Panel (Standard)</b>	
Instance	Boiler Room

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Standard)</b>	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	6
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	85,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Manual Pull Station</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Strobe</b>	Does not exist
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cerberus Pyrotronics
Model	PRO FC901
EquipmentId	CO & Heat Detector Panel
Capacity/Size Quantity	2
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Fire Alarm Control Panel (Standard)</b>	Inspected
Instance	Boiler Room

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	
<b>Fire Alarm Control Panel (Standard)</b>	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Circuits
Source of Capacity/Size	Inspector Estimate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	85,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 2nd Floor	Inspected
<b>Lighting</b>	
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Does not exist
<b>Local Sound System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1972
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Local Sound System</b>	
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Projection System</b>	
Instance on 2nd Floor	Does not exist
<b>Scoreboard</b>	
Instance on 2nd Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 2nd Floor	Does not exist
<b>INTERCOM SYSTEM</b>	
Does not exist	
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>LAN</b>	
Inspected	
<b>Local Distribution Frame (I/LDF)</b>	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance on Room 327	Inspected
<b>Lighting</b>	
Instance on Room 327	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 327	Inspected
<b>Pendant Mounted</b>	
Instance on Room 327	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 327	Does not exist
<b>Surface Mounted</b>	



**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Room 327	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 327	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 327	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 327	Does not exist
<b>Projection System</b>	
Instance on Room 327	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 327	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	
Condition	Inspected
Deficiency	1- Good
Deficiency	No deficiencies recorded
<b>LOCKER ROOM</b>	
Instance on 2nd Floor	Inspected
Alternative Use	Yes
<b>Lighting</b>	
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Does not exist
<b>MOTOR CONTROL CENTER</b>	
	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	
	Does not exist
<b>PANEL BOARD</b>	
	Inspected
<b>Fused Disconnect Switch Type</b>	Does not exist
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

<b>Question</b>	<b>Response</b>
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Instance	Room 112
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 125
Installation Year	1972
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 112
Deficiency Quantity	85,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SECURITY</b>	Inspected
<b>Intrusion Alarm System</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	Room 116
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2002
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	Does not exist
<b>IPDVS/CCTV System</b>	Does not exist
<b>Lighting - Security</b>	Inspected
Condition	1- Good
Replacement Quantity	17
Replacement Uom	EACH
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Instance Quantity Uom	EACH
Manufacturer	Electric Switchboard
EquipmentId	Main Switch A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electric Switchboard
EquipmentId	Main Switch B
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
EquipmentId	Mini School Main Switch
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	S.Switch - L.P.E.M Emergency Disconnect Switch
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Does not exist
<b>SWITCHBOARD</b>	Inspected
Number of Spares	3
<b>Air Circuit Breaker Type</b>	Does not exist
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X140**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Manufacturer	Electric Switchboard
EquipmentId	SWBD A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electric Switchboard
EquipmentId	SWDB B
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	
	Inspected
<b>PBX/Intercom</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Standard</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	
	Inspected
<b>Lighting</b>	
	Inspected
<b>Lighting Fixture - Fluorescent</b>	
	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	
	Inspected
<b>Lighting</b>	
	Inspected
<b>Lighting Fixture - Fluorescent</b>	
	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2018-2019

*Electrical Inspection*

X140

Question	Response
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TRANSFORMER</b>	Does not exist
<b>TV SYSTEM</b>	Inspected
Cable System Exist?	Yes
Operational?	Yes
<b>Main Equipment Rack</b>	Does not exist