

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

School: THE NORWOOD EAST CAMPUS - BRONX, 3177 WEBSTER AVENUE, BROOKLYN, NY, 10467

InspectionId	Inspection Type	Time In	Last Edited
3798	ELECTRICAL	2020-02-24 08:09AM	2020-02-24 03:54PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Electrical Systems and Components Years: 2014
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Other	They cannot make any Announcements because of Public Address System (Microphone/Jack Not Operational)	Public Address System (Microphone/Jack Not Operational)	Custodian's Office, Room 108	Joseph Gonazalez	Fireman	No Photo Taken
No	Emergency Generator Components - Not Operational	Fire Alarm System Main Panel is on Trouble Mode because of Generator Not Operational	Emergency Generator	Roof - Generator Enclosure	Joseph Gonazalez	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CITY FIRE ALARM SYSTEM	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Surface Mounted	Does not exist
COMPUTER LAB	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS#1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ERP-GENERATOR
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Fire Pump Room 130
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Tornatech
EquipmentId	FirePump Power Transfer Switch
Capacity/Size Quantity	60
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof - Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	SENS
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Diesel	Inspected
Instance	Roof - Generator Enclosure
Instance Condition	4- Between Fair and Poor

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
EMERGENCY GENERATOR SET	
Diesel	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Emergency Generator
Capacity/Size Quantity	345
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	276
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	958
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	GENERATOR NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	By Room 329
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
FIRE ALARM SYSTEM	
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3
EquipmentId	Fire Alarm Horn Strobe Panel
Capacity/Size Quantity	24
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Does not exist
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Instance on 4th Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Instance on 4th Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Does not exist
Dimming System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	
Does not exist	
KITCHEN	

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	
Instance on Room 215	Inspected
Lighting	
Instance on Room 215	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 215	Inspected
Pendant Mounted	
Instance on Room 215	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 215	Does not exist
Surface Mounted	
Instance on Room 215	Does not exist
Lighting Fixture - HID	
Instance on Room 215	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 215	Does not exist
Lighting Fixture - LED	
Instance on Room 215	Does not exist
Projection System	
Instance on Room 215	Does not exist
Raceway With Receptacles	
Instance on Room 215	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
LIGHTNING PROTECTION	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LOCKER ROOM	
Instance on Room 405A - Boys, Room 405B - Girls	Inspected
Alternative Use	Yes
Lighting	
Instance on Room 405A - Boys, Room 405B - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 405A - Boys, Room 405B - Girls	Inspected
Pendant Mounted	
Instance on Room 405A - Boys, Room 405B - Girls	Does not exist
Recessed Mounted	
Instance on Room 405A - Boys, Room 405B - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 405A - Boys, Room 405B - Girls	Does not exist
Lighting Fixture - HID	
Instance on Room 405A - Boys, Room 405B - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 405A - Boys, Room 405B - Girls	Does not exist
Lighting Fixture - LED	
Instance on Room 405A - Boys, Room 405B - Girls	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Telecom Room 313
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2014
Source of Installation Year	Documented
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Location/Instance	Room 108, Custodian's Office
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
SCIENCE LAB	
Instance on Room 520	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 524	Inspected
Power Panel?	Yes
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 520	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 524	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 520	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on Room 524	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 520	Inspected
Instance on Room 524	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 520	Inspected
Instance on Room 524	Inspected
Pendant Mounted	
Instance on Room 520	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 524	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
Surface Mounted	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
Lighting Fixture - HID	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 520	Inspected
Instance on Room 524	Does not exist
Pendant Mounted	
Instance on Room 520	Does not exist
Recessed Mounted	
Instance on Room 520	Does not exist
Surface Mounted	
Instance on Room 520	Inspected
Instance Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
Power Supply	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
Projection System	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
SCIENCE PREP ROOM	
Instance on Room 522	Inspected
Power Panel?	No
Alternative Use	No
Emergency Gas Shut-Off Valve	
Instance on Room 522	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 522	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Lighting	
Instance on Room 522	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 522	Inspected
Pendant Mounted	
Instance on Room 522	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 522	Does not exist
Surface Mounted	
Instance on Room 522	Does not exist
Lighting Fixture - HID	
Instance on Room 522	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 522	Does not exist
Lighting Fixture - LED	
Instance on Room 522	Does not exist
Power Supply	
Instance on Room 522	Does not exist
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Custodian's Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Model	Vista - 128BP
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Wall facing Webster Avenue
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Replacement Quantity	24
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Switch Gear Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MRPP
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Switch Gear Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
SERVICE SWITCH	
EquipmentId	Main Disconnect
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Switch Gear Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Fire Pump
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	8
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Mechanical Room R01A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Switch Gear Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2019-2020**

Electrical Inspection

X177

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A (Emergency Generator Switchboard)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Inspected
Cable System Exist?	Yes
Operational?	Yes
Main Equipment Rack	Does not exist