

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

School: **P.S./I.S. 218 - BRONX, 1220 GERARD AVENUE, BRONX, NY, 10452**

InspectionId	Inspection Type	Time In	Last Edited
1722	ELECTRICAL	2019-01-23 09:09AM	2019-06-27 03:52PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Security Lights Years: 2016, 1999 Systems: Raceways in Computer Lab 408, Auditorium - Local Sound System and Projection System Years: 2015 Systems: Auditorium - Theater Lighting System Years: 2010 Systems: Motor Starters Years: 2010, 2009, 1999 Systems: LAN, Telephone System Years: 2009 Systems: Gymnasium - Scoreboard Years: 2008 Systems: Gymnasium - LED Lighting, Intercom System - Elevator Years: 2016 Systems: All Other Electrical Systems and Components Years: 1999 Systems: Auditorium LED Lighting Years: 2019
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Heat Detector	Boiler Room	Louis O'Keefe	Handyman	No Photo Taken
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Duct Smoke Detector	Mechanical Room (AHU-1, AHU-2, AHU-4)	Louis O'Keefe	Handyman	No Photo Taken
No	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Elevator Recall	Elevator Device IDs: 2P10140, 2P10141	Louis O'Keefe	Handyman	No Photo Taken
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Area Smoke Detector	Penthouse Mechanical Room	Louis O'Keefe	Handyman	No Photo Taken
Yes	Fire Alarm System - Defective	N/A	Fire Alarm System	Main Entrance Lobby	Louis O'Keefe	Handyman	No Photo Taken

**Inspection**

Question	Response
----------	----------

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	
Instance on 2nd Floor	Inspected
<b>House Lighting</b>	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 2nd Floor	Inspected
<b>Dimming System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Lighting</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not exist
<b>Projection System</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>Theater Lighting System</b>	
Instance on 1st Floor - Students	Does not exist
Instance on 1st Floor - Staff	Does not exist
<b>CITY FIRE ALARM SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Inspected
<b>Lighting</b>	Inspected
Does a Chandelier Exist?	No

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Does not exist
<b>Surface Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - LED</b>	Does not exist
<b>COMPUTER LAB</b>	
Instance on Room 408	Inspected
Power Panel?	Yes
<b>Lighting</b>	
Instance on Room 408	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 408	Inspected
<b>Pendant Mounted</b>	
Instance on Room 408	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 408	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 408	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 408	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 408	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 408	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 408	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	
	Does not exist
<b>EMERGENCY GENERATOR SET</b>	
	Inspected
<b>Automatic Transfer Switch (ATS)</b>	
Instance	Room C01 - Mechanical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Firetrol

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
EquipmentId	Limited Service Controller with Fire Pump Power Transfer Switch
Capacity/Size Quantity	25
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	N/A
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Room C15 - Generator Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	24V Battery Float Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	Room C15 - Generator Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cummins Onan
EquipmentId	Emergency Generator
Capacity/Size Quantity	375

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Diesel</b>	
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	300
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	984
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
	Does not exist
<b>EMERGENCY LIGHTING</b>	
	Inspected
<b>Battery Pack</b>	Does not exist
<b>Non Battery Pack</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	
	Inspected
<b>Battery Pack</b>	Does not exist
<b>Non Battery Pack</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	
	Does not exist
<b>FIRE ALARM SYSTEM</b>	
	Inspected
<b>Area Smoke Detector</b>	Inspected
Condition	3- Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Penthouse Mechanical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	E470375
<b>Bell/Horn</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Does not exist
<b>Duct Smoke Detector</b>	
	Inspected
Condition	3- Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Mechanical Room C01 (AHU-1, AHU-2, AHU-4)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	E470375
<b>Elevator Recall</b>	
	Inspected
Condition	4- Between Fair and Poor
Deficiency	SYSTEM NOT OPERATIONAL
Deficiency Location/Instance	Elevator Device IDs: 2P10140, 2P10141
Deficiency Quantity	2
Quantity Uom	EACH

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Elevator Recall</b>	
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	E470375
<b>Fan Shutdown Control</b>	
Condition	Inspected
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	
Condition	Inspected
Instance	Room C01 - Mechanical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Ademco
EquipmentId	Fire Alarm Control Communicator
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Cutout Panel</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	DETECTOR NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	E470375
<b>Magnetic Door Holder/Contactor</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Main Panel</b>	
Condition	Inspected
<b>Bell At Panel</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	
Condition	Inspected
Instance	Main Entrance Lobby
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Simplex
Model	4100
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	64
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Diagram

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Installation Year	1999
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	E470375
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Manual Pull Station</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Room 109 - Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Simplex
Model	4100
EquipmentId	Purge Control Panel
Capacity/Size Quantity	64
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1999
Source of Installation Year	Documented



**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Sub-Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Deficiency	No deficiencies recorded
Instance	Penthouse and Room C01
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	Simplex
Model	N/A
EquipmentId	Transponder
Capacity/Size Quantity	5
Capacity/Size UOM	Zones
Source of Capacity/Size	Inspector Estimate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>GYMNASIUM</b>	
<b>Scoreboard</b>	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Does not exist
<b>INTERCOM SYSTEM</b>	
	Inspected
<b>Elevator</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Holding Area</b>	
	Does not exist
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>LAN</b>	
	Inspected
<b>Local Distribution Frame (I/LDF)</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIBRARY</b>	
Instance on Room 229	Inspected
<b>Lighting</b>	
Instance on Room 229	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 229	Inspected
<b>Pendant Mounted</b>	
Instance on Room 229	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Room 229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 229	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 229	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 229	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 229	Does not exist
<b>Projection System</b>	
Instance on Room 229	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not exist
<b>LOCKER ROOM</b>	
Instance on 1st Floor - Girls	Inaccessible
Instance on 1st Floor - Boys	Inspected
Alternative Use	Yes
<b>Lighting</b>	
Instance on 1st Floor - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Boys	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor - Boys	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor - Boys	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Boys	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Boys	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Boys	Does not exist
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Instance	Room 306
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC2100
Installation Year	1999
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Gymnasium, Room 407
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Rooms 302A, 402A	Inaccessible
<b>SECURITY</b>	Inspected
<b>Intrusion Alarm System</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	Room 109 - Custodian's Office
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1999
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Infrared Sensor</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Panic Switch</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Ultrasonic Sensor</b>	
	Does not exist
<b>IPDVS/CCTV System</b>	
	Does not exist
<b>Lighting - Security</b>	
Condition	1- Good
Replacement Quantity	35
Replacement Uom	EACH
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Service Switch No. 1, EDP
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Service Switch No. 2, MDB
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Service Switch No. 3, RPP
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	Fire Pump
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	
	Does not exist
<b>SWITCHBOARD</b>	
	Inspected
Number of Spares	4
<b>Air Circuit Breaker Type</b>	
	Does not exist
<b>Fused Disconnect Switch Type</b>	
	Inspected
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	EDP
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room C05 - Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDB
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	RPP
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Electrical Inspection**

**X235**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	
	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	
	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TOILET ROOM - STUDENT</b>	
	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not exist
<b>Recessed Mounted</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not exist
<b>Lighting Fixture - HID</b>	Does not exist
<b>Lighting Fixture - Incandescent</b>	Does not exist
<b>Lighting Fixture - LED</b>	Does not exist
<b>TRANSFORMER</b>	
	Does not exist
<b>TV SYSTEM</b>	
	Inspected
Cable System Exist?	Yes
Operational?	Yes
<b>Main Equipment Rack</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded