

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X444**

**School:** PRE-K CENTER @ 2510 MARION AVENUE - BRONX, 2510 MARION AVENUE, BRONX, NY, 10458

InspectionId	Inspection Type	Time In	Last Edited
2417	MECHANICAL	2019-02-13 02:43PM	2019-03-07 08:47PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Gas Fired Domestic Water Heater Years: 2019 Systems: Electric Domestic Water Heaters (2 of 3); Packaged / Rooftop Unit; Gas Service; Unit Heater/Cabinet Heaters; Boiler Fresh Air Louver/Damper; Boiler Emergency Stop Switch; F&T/Steam Drip Traps; Sprinkler System Years: 2017
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	3,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	1
MERs/Fan Rooms Locations	None
Are there any Emergency Stop Switches with Missing Hammers?	No components

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

**Inspection**

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
<b>Chilled Water System</b>	Does not exist
<b>Condenser Water Distribution: Piping, Pumps and Auxiliaries</b>	Does not exist
<b>Cooling Coil in Ductwork</b>	Does not exist
<b>Cooling Tower</b>	Does not exist
<b>Dry Cooler</b>	Does not exist
<b>DX Split System</b>	Does not exist
<b>Packaged / Rooftop Unit</b>	Inspected
Instance	Building Exterior - MDF Room Roof
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	N/A
Capacity/Size Quantity	15
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2017
Source of Installation Year	Documented
Source of Heating	Gas
Deficiency	No deficiencies recorded
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Piping</b>	Does not exist
<b>Return Fan</b>	Does not exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Does not exist
<b>COMPACTOR</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X444**

<b>Question</b>	<b>Response</b>
<b>COMPACTOR</b>	
Condition	1- Good
Deficiency	NOT IN USE
Deficiency Location/Instance	1st Floor - Compactor Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>CONVEYING</b>	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Inspected
<b>Roof Tank</b>	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Roof - Tank Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
<b>Supply Pump</b>	Does not exist
<b>Pressure Booster System</b>	Does not exist
<b>Water Service</b>	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Does not exist
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lochinvar
EquipmentId	N/A
Capacity/Size Quantity	120
Capacity/Size UOM	MBH Input

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X444**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Hot Water System</b>	
<b>Gas Fired Domestic Water Heater</b>	
Capacity/Size 2 Quantity	116
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	
	Does not exist
<b>Domestic Water Distribution Piping</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
	Inspected
<b>Interior Storm Piping</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Sewage Ejector Pump</b>	
	Does not exist
<b>Sewage/Waste/Vent Piping</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Sump Pump</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	
	Does not exist
<b>Enclosed IDF Room</b>	
Instance on Stair "C" Bulkhead	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Stair "C" Bulkhead	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>FIXTURES</b>	
	Inspected
<b>Staff And Other</b>	
	Inspected
<b>Janitor Sink</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
<b>Toilet</b>	
Condition	Inspected
Deficiency	1- Good
	No deficiencies recorded
<b>Urinal</b>	
	Does not exist
<b>Student</b>	
	Inspected
<b>Drinking Fountain</b>	
Condition	Inspected
Deficiency	1- Good
	No deficiencies recorded
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	1- Good
	No deficiencies recorded
<b>Locker Room Shower</b>	
	Does not exist
<b>Sink And Fountain Combo Unit</b>	
	Does not exist
<b>Toilet</b>	
	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X444**

<b>Question</b>	<b>Response</b>
<b>FIXTURES</b>	
<b>Student</b>	
<b>Toilet</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>CO/Gas Leak Detection</b>	Inspected
Instance	Gas Rig Room C02A, Gas Meter Room C03
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Gas Distribution Piping</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Gas Meter Room Vent</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Gas Pressure Booster</b>	Inspected
Instance	Gas Meter Room C03
Instance Condition	1- Good
Instance Quantity	2
Instance Quantity Uom	EACH
Manufacturer	
EquipmentId	N/A
Capacity/Size Quantity	1
Capacity/Size UOM	HP
Source of Capacity/Size	Documented
Installation Year	2017
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>HEATING</b>	Inspected
<b>Heating Coil In Ductwork</b>	Does not exist
<b>Hydronic Heating</b>	Does not exist
<b>Radiator/Convactor/Fin Tube</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>MER Steam and Condensate Piping</b>	Does not exist
<b>Steam Condensate Return Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X444**

Question	Response
<b>HEATING</b>	
<b>Steam Heating</b>	
<b>Steam Condensate Return Pumping System</b>	Does not exist
<b>Steam Piping</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Room 405
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Terminal Unit Thermostatic Trap</b>	Does not exist
<b>Steam supplied by External Sources</b>	Does not exist
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	1- Good
Deficiency	DEFECTIVE
Deficiency Location/Instance	Multi-purpose Room; Rooms 106F, 106H
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>HEATING PLANT</b>	
Replacement Quantity	2,599
Replacement Uom	MBH NET
Instance on Basement	Inspected
Burner Type	Oil
Heating Plant Oil Number	4
<b>Boiler Auxiliaries</b>	
Instance on Basement	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Basement	Does not exist
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Basement	Does not exist
<b>Boiler Flue Exhaust</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Basement	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

**Mechanical Inspection**

**X444**

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Room Steam And Condensate Piping</b>	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Safety Valve</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler System</b>	
Instance on Basement	Inspected
<b>Coal-fired Boiler</b>	
Instance on Basement	Does not exist
<b>Hot Water Boiler</b>	
Instance on Basement	Does not exist
<b>Modular Boiler</b>	
Instance on Basement	Does not exist
<b>Steam Boiler</b>	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	2,599
Instance Quantity Uom	MBH NET
Manufacturer	A. L. Eastmond & Sons Inc.
EquipmentId	87782-04
Capacity/Size Quantity	2599
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1985
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fuel System</b>	
Instance on Basement	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Burner/Burner Control Panel</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Fuel Oil Storage/Supply System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Basement	Does not exist
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>CO Detector</b>	
Instance on 1st Floor	Not required
<b>Gas System</b>	
Instance on 1st Floor	Does not exist
<b>Grease Trap</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2018-2019**

***Mechanical Inspection***

**X444**

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	
<b>Grease Trap</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on 1st Floor	Does not exist
<b>Hood Exhaust Ductwork</b>	
Instance on 1st Floor	Does not exist
<b>Hood Exhaust Fan</b>	
Instance on 1st Floor	Does not exist
<b>Hood Fire Suppression System</b>	
Instance on 1st Floor	Does not exist
<b>Hot Water Temperature Booster</b>	
Instance on 1st Floor	Does not exist
<b>Kitchen Sink</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>MDF Room</b>	
Instance on Building Exterior - MDF Room	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Building Exterior - MDF Room	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	
	Does not exist
<b>SCIENCE LAB</b>	
	Does not exist
<b>SCIENCE PREP ROOM</b>	
	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	
	Does not exist
<b>Fire Booster Pump Assembly</b>	
	Does not exist
<b>Roof Tank</b>	
	Does not exist
<b>Siamese Connection</b>	
	Does not exist
<b>Sprinkler Head</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	
	Does not exist
<b>Water Gong</b>	
	Does not exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	
	Does not exist
<b>SWIMMING POOL</b>	
	Does not exist
<b>VENTILATION</b>	
	Inspected
<b>Exhaust Fan</b>	
	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	
	Does not exist
<b>Metal Ductwork</b>	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	
	Does not exist

NYC Department of Education  
Building Condition Assessment Survey 2018-2019

*Mechanical Inspection*

X444

---

Question	Response
<b>VENTILATION</b>	
Unit Ventilator	Does not exist

---