

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

School: ADLAI E. STEVENSON EDUCATIONAL CAMPUS - X, 1980 LAFAYETTE AVENUE, BRONX, NY, 10473

| InspectionId | Inspection Type | Time In | Last Edited |
|--------------|-----------------|--------------------|--------------------|
| 2006 | ELECTRICAL | 2019-01-28 09:58AM | 2019-02-05 11:18AM |

Asset Data

| Question | Answer |
|---|--|
| Have any Systems/Major Building Components been upgraded? | Systems: Most Security Lights, Intrusion Alarm System (Remote Annunciator), Boys Locker Room, Girls Locker Room (Pendant and Surface Fluorescent Lighting) Years: 2017 Systems: Auditorium (Local Sound System, Projection System, Theater Lighting System, LED Lighting Retrofitted), Gymnasiums (LED Lighting, Local Sound System), West Gymnasium (Scoreboard), Telephone System Years: 2016 Systems: Fire Alarm System (Main Panel) Years: 2012 Systems: Library, Science Lab - Rooms (265, 267), Auditorium Projection System Years: 2010 Systems: Science Lab - Rooms (165, 169, 171, 271), Science Demo Room 383, Science Prep Rooms (167, 269) Years: 2008 Systems: IPDVS/CCTV System Years: 2018 Systems: Public Address System, Students Cafeteria (Lighting, Local Sound System), Computer Lab - Room 183 Years: 2007 Systems: Intrusion Alarm System (Central Control Panel) Years: 2005 Systems: Partial Molded Case Circuit Breaker Panel Board Years: 2000, 2008, 2015, 2016 Systems: Interior Fluorescent Lighting, Kitchen (Fluorescent Lighting Retrofitted) Years: 1995 Systems: Intrusion Alarm System Years: 1993 Systems: Fire Alarm System Years: 1991 Type of Service Does Interactive Whiteboard (IWB) Exist? Water Penetration In Electrical Room? |
| | Below Ground Yes No |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | Yes |
| Are dedicated intercoms available in all of these spaces for use during a fire? | Yes |
| Are all dedicated intercoms operational? | Yes |

Priority Condition

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
|------------------|--|-----------------------|-------------------------------|-------------------------------------|--------------------|-----------------|----------------|
| Yes | Fire Alarm System - Components Not Operational | N/A | Fire Alarm System - Strobe | Staff Toilet Room 206, Exit 22 - 23 | Vincent Agovino | Fireman | No Photo Taken |
| Yes | Fire Alarm System - Components Not Operational | N/A | Fire Alarm System - Bell/Horn | Auditorium | Vincent Agovino | Fireman | No Photo Taken |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| | | | | | | | |
|-----|--|-----|---|------------------------------|-----------------|---------|----------------|
| No | Intercom - Not Operational | N/A | Intercom System - Elevator | Elevator - Device ID: 2P4202 | Vincent Agovino | Fireman | No Photo Taken |
| Yes | Fire Alarm System - Components Not Operational | N/A | Fire Alarm System - Manual Pull Station | Auditorium - By Stage | Vincent Agovino | Fireman | No Photo Taken |

Inspection

| Question | Response |
|--|-------------------------------------|
| Electrical | |
| ATHLETIC FIELD | Does not exist |
| AUDITORIUM | |
| Instance on 1st Floor | Inspected |
| House Lighting | |
| Instance on 1st Floor | Inspected |
| Does a Chandelier Exist? | No |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | |
| Instance on 1st Floor | Does not exist |
| Surface Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 1st Floor | Does not exist |
| Local Sound System | |
| Instance on 1st Floor | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|----------------------------------|
| AUDITORIUM | |
| Local Sound System | |
| Instance Condition | 1- Good |
| Installation Year | 2016 |
| Source of Installation Year | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Is the projector on a cart or installed on the ceiling? | Ceiling |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on 1st Floor | Inspected |
| Dimming System | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| AUXILIARY SIGNAL/BELL SYSTEM | |
| Condition | Inspected |
| Deficiency | 3- Fair |
| Deficiency Location/Instance | DOOR PUSH BUTTON NOT OPERATIONAL |
| Deficiency Quantity | Outside By Kitchen |
| Quantity Uom | 1 |
| Potential Action | EACH |
| Urgency of Action | MAINTENANCE |
| Purpose of Action | PRIORITY 3 |
| Violations | LEVEL 2 |
| | No violations recorded |
| CAFETERIA | |
| Instance on Room 160 | Inspected |
| Instance on Room 170 | Inspected |
| Instance on Room 180 | Inspected |
| Lighting | |
| Instance on Room 160 | Inspected |
| Instance on Room 170 | Inspected |
| Instance on Room 180 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 160 | Inspected |
| Instance on Room 170 | Inspected |
| Instance on Room 180 | Inspected |
| Pendant Mounted | |
| Instance on Room 160 | Does not exist |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Does not exist |
| Recessed Mounted | |
| Instance on Room 160 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Inspected |
| Instance Condition | 2- Between Good and Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|--------------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 160 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 170 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 180 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room 160 | Does not exist |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 160 | Does not exist |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 160 | Does not exist |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Does not exist |
| Local Sound System | |
| Instance on Room 160 | Inspected |
| Instance Condition | 3- Fair |
| Installation Year | 2007 |
| Source of Installation Year | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Inspected |
| Instance Condition | 3- Fair |
| Installation Year | 2007 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on Room 160 | Does not exist |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Does not exist |
| Theater Lighting System | |
| Instance on Room 160 | Does not exist |
| Instance on Room 170 | Does not exist |
| Instance on Room 180 | Does not exist |
| CITY FIRE ALARM SYSTEM | |
| Condition | Inspected |
| Deficiency | 5- Poor |
| Deficiency Location/Instance | NOT OPERATIONAL |
| Deficiency Quantity | 1st Floor Corridor By Room 119 |
| Quantity Uom | 1 |
| Potential Action | EACH |
| | REPLACE |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|-------------------------------------|
| CITY FIRE ALARM SYSTEM | |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected |
| Lighting | Inspected |
| Does a Chandelier Exist? | No |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 10 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 37 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Recessed Mounted | Does not exist |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 44 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|--------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - LED | Does not exist |
| COMPUTER LAB | |
| Instance on Room 183 | Inspected |
| Power Panel? | No |
| Instance on Room 201 | Inspected |
| Power Panel? | No |
| Instance on Room 446 | Inspected |
| Power Panel? | Yes |
| Lighting | |
| Instance on Room 183 | Inspected |
| Instance on Room 201 | Inspected |
| Instance on Room 446 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 183 | Inspected |
| Instance on Room 201 | Inspected |
| Instance on Room 446 | Inspected |
| Pendant Mounted | |
| Instance on Room 183 | Does not exist |
| Instance on Room 201 | Does not exist |
| Instance on Room 446 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 183 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 201 | Does not exist |
| Instance on Room 446 | Does not exist |
| Surface Mounted | |
| Instance on Room 183 | Does not exist |
| Instance on Room 201 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 446 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 183 | Does not exist |
| Instance on Room 201 | Does not exist |
| Instance on Room 446 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 183 | Does not exist |
| Instance on Room 201 | Does not exist |
| Instance on Room 446 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 183 | Does not exist |
| Instance on Room 201 | Does not exist |
| Instance on Room 446 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 183 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 201 | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|---------------------------|
| COMPUTER LAB | |
| Raceway With Receptacles | |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 446 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | |
| Does not exist | |
| EMERGENCY GENERATOR SET | |
| Inspected | |
| Automatic Transfer Switch (ATS) | |
| Inspected | |
| Instance | Electrical Room B22 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Cummins Onan |
| EquipmentId | N/A |
| Capacity/Size Quantity | 400 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room B22 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Electrical Room B22 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Cummins Onan |
| EquipmentId | N/A |
| Capacity/Size Quantity | 200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room B22 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Battery Charger | |
| Inspected | |
| Instance | Basement - Generator Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Cummins Onan |
| EquipmentId | Battery Charger |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|--------------------------------------|
| EMERGENCY GENERATOR SET | |
| Battery Charger | |
| Capacity/Size Quantity | 10 |
| Capacity/Size UOM | AmpsDC |
| Capacity/Size 2 Quantity | 12 |
| Capacity/Size 2 UOM | VDC |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Basement - Generator Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Diesel | Does not exist |
| Natural Gas | Inspected |
| Instance | Basement - Generator Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Cummins Onan |
| EquipmentId | Emergency Generator |
| Capacity/Size Quantity | 106 |
| Capacity/Size UOM | kVA |
| Capacity/Size 2 Quantity | 85 |
| Capacity/Size 2 UOM | kW |
| Capacity/Size 3 Quantity | 295 |
| Capacity/Size 3 UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Basement - Generator Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | LESS THAN 20% SPARE CIRCUIT BREAKERS |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 3- Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | 1st Floor Corridor By Room 141 |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|---------------------------|
| EMERGENCY LIGHTING | |
| Battery Pack | |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | |
| Condition | Inspected |
| Deficiency | 3- Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | |
| Battery Pack | |
| Condition | Inspected |
| Deficiency | 3- Fair |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | |
| Condition | Inspected |
| Condition | 3- Fair |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Room 309, 409 |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| EXIT/EMERGENCY LIGHT | |
| Does not exist | |
| FIRE ALARM SYSTEM | |
| Inspected | |
| Area Smoke Detector | |
| Condition | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Bell/Horn | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | BELL/HORN NOT OPERATIONAL |
| Deficiency Location/Instance | Auditorium |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| CO Detector | |
| Does not exist | |
| Duct Smoke Detector | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Elevator Recall | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fan Shutdown Control | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Digital Communicator | |
| Does not exist | |
| Fused Cutout Panel | |
| Inspected | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|------------------------------|
| FIRE ALARM SYSTEM | |
| Heat Detector | Does not exist |
| Magnetic Door Holder/Contactor | Does not exist |
| Main Panel | Inspected |
| Bell At Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Notifier |
| Model | N/A |
| EquipmentId | N/A |
| Capacity/Size Quantity | 24 |
| Capacity/Size UOM | Zones |
| Capacity/Size 2 Quantity | 1 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Diagram |
| Installation Year | 2012 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Manual Pull Station | Inspected |
| Condition | 3- Fair |
| Deficiency | PULL STATION NOT OPERATIONAL |
| Deficiency Location/Instance | Auditorium - By Stage |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 5- Poor |
| Deficiency | PRINTER NOT OPERATIONAL |
| Deficiency Location/Instance | Custodian's Office |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Strobe | Inspected |
| Condition | 3- Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|--|
| FIRE ALARM SYSTEM | |
| Strobe | |
| Deficiency | STROBE NOT OPERATIONAL |
| Deficiency Location/Instance | Staff Toilet Room 206, 1st Floor By Exit 22-23 |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Sub-Panel | Does not exist |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | |
| Instance on 2nd Floor - East | Inspected |
| Instance on 2nd Floor - West | Inspected |
| Lighting | |
| Instance on 2nd Floor - East | Inspected |
| Instance on 2nd Floor - West | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Does not exist |
| Lighting Fixture - HID | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Does not exist |
| Lighting Fixture - LED | |
| Instance on 2nd Floor - East | Inspected |
| Instance on 2nd Floor - West | Inspected |
| Pendant Mounted | |
| Instance on 2nd Floor - East | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Instance on 2nd Floor - West | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Does not exist |
| Surface Mounted | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Does not exist |
| Local Sound System | |
| Instance on 2nd Floor - East | Inspected |
| Instance Condition | 1- Good |
| Installation Year | 2016 |
| Source of Installation Year | Custodial Staff |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|----------------------------------|
| GYMNASIUM | |
| Local Sound System | |
| Instance on 2nd Floor - West | Inspected |
| Instance Condition | 1- Good |
| Installation Year | 2016 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Does not exist |
| Scoreboard | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on 2nd Floor - East | Does not exist |
| Instance on 2nd Floor - West | Does not exist |
| INTERCOM SYSTEM | |
| Elevator | |
| Condition | Inspected |
| Deficiency | 4- Between Fair and Poor |
| Deficiency Location/Instance | INTERCOM CABINET NOT OPERATIONAL |
| Deficiency Quantity | Elevator - Device ID: 2P4202 |
| Quantity Uom | 1 |
| Potential Action | EACH |
| Urgency of Action | REPLACE |
| Purpose of Action | PRIORITY 5 |
| Violations | LEVEL 6 |
| | No violations recorded |
| Holding Area | |
| | Does not exist |
| KITCHEN | |
| Instance on 1st Floor | Inspected |
| Lighting | |
| Instance on 1st Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 1st Floor | Inspected |
| Pendant Mounted | |
| Instance on 1st Floor | Does not exist |
| Recessed Mounted | |
| Instance on 1st Floor | Does not exist |
| Surface Mounted | |
| Instance on 1st Floor | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 1st Floor | Does not exist |
| Lighting Fixture - LED | |
| Instance on 1st Floor | Does not exist |
| LAN | |
| | Inspected |
| Local Distribution Frame (I/LDF) | |
| Condition | Inspected |
| Deficiency | 3- Fair |
| | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|--------------------------|
| LAN | |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| LIBRARY | |
| Instance on Room 209 | Inspected |
| Lighting | |
| Instance on Room 209 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 209 | Inspected |
| Pendant Mounted | |
| Instance on Room 209 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | |
| Instance on Room 209 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 209 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Room 209 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 209 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 209 | Does not exist |
| Projection System | |
| Instance on Room 209 | Does not exist |
| Raceway With Receptacles | |
| Instance on Room 209 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | |
| | Does not exist |
| LOCKER ROOM | |
| Instance on 2nd Floor - Boys | Inspected |
| Alternative Use | No |
| Instance on 2nd Floor - Girls | Inspected |
| Alternative Use | No |
| Lighting | |
| Instance on 2nd Floor - Boys | Inspected |
| Instance on 2nd Floor - Girls | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on 2nd Floor - Boys | Inspected |
| Instance on 2nd Floor - Girls | Inspected |
| Pendant Mounted | |
| Instance on 2nd Floor - Boys | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Instance on 2nd Floor - Girls | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|-------------------------------------|
| LOCKER ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Recessed Mounted | |
| Instance on 2nd Floor - Boys | Does not exist |
| Instance on 2nd Floor - Girls | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on 2nd Floor - Boys | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Instance on 2nd Floor - Girls | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on 2nd Floor - Boys | Does not exist |
| Instance on 2nd Floor - Girls | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on 2nd Floor - Boys | Does not exist |
| Instance on 2nd Floor - Girls | Does not exist |
| Lighting Fixture - LED | |
| Instance on 2nd Floor - Boys | Does not exist |
| Instance on 2nd Floor - Girls | Does not exist |
| MOTOR CONTROL CENTER | |
| Instance | Inspected |
| Instance Condition | Boiler Room |
| Instance Quantity | 3- Fair |
| Instance Quantity Uom | 1 |
| Manufacturer | EACH |
| EquipmentId | N/A |
| Capacity/Size Quantity | N/A |
| Capacity/Size UOM | 200 |
| Capacity/Size 2 Quantity | Amps |
| Capacity/Size 2 UOM | 1 |
| Source of Capacity/Size | Section(s) |
| Installation Year | Inspector Estimate |
| Source of Installation Year | 1970 |
| Deficiency | Documented |
| Deficiency Quantity | MCC INDICATOR LIGHT NOT OPERATIONAL |
| Quantity Uom | 10 |
| Potential Action | EACH |
| Urgency of Action | MAINTENANCE |
| Purpose of Action | PRIORITY 3 |
| Violations | LEVEL 2 |
| Deficiency | No violations recorded |
| Deficiency Location/Instance | BEYOND USEFUL LIFE |
| Deficiency Quantity | Boiler Room |
| Quantity Uom | 1 |
| Potential Action | EACH |
| Urgency of Action | REPLACE |
| Purpose of Action | PRIORITY 1 |
| Violations | LEVEL 2 |
| Instance | No violations recorded |
| Instance Condition | Basement Mechanical Room |
| Instance Condition | 3- Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|--|
| MOTOR CONTROL CENTER | |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | N/A |
| EquipmentId | N/A |
| Capacity/Size Quantity | 100 |
| Capacity/Size UOM | Amps |
| Capacity/Size 2 Quantity | 1 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Inspector Estimate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Basement Mechanical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| MULTIPURPOSE ROOM | Does not exist |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room B22, Rooms 142, 181 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3- Fair |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | Kitchen, West Gymnasium Mechanical Room, 4th Floor Corridor By Rooms 446, 466 |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|---|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Violations | No violations recorded |
| Deficiency | PANEL BOARD DIRECTORY MISSING OR REQUIRES UPDATING |
| Deficiency Location/Instance | Electrical Room, East Gymnasium Mechanical Room, 2nd Floor Corridor By Room 212, 4th Floor Corridor By Room 496 |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | PANEL BOARD DOOR LOCK IS MISSING |
| Deficiency Location/Instance | Electrical Room, Room 181 |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | PANEL BOARD COVER IS MISSING |
| Deficiency Location/Instance | Room 142 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Corridors, Kitchen, Auditorium Mechanical Room, East Gymnasium Mechanical Room, Boiler Room, Auditorium, Basement Mechanical Room, Rooms (142, 499, 181,361, 365, 461, 467) |
| Deficiency Quantity | 56 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| PUBLIC ADDRESS SYSTEM | |
| Instance | Inspected |
| Instance Condition | General Office - Room 103 |
| Instance Quantity | 2- Between Good and Fair |
| Instance Quantity Uom | 1 |
| Model | EACH |
| Installation Year | Dukane 250 |
| Source of Installation Year | 2007 |
| Deficiency | Clock NOT OPERATIONAL |
| Deficiency Location/Instance | Custodial Staff |
| Deficiency Quantity | CLOCK NOT OPERATIONAL |
| Quantity Uom | Classrooms and Corridors |
| Potential Action | 30 |
| Urgency of Action | EACH |
| Purpose of Action | REPLACE |
| Violations | PRIORITY 3 |
| | LEVEL 2 |
| | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|-------------------------------------|--------------------------|
| SCIENCE DEMO ROOM | |
| Instance on Rooms 462, 466 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance on Room 464 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance on Room 492 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Instance on Room 494 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance on Room 451 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance on Rooms 392, 394 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance on Rooms 351, 362, 364 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Instance on Room 366 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance on Room 383 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Emergency Gas Shut-Off Valve | |
| Instance on Rooms 462, 466 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 464 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 492 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 494 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 451 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 392, 394 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 351, 362, 364 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 366 | Inspected |
| Instance Condition | 3- Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---------------------------------------|--------------------------|
| SCIENCE DEMO ROOM | |
| Emergency Gas Shut-Off Valve | |
| Deficiency | No deficiencies recorded |
| Instance on Room 383 | Does not exist |
| Emergency Shut-Off Power | |
| Instance on Rooms 462, 466 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 464 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 492 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 494 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 451 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 392, 394 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 351, 362, 364 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 366 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 383 | Does not exist |
| Lighting | |
| Instance on Rooms 462, 466 | Inspected |
| Instance on Room 464 | Inspected |
| Instance on Room 492 | Inspected |
| Instance on Room 494 | Inspected |
| Instance on Room 451 | Inspected |
| Instance on Rooms 392, 394 | Inspected |
| Instance on Rooms 351, 362, 364 | Inspected |
| Instance on Room 366 | Inspected |
| Instance on Room 383 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Rooms 462, 466 | Inspected |
| Instance on Room 464 | Inspected |
| Instance on Room 492 | Inspected |
| Instance on Room 494 | Inspected |
| Instance on Room 451 | Inspected |
| Instance on Rooms 392, 394 | Inspected |
| Instance on Rooms 351, 362, 364 | Inspected |
| Instance on Room 366 | Inspected |
| Instance on Room 383 | Inspected |
| Pendant Mounted | |
| Instance on Rooms 462, 466 | Inspected |
| Instance Condition | 3- Fair |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---------------------------------------|--------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Deficiency | No deficiencies recorded |
| Instance on Room 464 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 492 | Does not exist |
| Instance on Room 494 | Does not exist |
| Instance on Room 451 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 392, 394 | Does not exist |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Instance on Room 383 | Does not exist |
| Recessed Mounted | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 492 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 494 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 392, 394 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Instance on Room 383 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 492 | Does not exist |
| Instance on Room 494 | Does not exist |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 392, 394 | Does not exist |
| Instance on Rooms 351, 362, 364 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 366 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 383 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 492 | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|-------------------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Lighting Fixture - HID | |
| Instance on Room 494 | Does not exist |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 392, 394 | Does not exist |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Instance on Room 383 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Rooms 462, 466 | Inspected |
| Instance on Room 464 | Inspected |
| Instance on Room 492 | Does not exist |
| Instance on Room 494 | Does not exist |
| Instance on Room 451 | Inspected |
| Instance on Rooms 392, 394 | Does not exist |
| Instance on Rooms 351, 362, 364 | Inspected |
| Instance on Room 366 | Inspected |
| Instance on Room 383 | Does not exist |
| Pendant Mounted | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Recessed Mounted | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Surface Mounted | |
| Instance on Rooms 462, 466 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Room 464 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Room 451 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 2 |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|-------------------------------------|
| SCIENCE DEMO ROOM | |
| Lighting | |
| Lighting Fixture - Incandescent | |
| Surface Mounted | |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Rooms 351, 362, 364 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Room 366 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Lighting Fixture - LED | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 492 | Does not exist |
| Instance on Room 494 | Does not exist |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 392, 394 | Does not exist |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Instance on Room 383 | Does not exist |
| Power Supply | |
| Instance on Rooms 462, 466 | Inspected |
| Instance on Room 464 | Inspected |
| Instance on Room 492 | Inspected |
| Instance on Room 494 | Inspected |
| Instance on Room 451 | Inspected |
| Instance on Rooms 392, 394 | Inspected |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Instance on Room 383 | Does not exist |
| Instructor Unit | |
| Instance on Rooms 462, 466 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 464 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---------------------------------|--------------------------|
| SCIENCE DEMO ROOM | |
| Power Supply | |
| Instructor Unit | |
| Instance on Room 492 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 494 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 451 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 392, 394 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Meter Demonstration Unit | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 492 | Does not exist |
| Instance on Room 494 | Does not exist |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 392, 394 | Does not exist |
| Projection System | |
| Instance on Rooms 462, 466 | Does not exist |
| Instance on Room 464 | Does not exist |
| Instance on Room 492 | Does not exist |
| Instance on Room 494 | Does not exist |
| Instance on Room 451 | Does not exist |
| Instance on Rooms 392, 394 | Does not exist |
| Instance on Rooms 351, 362, 364 | Does not exist |
| Instance on Room 366 | Does not exist |
| Instance on Room 383 | Does not exist |
| SCIENCE LAB | |
| Instance on Room 467 | Inspected |
| Power Panel? | Yes |
| Alternative Use | No |
| Instance on Room 461 | Inspected |
| Power Panel? | Yes |
| Alternative Use | No |
| Instance on Rooms 265, 267 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Instance on Rooms 361, 365 | Inspected |
| Power Panel? | Yes |
| Alternative Use | No |
| Instance on Rooms 271, 169 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Instance on Room 171 | Inspected |
| Power Panel? | No |
| Alternative Use | Yes |
| Instance on Room 165 | Inspected |
| Power Panel? | No |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|-------------------------------------|--------------------------|
| SCIENCE LAB | |
| Alternative Use | No |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 467 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 461 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 265, 267 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 361, 365 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 271, 169 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 171 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 165 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Room 467 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 461 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 265, 267 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 361, 365 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 271, 169 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 171 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 165 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting | |
| Instance on Room 467 | Inspected |
| Instance on Room 461 | Inspected |
| Instance on Rooms 265, 267 | Inspected |
| Instance on Rooms 361, 365 | Inspected |
| Instance on Rooms 271, 169 | Inspected |
| Instance on Room 171 | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---------------------------------------|--------------------------|
| SCIENCE LAB | |
| Lighting | |
| Instance on Room 165 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 467 | Inspected |
| Instance on Room 461 | Inspected |
| Instance on Rooms 265, 267 | Inspected |
| Instance on Rooms 361, 365 | Inspected |
| Instance on Rooms 271, 169 | Inspected |
| Instance on Room 171 | Inspected |
| Instance on Room 165 | Inspected |
| Pendant Mounted | |
| Instance on Room 467 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 461 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 265, 267 | Does not exist |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Does not exist |
| Instance on Room 171 | Does not exist |
| Instance on Room 165 | Does not exist |
| Recessed Mounted | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 265, 267 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 171 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 165 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 265, 267 | Does not exist |
| Instance on Rooms 361, 365 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 271, 169 | Does not exist |
| Instance on Room 171 | Does not exist |
| Instance on Room 165 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 265, 267 | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|-------------------------------------|
| SCIENCE LAB | |
| Lighting | |
| Lighting Fixture - HID | |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Does not exist |
| Instance on Room 171 | Does not exist |
| Instance on Room 165 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 467 | Inspected |
| Instance on Room 461 | Inspected |
| Instance on Rooms 265, 267 | Does not exist |
| Instance on Rooms 361, 365 | Inspected |
| Instance on Rooms 271, 169 | Inspected |
| Instance on Room 171 | Inspected |
| Instance on Room 165 | Does not exist |
| Pendant Mounted | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Does not exist |
| Instance on Room 171 | Does not exist |
| Recessed Mounted | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Does not exist |
| Instance on Room 171 | Does not exist |
| Surface Mounted | |
| Instance on Room 467 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Room 461 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance on Rooms 361, 365 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|--------------------------|
| SCIENCE LAB | |
| Lighting | |
| Lighting Fixture - Incandescent | |
| Surface Mounted | |
| Instance on Rooms 271, 169 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 171 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - LED | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 265, 267 | Does not exist |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Does not exist |
| Instance on Room 171 | Does not exist |
| Instance on Room 165 | Does not exist |
| Power Supply | |
| Instance on Room 467 | Inspected |
| Instance on Room 461 | Inspected |
| Instance on Rooms 265, 267 | Inspected |
| Instance on Rooms 361, 365 | Inspected |
| Instance on Rooms 271, 169 | Inspected |
| Instance on Room 171 | Does not exist |
| Instance on Room 165 | Inspected |
| Instructor Unit | |
| Instance on Room 467 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 461 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 265, 267 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 361, 365 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 271, 169 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 165 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Meter Demonstration Unit | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 265, 267 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|-------------------------------------|--------------------------|
| SCIENCE LAB | |
| Power Supply | |
| Meter Demonstration Unit | |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 165 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Student Unit | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 265, 267 | Does not exist |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Does not exist |
| Instance on Room 165 | Does not exist |
| Projection System | |
| Instance on Room 467 | Does not exist |
| Instance on Room 461 | Does not exist |
| Instance on Rooms 265, 267 | Does not exist |
| Instance on Rooms 361, 365 | Does not exist |
| Instance on Rooms 271, 169 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 171 | Does not exist |
| Instance on Room 165 | Does not exist |
| SCIENCE PREP ROOM | |
| Instance on Room 465 | Inspected |
| Power Panel? | Yes |
| Alternative Use | No |
| Instance on Room 463 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Instance on Room 363 | Inspected |
| Power Panel? | Yes |
| Alternative Use | Yes |
| Instance on Rooms 269, 167 | Inspected |
| Power Panel? | No |
| Alternative Use | No |
| Emergency Gas Shut-Off Valve | |
| Instance on Room 465 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 463 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 363 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 269, 167 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Emergency Shut-Off Power | |
| Instance on Room 465 | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|--------------------------|
| SCIENCE PREP ROOM | |
| Emergency Shut-Off Power | |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 463 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 363 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 269, 167 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting | |
| Instance on Room 465 | Inspected |
| Instance on Room 463 | Inspected |
| Instance on Room 363 | Inspected |
| Instance on Rooms 269, 167 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 465 | Inspected |
| Instance on Room 463 | Inspected |
| Instance on Room 363 | Inspected |
| Instance on Rooms 269, 167 | Inspected |
| Pendant Mounted | |
| Instance on Room 465 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 463 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 363 | Does not exist |
| Instance on Rooms 269, 167 | Does not exist |
| Recessed Mounted | |
| Instance on Room 465 | Does not exist |
| Instance on Room 463 | Does not exist |
| Instance on Room 363 | Does not exist |
| Instance on Rooms 269, 167 | Inspected |
| Instance Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | |
| Instance on Room 465 | Does not exist |
| Instance on Room 463 | Does not exist |
| Instance on Room 363 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Rooms 269, 167 | Does not exist |
| Lighting Fixture - HID | |
| Instance on Room 465 | Does not exist |
| Instance on Room 463 | Does not exist |
| Instance on Room 363 | Does not exist |
| Instance on Rooms 269, 167 | Does not exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 465 | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|--|-------------------------------|
| SCIENCE PREP ROOM | |
| Lighting | |
| Lighting Fixture - Incandescent | |
| Instance on Room 463 | Does not exist |
| Instance on Room 363 | Does not exist |
| Instance on Rooms 269, 167 | Does not exist |
| Lighting Fixture - LED | |
| Instance on Room 463 | Does not exist |
| Instance on Room 463 | Does not exist |
| Instance on Room 363 | Does not exist |
| Instance on Rooms 269, 167 | Does not exist |
| Power Supply | |
| Instance on Room 463 | Inspected |
| Instance on Room 463 | Inspected |
| Instance on Room 363 | Inspected |
| Instance on Rooms 269, 167 | Does not exist |
| Instructor Unit | |
| Instance on Room 463 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 463 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 363 | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| SECURITY | |
| | Inspected |
| Intrusion Alarm System | |
| | Inspected |
| Central Control Panel | |
| Instance | Custodian's Office - Room 109 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista - 128B |
| Installation Year | 2005 |
| Source of Installation Year | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | |
| | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | |
| | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | |
| | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | |
| | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Ultrasonic Sensor | |
| | Does not exist |
| IPDVS/CCTV System | |
| | Inspected |
| Condition | 1- Good |
| Installation Year | 2018 |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|------------------------------|-------------------------------------|
| SECURITY | |
| IPDVS/CCTV System | |
| Source of Installation Year | Custodial Staff |
| Deficiency | No deficiencies recorded |
| Lighting - Security | |
| Condition | Inspected |
| Replacement Quantity | 2- Between Good and Fair |
| Replacement Uom | 72 |
| Deficiency | EACH |
| Deficiency Location/Instance | LIGHTING FIXTURE BEYOND USEFUL LIFE |
| Deficiency Quantity | Outside by Main Entrance |
| Quantity Uom | 27 |
| Potential Action | EACH |
| Urgency of Action | REPLACE-UPGRADE |
| Purpose of Action | PRIORITY 1 |
| Violations | LEVEL 3 |
| | No violations recorded |
| SERVICE SWITCH | |
| Instance | Inspected |
| Instance Condition | Electrical Room B22 |
| Instance Quantity | 3- Fair |
| Instance Quantity Uom | 1 |
| Manufacturer | EACH |
| EquipmentId | Royal Switchboard Co. |
| Capacity/Size Quantity | Main Switch MDP#1 Fuse 3500A |
| Capacity/Size UOM | 3500 |
| Source of Capacity/Size | Amps |
| Installation Year | Fuse Size |
| Source of Installation Year | 1970 |
| Deficiency | Documented |
| Deficiency Location/Instance | BEYOND USEFUL LIFE |
| Deficiency Quantity | Electrical Room B22 |
| Quantity Uom | 1 |
| Potential Action | EACH |
| Urgency of Action | REPLACE |
| Purpose of Action | PRIORITY 1 |
| Violations | LEVEL 2 |
| | No violations recorded |
| Instance | Electrical Room B22 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Royal Switchboard Co. |
| EquipmentId | Main Switch MDP#2 Fuse 3500A |
| Capacity/Size Quantity | 3500 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Fuse Size |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room B22 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| SWIMMING POOL | |
| | Does not exist |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|---------------------------------------|
| SWITCHBOARD | Inspected |
| Number of Spares | 0 |
| Air Circuit Breaker Type | Does not exist |
| Fused Disconnect Switch Type | Inspected |
| Instance | Electrical Room B22 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Royal Switchboard Co. |
| EquipmentId | N/A |
| Capacity/Size Quantity | 3500 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 6 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room B22 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Instance | Electrical Room B22 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Royal Switchboard Co. |
| EquipmentId | N/A |
| Capacity/Size Quantity | 3500 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 6 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room B22 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Fused Knife Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Inspected |
| Instance | Basement - Generator Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Royal Switchboard Co. |
| EquipmentId | N/A (Emergency Generator Switchboard) |
| Capacity/Size Quantity | 438 |
| Capacity/Size UOM | Amps Total |

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X450

| Question | Response |
|---|---------------------------|
| SWITCHBOARD | |
| Molded Case Circuit Breaker Type | |
| Capacity/Size 2 Quantity | 1 |
| Capacity/Size 2 UOM | Section(s) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1970 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Basement - Generator Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| TELEPHONE SYSTEM | Inspected |
| PBX/Intercom | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Standard | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| TRANSFORMER | Does not exist |
| TV SYSTEM | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Electrical Inspection

X450

| Question | Response |
|----------------------------|----------------|
| TV SYSTEM | |
| Cable System Exist? | Yes |
| Operational? | Yes |
| Main Equipment Rack | Does not exist |
