

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

School: JANE ADDAMS HS - X, 900 TINTON AVENUE, BRONX, NY, 10456

InspectionId	Inspection Type	Time In	Last Edited
853	MECHANICAL	2018-12-18 07:58AM	2019-06-21 03:54PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: MDF Room - Dedicated A/C Equipment (DX Split System, 1 of 2) Years: 2012 Systems: Boiler Safety Valves; Boiler #1 re-tubed; Water Service: RPZs (in RPZ Closets 120B and 143A, 2 of 3) Years: 2015 Systems: Fixtures - Toilets, Urinals Years: 2016
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	8,050
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	MERs B22D, B32, B40; Fan Room B22
Are there any spaces with Missing or Defective CO Detectors?	Basement - Generator Room B36
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image	
		No condition recorded						

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
Dry Cooler	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Return Fan	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLIMATE CONTROL SYSTEM	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
CLIMATE CONTROL SYSTEM	
BMS	Does not exist
Electric System	Does not exist
Hybrid System	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Throughout
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TERMINAL UNIT CONTROLLER
Deficiency Location/Instance	MERs B22D, B32, B40
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE AIR COMPRESSOR
Deficiency Location/Instance	MER B40 (defective motor)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	Does not exist
CONVEYING	Inspected
Ash Hoist	Does not exist
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	3- Fair
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Inspected
Electric Pressure Booster System	Inspected
Instance	MER B40
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	
Electric Pressure Booster System	
Manufacturer	SyncroFlo
EquipmentId	N/A
Capacity/Size Quantity	2
Capacity/Size UOM	Total # Pumps
Capacity/Size 2 Quantity	15
Capacity/Size 2 UOM	Total Pumps HP
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Hydraulic/Pneumatic Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Room under Stair "D", Storage Room B40A
Instance Condition	2- Between Good and Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Storage Room B40A / Domestic Water Main
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	PVI
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	1,500
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Room 135

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Interior Storm Piping	
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
Enclosed IDF Room	Does not exist
Instance on Rooms B14B, 116A, 216A, 314A	Inspected
Dedicated A/C Equipment	
Instance on Rooms B14B, 116A, 216A, 314A	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Rooms B14B, 116A, 216A, 314A
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
FIXTURES	
Staff And Other	Inspected
Janitor Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	
Condition	1- Good
Deficiency	No deficiencies recorded
Student	
Drinking Fountain	
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Corridors near Rooms 129, 229, 325
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
FIXTURES	
Student	
Lavatory/Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	
Instance on 4th Floor - Boys	Inaccessible
Instance Quantity	1
Instance Quantity Uom	EACH
Instance on 4th Floor - Girls	Inaccessible
Instance Quantity	1
Instance Quantity Uom	EACH
Sink And Fountain Combo Unit	
	Does not exist
Toilet	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	
	Does not exist
GAS SERVICE	
	Inspected
CO/Gas Leak Detection	
	Inspected
Instance	Boiler Room, Gas Meter Room B9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	1997
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Gas Meter Room B9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Distribution Piping	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	
	Inspected
Instance	Gas Meter Room B9
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Eclipse
EquipmentId	N/A
Capacity/Size Quantity	29500
Capacity/Size UOM	SCFH

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
GAS SERVICE	
Gas Pressure Booster	
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
HEATING	
Heating Coil In Ductwork	
Condition	Inspected
Deficiency	2- Between Good and Fair
Hydronic Heating	
Backflow Preventer	
Condition	Inspected
Deficiency	Does not exist
Hot Water Heat Exchanger	
Condition	Inspected
Deficiency	3- Fair
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	
Condition	Inspected
Deficiency	2- Between Good and Fair
Radiator/Convactor/Fin Tube	
Condition	Inspected
Deficiency	3- Fair
Steam Heating	
F&T/Steam Drip Trap	
Condition	Inspected
Deficiency	5- Poor
Deficiency Location/Instance	DEFECTIVE/DETERIORATED
Deficiency Quantity	Basement
Quantity Uom	25
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
MER Steam and Condensate Piping	
Condition	Inspected
Deficiency	3- Fair
Steam Condensate Return Piping	
Condition	Inspected
Deficiency	3- Fair
Steam Condensate Return Pumping System	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	DEFECTIVE CONTROLS
Deficiency Quantity	MER B32
Quantity Uom	1
Potential Action	EACH
Urgency of Action	REPAIR
Purpose of Action	PRIORITY 3
Violations	LEVEL 2
Steam Piping	
Condition	Inspected
Deficiency	3- Fair
Terminal Unit Thermostatic Trap	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	DEFECTIVE/DETERIORATED

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
HEATING	
Steam Heating	
Terminal Unit Thermostatic Trap	
Deficiency Location/Instance	Rooms 107, 117, 118, 201, 217, 301, 307, 315, 318, 332, 436, 442 and other locations (~10%)
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING PLANT	
Replacement Quantity	12,996
Replacement Uom	MBH NET
Instance on Basement	Inspected
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FEEDWATER TANK:DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Flue Exhaust	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH NET
Manufacturer	Burnham
EquipmentId	108249-01
Capacity/Size Quantity	8369
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,498
Instance Quantity Uom	MBH NET
Manufacturer	Burnham
EquipmentId	108249-02
Capacity/Size Quantity	8369
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	1997
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
HEATING PLANT	
Fuel System	
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	FUEL OIL PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room near Fuel Oil Pumps
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
KITCHEN	
Instance on 3rd Floor	Inspected
CO Detector	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas System	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Grease Trap	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
KITCHEN	
Hood Fire Suppression System	
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Kitchen Sink	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
MDF Room	
Instance on Room 320A	Inspected
Dedicated A/C Equipment	
Instance on Room 320A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
Instance on Rooms 135, 136, 137	Inspected
Alternative Use	Yes
Instance on Room 227	Inspected
Alternative Use	No
Instance on Room 225	Inspected
Alternative Use	No
Instance on Room 117	Inaccessible
Acid Waste Neutralizing Tank	
Instance on Rooms 135, 136, 137	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 227	Does not exist
Instance on Room 225	Does not exist
CO Detector	
Instance on Rooms 135, 136, 137	Not required
Instance on Room 227	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shower	
Instance on Rooms 135, 136, 137	Does not exist
Instance on Room 227	Does not exist
Instance on Room 225	Does not exist
Eye Wash	
Instance on Rooms 135, 136, 137	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 227	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
SCIENCE DEMO ROOM	
Eye Wash	
Deficiency Location/Instance	Room 225
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fixed Laboratory Hood	
Instance on Rooms 135, 136, 137	Does not exist
Instance on Room 227	Does not exist
Instance on Room 225	Does not exist
Hood Exhaust Ductwork	
Instance on Rooms 135, 136, 137	Does not exist
Instance on Room 227	Does not exist
Instance on Room 225	Does not exist
Hood Exhaust Fan	
Instance on Rooms 135, 136, 137	Does not exist
Instance on Room 227	Does not exist
Instance on Room 225	Does not exist
Laboratory Sink	
Instance on Rooms 135, 136, 137	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 227	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 225	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Rooms 135, 136, 137	Does not exist
Instance on Room 227	Does not exist
Instance on Room 225	Does not exist
SCIENCE LAB	
Instance on Rooms 118, 120	Inaccessible
SCIENCE PREP ROOM	
Instance on Room 115	Inspected
Alternative Use	Yes
Acid Waste Neutralizing Tank	
Instance on Room 115	Does not exist
CO Detector	
Instance on Room 115	Not required
Emergency Shower	
Instance on Room 115	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Eye Wash	
Instance on Room 115	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fixed Laboratory Hood	

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
SCIENCE PREP ROOM	
Fixed Laboratory Hood	
Instance on Room 115	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room 115	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on Room 115	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Laboratory Sink	
Instance on Room 115	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 115	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
	Inspected
Dry Sprinkler Alarm Valve Assembly	
	Does not exist
Fire Booster Pump Assembly	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Roof Tank	
	Does not exist
Siamese Connection	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Sprinkler Head	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Sprinkler Piping	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Standpipe System	
	Inspected
Hose Valve Assembly	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Piping	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Water Gong	
	Does not exist
Wet Sprinkler Alarm Valve Assembly	
Condition	Inspected
Deficiency	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Storage Room B40A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
SWIMMING POOL	
	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X650

Question	Response
VENTILATION	Inspected
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Main Roof
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded