

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X945

School: **P.S. 87 TRANSPORTABLE - X, 1935 BUSSING AVENUE, BRONX, NY, 10466**

InspectionId	Inspection Type	Time In	Last Edited
1359	MECHANICAL	2019-01-09 01:45PM	2019-01-14 08:43PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Electric Domestic Water Heaters (2 of 4) Years: 2011 Systems: Electric Domestic Water Heaters (1 of 4) Years: 2018
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	N/A
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
Dry Cooler	Does not exist
DX Split System	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Refrigerant Piping	Does not exist
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Mechanical Inspection

X945

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage Ejector Pump	Does not exist
Sewage/Waste/Vent Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
Enclosed IDF Room	Does not exist
FIXTURES	Inspected
Staff And Other	Does not exist
Student	Inspected
Drinking Fountain	Does not exist
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Room T-4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Does not exist
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Does not exist
HEATING	Does not exist
HEATING PLANT	Does not exist
KITCHEN	Does not exist
MDF Room	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Mechanical Inspection

X945

Question	Response
VENTILATION	
Metal Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist