

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X953

School: **AUXILIARY SERVICES HS - BRONX, 3450 EAST TREMONT AVENUE, BRONX, NY, 10465**

InspectionId	Inspection Type	Time In	Last Edited
5097	ELECTRICAL	2019-05-28 11:35AM	2019-05-28 03:38PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Motor Starter Years: 2013 Systems: LAN, Telephone System Years: 2011 Systems: Lighting - Security Years: 2001, 2010 Systems: All Other Electrical Systems and Components Years: 2001
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	condition recorded						

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
CAFETERIA	Does not exist
CITY FIRE ALARM SYSTEM	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X953

Question	Response
COMPUTER LAB	
Instance on Rooms 305, 315, 318	Inspected
Power Panel?	No
Lighting	
Instance on Rooms 305, 315, 318	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 305, 315, 318	Inspected
Pendant Mounted	
Instance on Rooms 305, 315, 318	Does not exist
Recessed Mounted	
Instance on Rooms 305, 315, 318	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Rooms 305, 315, 318	Does not exist
Lighting Fixture - HID	
Instance on Rooms 305, 315, 318	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 305, 315, 318	Does not exist
Lighting Fixture - LED	
Instance on Rooms 305, 315, 318	Does not exist
Raceway With Receptacles	
Instance on Rooms 305, 315, 318	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT LIGHT	Inspected
Battery Pack	
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Area Smoke Detector	
Condition	3- Fair
Deficiency	No deficiencies recorded
Bell/Horn	
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Duct Smoke Detector	
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X953

Question	Response
FIRE ALARM SYSTEM	
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Room 103
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Fire-Lite Alarms Inc
Model	MS-9600
EquipmentId	Fire Alarm Control Panel
Capacity/Size Quantity	12
Capacity/Size UOM	Zones
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Diagram
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sub-Panel	Does not exist
Tamper Flow Switch/Chain	Does not exist
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not exist
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
KITCHEN	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X953

Question	Response
LAN	
Main Equipment Rack (MDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Does not exist
LIGHTNING PROTECTION	Does not exist
LOCKER ROOM	Does not exist
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SECURITY	Inspected
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 104
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Ultrasonic Sensor	Does not exist
IPDVS/CCTV System	Does not exist
Lighting - Security	Inspected
Condition	3- Fair
Replacement Quantity	11
Replacement Uom	EACH
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X953

Question	Response
SERVICE SWITCH	
Instance	Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	S.S.1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	S.S.2
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	S.S.3
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not exist
SWITCHBOARD	Inspected
Number of Spares	0
Air Circuit Breaker Type	Does not exist
Fused Disconnect Switch Type	Inspected
Instance	Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2018-2019**

Electrical Inspection

X953

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance	Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Cutler Hammer
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Recessed Mounted	Inspected

NYC Department of Education
Building Condition Assessment Survey 2018-2019

Electrical Inspection

X953

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TRANSFORMER	Does not exist
TV SYSTEM	Does not exist